

REF: ASB/ 77 000 11 11

ASS. REC. BY:

REF:

GAZ/ 22 002245/KV y3Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s Poon Siang Leon

of _____

Insured: GBH 5578B

Policy No. _____


Claims No. CLMOMVC000004139

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 09 days Res.: Yes or NoLump Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKS 409A Yr Regn: 07.19Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel 1.8V c.c 1496Colour: M. L. Brown A/C: Insured / Std / NI / NASp. Reading: 68912 T/Radio: Insured / Std / NI / NAEng/No: 1810JX20196C/No: THMRU R43Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rlm / STD A/Rlm orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mmR/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mmD.O.A. 8/3/22D.O.I. 10/3/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

cls body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Atty Paid 1.B.1

21/3/22 Kenneth informed final fig \$7926.19 (red 8301.81,51%)

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2) 21/3/22-typist

Days Of Repair: 9Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

) \$ + RS. \$

) Fixers

) Others

Report Format: TP

Lump Sum / I.B.I. (\$ 7926.19

TOTAL



方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

PHANG CHANG HUEI
APT BLK 605 ELIAS ROAD
#11-196
SINGAPORE 510605

Not Asstained
LI Sing @
Money After Pass
9 days

Dear sir
Estimate cost of repair to vehicle no. SKS409A
To supply

1. Front fender	R 421.10 X
2. Front fender arc garish	R 168.80 X
3. Front door	Ry 889.20 —
4. Front door sticker x2	McC 38.40 —
5. Front door hinge x2	R 85.00 X
6. Front door outer moulding	Bu 198.80 —
7. Front door sun vision one set	Mc 160.00 —
8. Front door rubber	Mc/Cut 185.00 50% in
9. Front door lock inner	Ad 309.90 —
10. Front door outer lock	230.00 ?
11. Front door outer handle	CM 198.00 —
12. Front door outer handle inner part	Dr 102.00 —
13. Front channel	95.00 ?
14. Front channel rubber	125.00 ?
15. Front door motor and gear	At/Te 416.90 —
16. Front door mirror	Ad/Dr 606.60 —
17. Front door and rear door protector	Mc 120.00 30% in
18. Rocker panel garish	R 434.50 X ?
19. Centre pillar	R 725.40 ?
20. Rear door	Ry 960.60 —
21. Rear door sticker x2	Mc 48.00 —
22. Rear door outer mounding	Sc 102.00 X
23. Rear door side rubber	85.60 ?
24. Rear door hinge x2	Ry 128.00 —
25. Rear door channel	Sc 85.00 X
26. Rear door channel rubber	Sc 125.00 X
27. Rear door rubber	CM 195.70 50% in
28. Rear door sticker lower	Mc 60.00 —
29. Rear door motor and gear	393.10 ?
30. Rear fender right arc garish	Ad 187.90 —
31. Rear fender	Ry 655.10 —
32. Rear bumper	R 829.60 X
33. Rear bumper Conner right	Bu 173.80 —
34. Rear wheel rim	Ad 850.00 —
Less 20%	15,847.50
	3,169.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



方 商 昭 噴 漆

POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

Pg 2

Labour charges

Rust proofing	100.00	906
To remove cushion and carpet	450.00	1201
Panel beating	1,800.00	1000
Spray painting	1,200.00	1100
Total	16,228.00	

Your faithfully

ALBERT POON

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	09/03/2022 10:26 (SGT)
Date of Accident	08/03/2022 12:45 (SGT)
Exact Location of Accident	Near 143 Tyrwhitt Rd, Singapore 207559
Additional Location Information	T-Junction of Horne Road & Tyrwhitt Road
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS409A
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	PHANG CHANG HUEI
NRIC No	SXXXX121F
Email Address	pchcar409@gmail.com
Mobile Phone No	(Phone) +65-91888007
Alternative Phone No	+65-91888007

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Hr-v
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1500

INSURANCE COMPANY


Name of Insurance Company	Liberty Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	-
Cover Note Number	-

DRIVER

Name of Driver	PHANG CHANG HUEI
NRIC No	SXXXX121F

Vehicle Number: SKS 409A

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 8-mar-22 I was driving straight on Tyrwhitt Road. Suddenly, I saw Vehicle (B) came out from Horne, making a left Turn and hit my vehicle (A) on the right side of my vehicle (A).

The impact caused my vehicle (A) to be pushed all the way to the left lane.

I feel painful on my right arm, and will consult GP Doctor.

Remarks: The vehicle (B) enter to One way street

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature (if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name
NIC / FIN No.