



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22002247/Kvy3e2 Date: 29/05/2023	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLJ 7092T	Veh. Inspected	SMG 6920P	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10014161/JM	Excess (\$)	0.00	
Assign From	SHAFAWATI MD RABU	Assign Date	10/03/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	SKODA SUPERB (A)	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	TMBBD7NP6K7021893	Colour	METALLIC GREY	
Odometer	104349 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	235/40Z R19	WINDFORCE	5 mm	
L/H Front Tyre	235/40Z R19	WINDFORCE	5 mm	
R/H Rear Tyre	235/40Z R19	WINDFORCE	8 mm	
L/H Rear Tyre	235/40Z R19	WINDFORCE	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	04/03/2022	Inspection Date	10/03/2022	
Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	