

Your Ref: 19/19/20/VP02/310912

Date: 31st Mar 2022

Our Ref: CS1/LPM22002257/Kvy3e2

M/s Lonpac Insurance Bhd

21st Flr, Bangunan Public Bank
No. 6 Jalan Sultan Sulaiman
50000 Kuala Lumpur, Malaysia
(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMD 1720Z
INSURED VEHICLE: JKN 1505
ACCIDENT DATE: 04/06/2019

We thank you for your instruction on 07/03/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMD 1720Z from M/s CA Appraiser Pte Ltd.
- b) Polis Diraja Malaysia of Vehicles SMD 1720Z.
- c) Colour damaged vehicle photographs of SMD 1720Z.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMD 1720Z
Make & Model	: KIA Sorento 2.2 (8AT) CRDI 2WD S/R
Year of Registration	: 2018
Chassis Number	: KNAPH81BMJ5465576
Engine Capacity	: 2199 cc

- 2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.