

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX

SINGAPORE 069110

INV No. AC2201999

INV Date 06/04/2022

Reference CS/EQI22002258/Evy3n2

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. EC 91L

Insured Veh. SMZ 3127H

Claim No. DM22HO00361/CH

Policy No.

Accident Date 09/03/2022

Inspection Date 15/03/2022

Description	Total
Survey Inspection	230.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	230.00
GST (7%)	16.10
Grand Total	246.10

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

HYN



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110 Code: EQI 1. Policy Particulars: - THIRD PARTY CLAIM Insured Veh. SMZ 3127H Veh. Inspected EC 91L Policy No. Coverage (\$) 0.00 Claim No. DM22H000361/CH Excess (\$) 0.00 Assign From NG CHEN HOW Assign Date 10/03/2022 Vehicle Particulars & Condition Make & Model VOLKSWAGEN TIGUAN C.C 1395 Engine No. HIDDEN Year of Reg. 2019 Chassis No. WVGZZZ5NZJW973963 Colour BLUE Odometer 32078 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres KIZE Make Balance R/H Front Tyre 235/55 R18 BRIDGESTONE 5 mm L/H Front Tyre 235/55 R18 BRIDGESTONE 5 mm L/H Rear Tyre 235/55 R18 BRIDGESTONE 5 mm THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 09/03/2022 Inspection Date 15/03/2022	Affiliated to Federation Internationale Des Experts En Automobile			
#17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110 Code: EQI 1. Policy Particulars: - THIRD PARTY CLAIM Insured Veh. SMZ 3127H Veh. Inspected EC 91L Policy No. Coverage (\$) 0.00 Claim No. DM22H000361/CH Excess (\$) 0.00 Assign From NG CHEN HOW Assign Date 10/03/2022 2. Vehicle Particulars & Condition Make & Model VOLKSWAGEN TIGUAN c.c 1395 Engine No. HIDDEN Year of Reg. 2019 Chassis No. WVGZZZ5NZJW973963 Colour BLUE Odometer 32078 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres R/H Front Tyre 235/55 R18 BRIDGESTONE 5 mm L/H Front Tyre 235/55 R18 BRIDGESTONE 5 mm R/H Rear Tyre 235/55 R18 BRIDGESTONE 5 mm L/H Rear Tyre 235/55 R18 BRIDGESTONE 5 mm JAMAGES SEE DETAILS. General Information	EQ INSURANCE COMPANY LTD Ref: CS/EQI22002258/Evy3n2			
1. Policy Particulars :- THIRD PARTY CLAIM Insured Veh. SMZ 3127H Veh. Inspected EC 91L Policy No. Coverage (\$) 0.00 Claim No. DM22HO00361/CH Excess (\$) 0.00 Assign From NG CHEN HOW Assign Date 10/03/2022 2. Vehicle Particulars & Condition Make & Model VOLKSWAGEN TIGUAN c. c 1395 Engine No. HIDDEN Year of Reg. 2019 Chassis No. WVGZZZ5NZJW973963 Colour BLUE Odometer 32078 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD GOOD 3. Conditions of Tyres Size Make Balance R/H Front Tyre 235/55 R18 BRIDGESTONE 5 mm L/H Front Tyre 235/55 R18 BRIDGESTONE 5 mm L/H Rear Tyre 235/55 R18 BRIDGESTONE 5 mm L/H Rear Tyre 235/55 R18 BRIDGESTONE	#17-00 TOWER BL	R BLOCK	Date:	06/04/2022
Insured Veh. SMZ 3127H			Code:	EQI
Policy No. Claim No. DM22HO00361/CH Excess (\$) 0.00 Assign From NG CHEN HOW Assign Date 10/03/2022 2. Vehicle Particulars & Condition Make & Model VOLKSWAGEN TIGUAN c.c 1395 Engine No. HIDDEN Year of Reg. 2019 Chassis No. WVGZZZ5NZJW973963 Colour BLUE Odometer 32078 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres Name R/H Front Tyre 235/55 R18 BRIDGESTONE 5 mm		Policy Particular	s :- THIRD PARTY CLAII	M
Claim No. DM22H000361/CH Excess (\$) 0.00 Assign From NG CHEN HOW Assign Date 10/03/2022	Insured Veh.	ı. SMZ 3127H	Veh. Inspected	EC 91L
Assign From NG CHEN HOW Assign Date 10/03/2022 2. Vehicle Particulars & Condition Make & Model VOLKSWAGEN TIGUAN c.c 1395 Engine No. HIDDEN Year of Reg. 2019 Chassis No. WVGZZZ5NZJW973963 Colour BLUE Odometer 32078 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres Size Make Balance	Policy No.		Coverage (\$)	0.00
2. Vehicle Particulars & Condition Make & Model VOLKSWAGEN TIGUAN c.c 1395 Engine No. HIDDEN Year of Reg. 2019 Chassis No. WVGZZZ5NZJW973963 Colour BLUE Odometer 32078 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres Size Make Balance R/H Front Tyre 235/55 R18 BRIDGESTONE 5 mm L/H Front Tyre 235/55 R18 BRIDGESTONE 5 mm R/H Rear Tyre 235/55 R18 BRIDGESTONE 5 mm L/H Rear Tyre 235/55 R18 BRIDGESTONE 5 mm L/H Rear Tyre 235/55 R18 BRIDGESTONE 5 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. General Information	Claim No.	DM22HO00361/CH	Excess (\$)	0.00
Make & Model	Assign From	n NG CHEN HOW	Assign Date	10/03/2022
Engine No. HIDDEN Year of Reg. 2019 Chassis No. WVGZZZ5NZJW973963 Colour BLUE Odometer 32078 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres Size Make Balance R/H Front Tyre 235/55 R18 BRIDGESTONE 5 mm L/H Front Tyre 235/55 R18 BRIDGESTONE 5 mm R/H Rear Tyre 235/55 R18 BRIDGESTONE 5 mm L/H Rear Tyre 235/55 R18 BRIDGESTONE 5 mm L/H Rear Tyre 235/55 R18 BRIDGESTONE 5 mm L/H Rear Tyre 235/55 R18 BRIDGESTONE 5 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. General Information		Vehicle Par	ticulars & Condition	
Chassis No. WVGZZZ5NZJW973963 Colour BLUE Odometer 32078 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD Conditions of Tyres Size Make Balance	Make & Model	del VOLKSWAGEN TIGUAN	c.c	1395
Odometer 32078 KM Steering IN ORDER Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres Size Make Balance	Engine No.	HIDDEN	Year of Reg.	2019
Brakes IN ORDER Modification SPORTS RIM General GOOD 3. Conditions of Tyres Size Make Balance R/H Front Tyre 235/55 R18 BRIDGESTONE 5 mm L/H Front Tyre 235/55 R18 BRIDGESTONE 5 mm R/H Rear Tyre 235/55 R18 BRIDGESTONE 5 mm L/H Rear Tyre 235/55 R18 BRIDGESTONE 5 mm L/H Rear Tyre 235/55 R18 BRIDGESTONE 5 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. 5. General Information	Chassis No.	. WVGZZZ5NZJW973963	Colour	BLUE
General GOOD 3. Conditions of Tyres Size Make Balance	Odometer	32078 KM	Steering	IN ORDER
3. Conditions of Tyres Size Make Balance	Brakes	IN ORDER	Modification	SPORTS RIM
Size Make Balance	Collection and the collection an			
R/H Front Tyre 235/55 R18 BRIDGESTONE 5 mm L/H Front Tyre 235/55 R18 BRIDGESTONE 5 mm R/H Rear Tyre 235/55 R18 BRIDGESTONE 5 mm L/H Rear Tyre 235/55 R18 BRIDGESTONE 5 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. General Information				
L/H Front Tyre 235/55 R18 BRIDGESTONE 5 mm R/H Rear Tyre 235/55 R18 BRIDGESTONE 5 mm L/H Rear Tyre 235/55 R18 BRIDGESTONE 5 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. General Information	Size Make Balance			
R/H Rear Tyre 235/55 R18 BRIDGESTONE 5 mm L/H Rear Tyre 235/55 R18 BRIDGESTONE 5 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. 5. General Information	R/H Front Tyre	yre 235/55 R18	BRIDGESTONE	5 mm
L/H Rear Tyre 235/55 R18 BRIDGESTONE 5 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. 5. General Information	L/H Front Tyre	yre 235/55 R18	BRIDGESTONE	5 mm
Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. General Information	R/H Rear Tyre	re 235/55 R18	BRIDGESTONE	5 mm
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. General Information	L/H Rear Tyre	re 235/55 R18	BRIDGESTONE	5 mm
DAMAGES SEE DETAILS. 5. General Information	. Description of Damages			
5. General Information	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
	DAMAGES SEE DETAILS.			
Accident Date 09/03/2022 Inspection Date 15/03/2022	General Information			
	Accident Date	ate 09/03/2022	Inspection Date	15/03/2022
Survey held at VOLKSWAGEN CENTRE SINGAPORE	Survey held at	lat VOLKSWAGEN CENTRE SIN	GAPORE	
247 ALEXANDRA ROAD SINGAPORE 159934				
5a. Remarks			Remarks	
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair		Estimat	e Days of Repair	
ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days	ESTIMATED NOR	NORMAL PERIOD FOR REPAIR:	6 Work	king Days



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EC 91L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER FOR BUMPER PRIMED REAR BUMPER (SN)	DENTED	1,492.76	1,492.76
1	SPOILER SATIN BLACK (SN)	CUT	304.02	304.02
4	RIVET (SN)	NECESSARY	5.28	5.28
1	SENSOR BRACKET (SN)	NECESSARY	14.17	14.17
1	SENSOR BRACKET (SN)	NECESSARY	14.17	14.17
1	SENSOR BRACKET (SN)	NECESSARY	14.17	14.17
1	SENSOR BRACKET (SN)	NECESSARY	14.17	14.17
1	2K-PLASTIC ADHESIVE (SN)	NECESSARY	85.80	85.80
1	BONDING AGENT FOR PLASTIC (SN)	NECESSARY	68.71	68.71
1	BUMPER REINFORCEMENT (SN)	NOT NECESSARY	678.70	-
1	ATTACHMENT STRIP BUMPER CENTRE BRACKET (SN)	NOT NECESSARY	69.19	-
1	GUIDE PIECE LHR BUMPER SIDE BRACKET (SN)	NOT NECESSARY	43.76	-
1	GUIDE PIECE RHR BUMPER SIDE BRACKET (SN)	NOT NECESSARY	43.76	-
1	GUIDE PIECE LHR BUMPER INNER BRACKET (SN)	NOT NECESSARY	43.76	-
1	GUIDE PIECE RHR BUMPER INNER BRACKET (SN)	NOT NECESSARY	43.76	-
1	REAR TRUNK LID (SN)	DENTED	2,804.91	2,804.91
1	INSCRIPTION BRIGHT CHROME TIGUAN EMBLEM (SN)	NECESSARY	104.22	104.22
1	VW SIGN BLACK HIGH GLOSS (SN)	NECESSARY	110.46	110.46
2	1K WINDOW ADHESIVE (SN)	NECESSARY	102.70	102.70
1	ALL PURPOSE CLEANER (SN)	NECESSARY	102.65	102.65
1	PRIMER (SN)	NECESSARY	30.22	30.22
2	APPLICATOR (SN)	NECESSARY	22.32	22.32
1	ACTIVATOR (SN)	NECESSARY	26.23	26.23
1	ADDITIONAL BRAKE LIGHT WI 3RD BRAKE LIGHT (SN)	NECESSARY	182.75	182.75
1	LED TAIL LIGHT LHF INNER TAILIGHT (SN)	NOT NECESSARY	601.00	-
			7,023.64	5,499.71
	LABOUR			
	LABOUR.		3,360.00	1,680.00
	WATER LEAK TEST.		150.00	150.00
	TFR BOOT LID MECH.		840.00	420.00

Report Ref No. CS/EQI22002258/Evy3n2



RECOMMENDED COST OF REPAIRS

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

10,949.71

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	R&R REAR W/SCREEN.		840.00	840.00
	SPRAY PAINTING.		3,200.00	1,600.00
	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR.		280.00	280.00
	B&P DIAGNOSIS AND PROGRAMMING.		480.00	480.00
			9,150.00	5,450.00
	GRAND TOTAL		16,173.64	10,949.71

Report Ref No. CS/EQI22002258/Evy3n2



Automotive Assessor

X:2.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate 5. Intribution provided must be as truthful and accurate as possible. Any white misteries entailed of withouting of material facts may allow insurance companies to reputing policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving

- and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 09/03/2022 16:31 (SGT) Date of Accident 09/03/2022 11:18 (SGT) Exact Location of Accident Singapore Additional Location Information ALONG CTE SLIP RD TO JION BOUDARY RD TWDS UPPER SERANGOON RD Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Volkswagen

Vehicle Registration Number EC91L

INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner **NEO JEN NEE** NRIC No S7525941G Email Address richardneo91@gmail.com Mobile Phone No (Phone) +65-96214485 Alternative Phone No (Home) +65-96214485

VEHICLE PARTICULARS

Manufacturer

Model Tiguan Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Private car Transmission Auto CC 1395

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd. Type of Coverage Comprehensive Fleet Policy Policy Number 2070059487-01 Cover Note Number

DRIVER

Name of Driver NEO KOON YONG

NRIC No S0457162B Date Of Birth 11/05/1946 Occupation Indoor Date Of Driving Pass 19/01/1967 Driving experience 55 YEARS AND 2 MONTHS Gender Mobile Number (Phone) +65-96214485 Alt, Phone Number Email Address richardneo91@gmail.com Address APT BLK 130 ANG MO KIO AVE 3 Address complement #02-1585 Postcode 560130 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Parent Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No DETAILS OF POLICE ACTION Was the accident reported to the police? Nο Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO SEKTCH PLAN & VIDEO ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number SMZ3127H Vehicle Manufacturer Vehicle Model

 Vehicle Manufacturer

 Vehicle Model

 Vehicle Variant

 Vehicle Colour

 Vehicle Category
 Private car

 Name of Driver
 TAN YORK WEE

 Contact Number
 (Phone) +65-96331138

 Address

ddress complement	_
ostcode	_
surance Company Name	_
ature Of Damage	_
etails of property damaged in accident	_
o. Of Passenger (Including Driver)	_

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my w orkshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes,

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre

Sketch Plan

Bandan M

Describe Circumstances of the Accident
GTE.
an of mad 2022 at about. 11.18 Am. drive alog 500 pd to jon Boundary ad to ward to plan soragion pol am 6tos at punction and check on coming can on my right, and 5 u z 31274. Evash infant on my Rail and demage. See photo.
od to jum Brundary and to ward to have covarion and
am stor at newstron and week on coming and to me
1013/1 and 6 413 3127 W 642/h is bout of the
and die total a clients
- 411. Nomarc. 336 14010.
2 ml Darda Delesto
3rd parry alasto
at the state of th
963311280 Tan forc wee

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. EC 91L

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. EC 91L

RE-INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315









