



凱摩哆服務 KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 10/03/2022

Attn: The Motor Claims Department

Your Insured veh no : PC1903H

TP China.
Xiao Chan.

WITHOUT PREJUDICE

(By Email Only)

China Taiping Insurance (S) Pte Ltd

3 Anson Road
#16-00 AXA Tower
Spring Leaf Tower
Singapore 079909
Tel : 6389 6111

JTEGH23B20004638

Dear Sir / Madam

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimated Cost of repair bill for Toyota Picnic SFP 5906 Z And PC 1903 H on 04/03/2022 @ 17:15PM.

Acknowledged by Repairer
Signature:

Date:

1pc	Front Door LH	Painted		\$	1,067.40	✓
1pc	Front Door Side Mirror	ut.		\$	1,102.35	935
1pc	Front Door Inner Rubber	new		\$	110.40	t.
1pc	Front Door Protector	del		\$	201.45	✓
1pc	Front Door Outer Moulding	new		\$	210.11	t.
1pc	Front Door Handle	ut		\$	110.45	✓
1pc	Front Door Hinge Top and Lower	new	\$74.30 2pcs	\$	74.30	t.
1pc	Rear Door LH	Dist		\$	1,004.95	✓
1pc	Rear Door Rubber	new		\$	110.40	t.
1pc	Rear Door Protector	del		\$	201.45	✓
1pc	Rear Door Outer Moulding	new		\$	210.11	t.
1pc	Rear Door handle	new		\$	110.40	t.
1pc	Rear Door Hinge Top and Lower	new	\$74.30 2pcs	\$	74.30	t.
				\$	4,588.07	
			Less 25%	\$	1,147.02	
				\$	3,441.05	

To dismantl & replace damage parts, panel beat where necessary

To putty, apply primer & spray paint on the affected portion.

To check wiring functions.

1230
\$ 680.00 500
\$ 850.00 700
\$ 120.00 30
\$ 5,091.05

Admin
1/5 11/03/22

04 Days

After Repairs Photos Required.

total: 391552
1/5: 3.1K