

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Ref:	CS/ASM22002295/Uvy3e2	
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		Date	: 31/03/2022	
	ATTN: ANG YVON	NE	Code	e: ASM	
1.	. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKK 3820S	Veh. Inspected	SJK 6740G	
	Policy No.	P1944330	Coverage (\$)	0.00	
	Claim No.	S2M03VGA	Excess (\$)	0.00	
	Assign From	ANG YVONNE	Assign Date	11/03/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VIOS E (A)	c.c	1497	
	Engine No.	HIDDEN	Year of Reg.	2008	
	Chassis No.	MR053HY9305083623	Colour	BLUE	
	Odometer	497601 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/55 R15	TRIANGLE	5 mm	
	L/H Front Tyre	195/55 R15	TRIANGLE	5 mm	
	R/H Rear Tyre	195/55 R15	TRIANGLE	5 mm	
	L/H Rear Tyre	195/55 R15	TRIANGLE	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	10/03/2022	Inspection Date	11/03/2022	
	Survey held at	AUTOBAY PTE LTD			
		NO. 1 KAKI BUKIT AVE 6 #02-11 SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:	5 Wo	rking Days	
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:	5 Wo	rking Days	