

(09/11/13) waf

ASS. REC. BY: Ben

REF:

CS/CT122002296/R1y3

936H

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMH 5224

at Workshop m/s

CYCLE &amp; CARRIAGE

of

188, PANDAN LOP

CTI

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

179k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMH 5224

Yr Regn: 2018 DEC

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MERCEDES BENZ E200 EKE

c.c. 1991

Colour

GREY

A/C: Insured / Std / NI / NA

Sp. Reading

51857

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD2130422A575821

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

275/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

04/03/22

D.O.I.

02/12/22

Survey held at

CYCLE &amp; CARRIAGE (P)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 103K

We will be advising our principal a cost of repair P/P \$5,667.70/-  
with 04 days of repair, subject to their approval.

(red, \$1005.68, 15%)

Date/Time, File Pass to?



: Prel. Report

1) 20/01/23



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

Add Fee:



: Site Insp

(\$

)

S + RS, SI



: Interview

(\$

)

Photos



: Tech. Invs

(\$

)

Others



: Weekend

(\$

)

Report Format :

tp

Lump Sum / I.B.I. (\$

5667.70

)



# ESTIMATE FOR SMG522U

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

CHINA TAIPING INSURANCE (S) PTE  
LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

Vehicle & Document Information  
WIP No 55390  
Reg No/Reg Date SMG522U / 20/12/2018  
Date In/Mileage / 39509  
Chassis No WDD2130422A5758219  
Engine No 27492031693079  
Make/Model MB/MB E 200 SEDAN EXCLUSIVE/EXCLUSIVE  
Colour/Trim 029 992 Selenite Gr/ 048 814 Nappa Nut B

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	01/12/2022/ 18:16	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

## Z REQUEST

Customer Request

M BPN SUN

POLICY NO/ACC DATE : 5120085604-01 // 4-3-2022  
DRIVE IN/TP VEH NUMBER : 4-3-2022 // GBJ7376T - CHINA TAIPING  
DATE IN/DATE SURVEY:  
DIRECT SETTLEMENT BY:

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESpray REAR BUMPER & RH/REAR FENDER

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO  
IDENTIFICATION STANDARD. NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT

M LH/REAR BUMPER CHROME MOULDING

M RH/REAR BUMPER CHROME MOULDING

M REAR LOWER BLACK TRIM BUMPER

M REAR BUMPER LOWER CHROME MOULDING

M LH/TAIL PIPE BRACKET

M RIVET

M DISTANCE SENSOR

R REAR BUMPER

1.00	152.14	00.00	152.14
1.00	152.14	00.00	152.14
1.00	336.57	00.00	336.57
1.00	362.74	00.00	362.74
1.00	71.09	00.00	71.09
12.00	4.93	00.00	59.16
1.00	195.43	00.00	195.43
1.00	1565.55	00.00	1565.55

960 1440.00  
1600 1800.00

0.10 380.00  
120.00

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirmed & accepted by

Authorized signatory and company stamp

Nett	6,634.82
7% GST on	464.44
Total Payable	7,099.26

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	05/03/2022 15:38 (SGT)
Date of Accident	04/03/2022 09:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ALONG WOODLANDS AVE 3
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMG522U
-----------------------------	---------

### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CHIN MOY YONG
NRIC No	S1826936H
Email Address	Carenechin@gmail.com
Mobile Phone No	(Phone) +65-98322463
Alternative Phone No	+65-98322463

### VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	200e
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1900

### INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5120085604-01
Cover Note Number	-

### DRIVER

Name of Driver	YONG CHEE HIONG
NRIC No	S2189623C

Date Of Birth	24/11/1965
Occupation	Indoor
Date Of Driving Pass	18/08/1987
Driving experience	34 YEARS AND 7 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98322463
Alt. Phone Number	-
Email Address	Carenechin@gmail.com
Address	48 TOH YI ROAD
Address complement	-
Postcode	596517
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	VIDEO SIZE IS BIG. WILL PROVIDE TO INSURANCE WHEN REQUIRED.
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ7376T
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	MUHAMMAD SYAHRIL
NRIC No	T0045996D



Contact Number .....	(Phone) +65-92709190
Address .....	-
Address complement .....	-
Postcode .....	-
Insurance Company Name .....	-
Nature Of Damage .....	-
Details of property damaged in accident .....	-
No. Of Passenger (Including Driver) .....	-



# SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: N. B. M.  
NRIC/FIN No.: 993875



SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 4/3/2022 at about 9:30am, I was driving my car SM6522U along Woodlands Ave 3. I then came to a stop as traffic light was red and I was stationary behind several vehicles. While queuing behind those vehicles, suddenly my rear side of car SM6522U was hit by a van GB57376T.

The front of van GB57376T hit the rear of my car SM6522U. I wish to state that traffic was heavy.

There were no injuries. That is all.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 5/1/2022 21:00hrs.

Reporting Centre Personnel's Signature  
Name: N/A  
NRIC/FIN No.: 992525



**Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	936H

**Vehicle Details**

Vehicle No.:	SMG522U
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Dec 2022
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E200 EXCLUSIVE (R18 LED)
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	27492031693079
Chassis No.:	WDD2130422A575821
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$57,519.00
Original Registration Date:	20 Dec 2018
First Registration Date:	20 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$75,535.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Dec 2028
PARF Rebate Amount:	\$56,651.00

**Intended COE Rebate Details**

COE Expiry Date:	19 Dec 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,101.00
COE Rebate Amount:	\$18,786.00
<b>Total Rebate Amount:</b>	<b>\$75,437.00</b>



# Mercedes-Benz E-Class E200 Exclusive

## Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

<b>Price</b>	<b>\$172,000</b>		
<b>Depreciation</b> ?	\$23,660 /yr <a href="#">View models with similar depre</a>	<b>Reg Date</b>	06-Aug-2018 (5yrs 8mths 1day COE left)
<b>Mileage</b>	65,000 km (15k /yr)	<b>Manufactured</b> ?	2018
<b>Road Tax</b> ?	\$1,202 /yr	<b>Transmission</b>	Auto
<b>Dereg Value</b> ?	\$75,886 as of today (change)	<b>OMV</b> ?	\$57,519
<b>COE</b> ?	\$33,900	<b>ARF</b> ?	\$75,535
<b>Engine Cap</b>	1,991 cc	<b>Power</b>	135.0 kW (181 bhp)
<b>Curb Weight</b> ?	1,605 kg	<b>No. of Owners</b> ?	2
<b>Type of Vehicle</b>	Luxury Sedan		