

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI22002300/Uvy3n2	
		TINSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	22/03/2022	
			Code	AGI	
1.	. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLR 3120E	Veh. Inspected	SKS 1919M	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10014223/EE	Excess (\$)	0.00	
	Assign From	SHAFAWATI	Assign Date	11/03/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	PORSCHE MACAN (A)	c.c	2997	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	WP1ZZZ95ZFLB62098	Colour	BLUE	
	Odometer	130163 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	235/55 R19	DUNLOP	7 mm	
	L/H Front Tyre	235/55 R19	DUNLOP	7 mm	
	R/H Rear Tyre	255/50 R19	DUNLOP	7 mm	
	L/H Rear Tyre	255/50 R19	DUNLOP	7 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	5. General Information				
	Accident Date	10/03/2022	Inspection Date	11/03/2022	
	Survey held at	39 WOODLANDS CLOSE, MEGA @ WOOLANDS #01-24			
	Repairer	NINETEEN AUTOWERKS PTE. LTD.			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: