



Next Step

Agree to perform service

# Service Request Details

Claim S2M03V5M Reference CS3/ASM22002302/y3 🧳 Loss Date 5 March 2022 Vendor Name LKK AUTO CONSULTANTS PTE LTD (TP) Type of Loss Third Party Vehicle Damage **Report Date** 8 Mar 2022 6:28:24 PM **Request Date** 11 March 2022 Due Date 18 March 2022 Services Pre-Repair Survey **Actions** 



Accept Work

### **Vehicle Information**

Incident Vehicle Registration # SNB3649H

Make

tpvd Jeep

Model

Wrangler

#### Service Address

, , ,

## Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD 383 SIN MING DRIVE, 575717, Singapore 65551188

#### Claim Handler

LOH Cynthia

cynthia.loh@axa.com.sg

Additional Instructions

Messages1

Invoices

History

Documents

Assessment

Metrics

Notes



0

TYPE

SENT 11/3/22 4:43 PM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT S2M03V5M

BODY Dear Cynthia, Thank you for the assignment. Repair...

