

635607

**A P LAW PRACTICE LLC**

(UEN No. 201939937D)

(GST Registration No. 201939937D)

151 Chin Swee Road

#10-03/05 Manhattan House

Singapore 169876

Tel: +65 6955 8899

Fax: +65 6900 9899

WhatsApp: +65-9171-4767

Email: caroline@aplp.com.sg

**We do not accept service of Court documents by fax.**

Our ref: AP/2021/004240

Your ref: SJG6036C

Date: 2 December 2021

Secretary in charge: Caroline

Secretary's email: caroline@aplp.com.sg

**CHUA CHIN HIANG (CAI ZHEN XIAN)**  
 BLK 522B TAMPINES CENTRAL 7  
 #08-19  
 SINGAPORE 522522

**By POST**  
 (Without attachments)

**AIG Asia Pacific Insurance Pte Ltd**  
 Insurer of **SJG6036C**  
 78 Shenton Way  
 #07-16 AIG Building  
 Singapore 079120

**By HAND**  
 (With attachments)

RECEIVED BY AIG Claims Dept	
07 DEC 2021	
CL No.	6838593563SG003

Dear Sirs,

**WITHOUT PREJUDICE**

**CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 17 OCTOBER 2021 AT ABOUT 1435 HRS INVOLVING MOTOR VEHICLES NO(S). SMA5189Y AND SJG6036C ALONG TAMPINES AVE 5**

We act for **LI YANG**, owner of **SMA5189Y**.

We are instructed by our client to claim damages against you/your insured in connection to the above-mentioned road traffic accident between our client and your/your insured's vehicle **SJG6036C**.


We are instructed that the above-mentioned road traffic accident was caused by your/your insured's negligence / the negligence of your authorised driver in the driving, management and/or control of your/your insured's vehicle.

As a result of the abovementioned road traffic accident, our clients' vehicle was damaged and our clients has been put to loss and expense, particular of which are as follows:

**COSTS OF REPAIR (WITH GST) \$ 3,424.00**

**LOSS OF RENTAL (WITH GST) \$ 1,926.00**

- Pre-repair \$ 642.00  
(03 days including intervening weekend @ \$214.00 per day)
- Loss of rental during repair works \$1,284.00  
(06 days including intervening weekend @ \$214.00 per day)

**Our Legal Costs with GST (At this stage)****\$ 1,605.00**

**Disbursements (To-date)****\$ 689.48**

1.	Survey Report Fees	\$ 485.00
2.	GIA / LTA searches fee	\$ 43.98
3.	Other Incidentals with GST	\$ 160.50

**Total \$ 7,644.48**

We enclose herewith the following supporting documents for your attention:

- a. Our client's Singapore Accident Statement;
- b. Copy of repair bill from our client's workshop;
- c. Copy of our client's surveyor report;
- d. Copy of the survey report tax invoice;
- e. Client's rental invoice;
- f. Copies of receipts for GIA / LTA searches;

In compliance with the pre-action protocol under the State Courts' Practice Direction 37, we had notified your insurer of the above-mentioned road traffic accident and to the best of our knowledge, your insurer had arranged for the pre-repair inspection of our client's vehicle.


*Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer*

*Please note that you or your insurer should send to us an acknowledgement of receipt to us within fourteen (14) days of your receipt of this letter, failing which, our client will have no alternative but to commence proceedings against you without further notice to you or your insurer*

*Please also note that if you a counterclaim against our client arising out of the above-mentioned accident, you are required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter*

*Should you fail to acknowledge receipt of this letter within fourteen (14) days, our client may commence Court proceedings against you without further notice to you or your insurer. For the avoidance of any doubt, **this letter serves as notice under Section 9(3) of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189)** of our client's intention to commence proceedings against you and/or your authorised driver.*

Yours faithfully,

**A P LAW PRACTICE LLC**

enc

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	18/10/2021 19:50 (SGT)
Date of Accident	17/10/2021 14:35 (SGT)
Exact Location of Accident	Tampines Ave 5, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA5189Y
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LI YANG
NRIC No	S8157268B
Email Address	ly.20080808@hotmail.com
Mobile Phone No	(Phone) +65-93207181
Alternative Phone No	+65-93207181

#### VEHICLE PARTICULARS

Manufacturer	Nissan
Model	Qashqai
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1200

#### INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMPCSNW00033702100
Cover Note Number	-

#### DRIVER

Name of Driver	LI YANG
NRIC No	S8157268B



Date Of Birth	25/05/1981
Occupation	Indoor
Date Of Driving Pass	19/03/2008
Driving experience	13 YEARS AND 7 MONTHS
Gender	Female
Mobile Number	(Phone) +65-93207181
Alt. Phone Number	+65-93207181
Email Address	ly.20080808@hotmail.com
Address	BLK 515B TAMPINES CENTRAL 7
Address complement	#15-14
Postcode	522515
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	4
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### PASSENGER 1

Name	SHI LUOJIA
Gender	Female

#### PASSENGER 2

Name	SHI XIAO BAO
Gender	Male

#### PASSENGER 3

Name	MARIA CLAIRE ANTONIO MAMARIL
Gender	Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Tampines Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18005871999
Alt. Police Station Phone No	(Fax) +65-65871699
Police Station Address	6 Tampines Ave 4 Singapore 529682
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

PLS REFER TO THE POLICE REPORT:T/20211017/2057

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	WITH DRIVER
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJG6036C
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### INJURED PERSONS DETAILS

##### INJURED 1

Name of injured person	LI YANG
Gender	Female
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	SLIGHT
Injured person in which vehicle?	SMA5189Y
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	-

##### INJURED 2

Name of injured person	SHI XIAO BAO
Gender	Male
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	SLIGHT
Injured person in which vehicle?	SMA5189Y
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	No

##### INJURED 3

Name of injured person	MARIA CLAIRE ANTONIO MAMARIL
Gender	Female
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	SLIGHT
Injured person in which vehicle?	SMA5189Y
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	No



# SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

## Sketch Plan

Attach as police report

Tampines Ave 6



Tampines Ave 5

A. SHAS188X

B. SJG 6086C

**Describe Circumstances of the Accident**

*W/S refer to the police report 57/2-03/10/17/2017*

**Declaration**

We declare the foregoing particulars are true in every respect.

*[Signature]*  
 Policyholder's Signature / Date & Time

*[Signature]*  
 Driver's Signature (If driver is not the policyholder) / Date & Time

*[Signature]* 18/10/17  
 Witnessed by Reporting Centre Personnel





**SINGAPORE  
POLICE FORCE**



T/20211017/2057

3 of 4

Police Station Of Origin:  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999

Report No. T/20211017/2057

## CONTINUATION OF REPORT

<b>Passenger</b>			
Name	MARIA CLAIRE ANTONIO MAMARIL	ID No	G8569225P
Related Vehicle	SMA5189Y (Car)	Contact No	83487713
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL


**Brief Details:**

On 17/10/21 at about 1435hrs, I was driving along Tampines Ave 5 towards Tampines Ave 6. I was driving on lane 2 of a 2 lane road. I made a left turn to Tampines Ave 6 however there was a bicycle crossing thus I had to stop. V2 was driving behind me, collided into the rear right side of my rear bumper.

Police and Ambulance were not at scene. I have in-car camera pointed to the rear of my vehicle which captured the incident. The car subsequently drove off straight before I could exit my vehicle. As I was holding up traffic and V2 did not make a stop, I moved off so as to not choke the turning point.

I am not sure of the estimated cost of repairs.



































**SINGAPORE  
POLICE FORCE**



T/20211017/2057

1 of 4

Police Station Of Origin:  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999

Report No: T/20211017/2057

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 17/10/2021 17:14		Vide Report No.:		Station/Diary No: 65	
<b>Informant's Particulars</b>					
Name of Informant: LI YANG			Address: APT. BLK 515B TAMPINES CENTRAL 7 #15-14 SINGAPORE 522515		
ID Type / ID No.: NRIC NO / S8157268B			Contact No: Home/Office:		Mobile: 93207181
Nationality: CHINESE			Email:		
Sex: Female	Age: 40	Date of Birth: 25/05/1981	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Telephone Marketer			Driving Licence Information: Class: 3		Date of Expiry:

**General Information of the Accident**

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 17/10/2021 14:35	Type of Location: T-Junction
Location: TAMPINES AVENUE 5				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJG6036C	Car	MERCEDES BENZ				0
SMA5189Y	Car	NISSAN	QASHQAI 1.2 DIG-T CVT	White	Slightly Damaged	3

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------





**SINGAPORE  
POLICE FORCE**



T/20211017/2057

Police Station Of Origin:  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999

2 of 4

Report No. T/20211017/2057

## CONTINUATION OF REPORT

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMA5189Y	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	DMPCSNW000337 02100	09/02/2021	08/02/2022

**Details of Person Involved**

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA

**Passenger**

Name	SHI LUOJIA	ID No.	T1839068F
Related Vehicle	SMA5189Y (Car)	Contact No.	NIL f
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Driver**

Name	LI YANG	ID No.	S8157268B
Related Vehicle	SMA5189Y (Car)	Contact No.	93207181
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Passenger**

Name	SHI XIAO BAO	ID No.	S8169271D
Related Vehicle	SMA5189Y (Car)	Contact No.	93266319 m
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL



**SINGAPORE  
POLICE FORCE**



T/20211017/2057

3 of 4

Police Station Of Origin:

Tampines N.P.C

6 Tampines Avenue 4 SINGAPORE 529682

Tel No: 1800-5871999

Report No. T/20211017/2057

**CONTINUATION OF REPORT**

<b>Passenger</b>			
Name	MARIA CLAIRE ANTONIO MAMARIL	ID No.	G8569225P
Related Vehicle	SMA5189Y (Car)	Contact No.	83487713
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 17/10/21 at about 1435hrs, I was driving along Tampines Ave 5 towards Tampines Ave 6. I was driving on lane 2 of a 2 lane road. I made a left turn to Tampines Ave 6 however there was a bicycle crossing thus I had to stop. V2 was driving behind me, collided into the rear right side of my rear bumper.

Police and Ambulance were not at scene. I have in-car-camera pointed to the rear of my vehicle which captured the incident. The car subsequently drove off straight before I could exit my vehicle. As I was holding up traffic and V2 did not make a stop, I moved off so as to not choke the turning point.

I am not sure of the estimated cost of repairs.



**SINGAPORE  
POLICE FORCE**



T/20211017/2057

Police Station Of Origin:

Tampines N.P.C

6 Tampines Avenue 4 SINGAPORE 529682

Tel No: 1800-5871999

4 of 4

Report No. T/20211017/2057

**CONTINUATION OF REPORT****Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature of Officer Recording The Report: G/ Sgt 3 NURFAIZ BIN NOORDIN	Signature Of Informant:  
Signature Of Interpreter: Not applicable	Date/Time: 17/10/2021 17:14
Officer In Charge Of Case: TP / HRT / SI KALESWARI PALANI Contact No: 65476902	Classification Of Case:
Authentication Stamp NP168	





## TAX INVOICE

SKG726Y  
BMW X3  
CHASSIS NO.: WBAWX320100B25674

Invoice Date  
27 Oct 2021  
Invoice Number  
2020-8237  
UEN/GST Reg. No.  
201539883N

STK AUTO (S) PTE. LTD.  
8 Kaki Bukit Ave 4  
#03-21 S 415875  
HP:91237949  
Tel:63860669

Description	Quantity	Unit Price	Amount SGD
MRS LI YANG			
CAR RENTAL 19/10/2021 TILL 25/10/2021	6.00	200.00	1,200.00
		Subtotal	1,200.00
		INCLUDES SALES GST 7%	84.00
		<b>TOTAL SGD</b>	<b>1,284.00</b>

**Due Date: 27 Oct 2021**

- \*\* Received In Good Order & Condition. Goods Sold Are Not Refundable/Return.
- \*\* Interest rate of 5% per month, calculated on a daily basis, is levied on payment for overdue amount/account owing to STK AUTO (S) PTE LTD after seven (7) days from date of invoice.
- \*\* Cheque should be crossed and make payable to "STK AUTO (S) PTE LTD".
- \*\* Transfer to OCBC current account: 6951-58626-001
- \*\* Paynow UEN NO. 201539883N

\_\_\_\_\_  
Customer's Signature

# STK Auto (S) Pte Ltd

PHOTOCOPY

8 Kaki Bukit Avenue 4

#03-21 Premier @ Kaki Bukit, Singapore 415875

**Owner :** Li Yang

**Date :** 26-Oct-21

**Address :** C/o : STK Auto (S) Pte Ltd

8 Kaki Bukit Avenue 4

#03-21 Premier @ Kaki Bukit, Singapore 415875

**Model :** Nissan Qashqai

**D.O.A :** 17-Oct-21

**Reg No. :** SMA 5189 Y

ITEM NO	DESCRIPTION		U.PRICE SGD	AMOUNT SGD
1	LUMP SUM REPAIR COST AS PER SURVEYOR REPORT RECOMMENDATION		SGD 3,200.00	SGD 3,200.00
Grand Total Amount:				SGD 3,200.00



# CL APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440

Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783

Reg No: 201000228E

## INVOICE

Li Yang

C/o: STK Auto (S) Pte Ltd

8 Kaki Bukit Avenue 4

#03-21 Premier @ Kaki Bukit, Singapore 415875

Invoice No. : CL/210502

Ref No. : STK/10/2103/TP

Date : 26 October 2021

DESCRIPTION	AMOUNT
<b>OUR SERVICE FEE CHARGES:</b>	
• SURVEY INSPECTION FOR VEHICLE NO. <u>SMA 5189 Y</u>	
• RESURVEY INSPECTION	
• DIGITAL PHOTOGRAPHS SERVICES (INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)	
• TRANSPORTATION	
<b>GRAND TOTAL</b>	<b>S\$ 485.00</b>

E & O. E

All cheque payment should be "Crossed" and made payable to "CL APPRAISER PTE LTD"

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd



**24 Peshurst Place, Singapore 556440**  
**Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783**  
**Reg No: 201000228E**

## VEHICLE INSPECTION REPORT

To: Li Yang  
C/o: STK Auto (S) Pte Ltd  
8 Kaki Bukit Avenue 4  
#03-21 Premier @ Kaki Bukit, Singapore 415875

Date : 26 October 2021  
Our ref : STK/10/2103/TP

Accident Date : 17 October 2021  
Inspection Date : 21 October 2021  
Repairer Name : STK Auto (S) Pte Ltd  
8 Kaki Bukit Avenue 4  
#03-21 Premier @ Kaki Bukit, Singapore 415875  
Type of Survey : Third Party

### PARTICULARS OF VEHICLE

Registration No	: SMA 5189 Y	Year / Capacity	: 2018 / 1197 cc
Make / Model	: Nissan Qashqai	Colour	: White
Chassis No	: SJNFEAJ11U2233989	Mileage	: 29918
Engine No	: HRA2595151A		

### CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front Nearside	: Bridgestone	215/60 R17	5 mm	Sport
Front Offside	: Bridgestone	215/60 R17	5 mm	Sport
Rear Nearside	: Bridgestone	215/60 R17	5 mm	Sport
Rear Offside	: Bridgestone	215/60 R17	5 mm	Sport

### GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the rear portion.  
(Details refer to the photographs attached)

Enclosed number of photographs: 45 copies

### REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

### RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$3,200.00** on a contractual basis.

Under normal circumstances, the repair period would be about 5 (Five) working days.

Vehicle Registration No.: SMA 5189 Y

Our Ref No.: STK/10/2103/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

**SPARE PARTS - LIST ITEMS**

1	Rear o/s taillamp	Damage	\$ 485.60	\$ 485.60
1	Rear bumper	Damage	\$ 737.00	\$ 737.00
1	Rear bumper inner sponge	Damage	\$ 200.80	\$ 200.80
1	Rear bumper reinforcement	Damage	\$ 659.20	\$ 659.20
1	Rear bumper reinforcement stay	Damage	\$ 135.00	\$ 135.00
1	Rear bumper o/s side retainer	Necessary	\$ 40.20	\$ 40.20
1	Rear o/s fender	Repair	\$ 1,269.40	
			<b>\$ 3,527.20</b>	<b>\$ 2,257.80</b>
			<i>Less 10%</i>	<i>\$ 225.78</i>
<b>Total Cost - List Items</b>			<b>\$ 3,174.48</b>	<b>\$ 2,032.02</b>

**SPECIAL NETT ITEMS**

1	Rear reverse sensor (1 set)	Damage	\$ 350.00	\$ 350.00
1	Rear bumper clip (1 set)	Necessary	\$ 60.00	\$ 60.00
<b>Total Cost - Special Nett items</b>			<b>\$ 410.00</b>	<b>\$ 410.00</b>

**Total cost of parts**
**\$ 3,584.48 \$ 2,442.02**



Vehicle Registration No.: SMA 5189 Y

Our Ref No.:

STK/10/2103/TP

S/No	Description	Repairer's Estimate	Revised Amount
	<b>Total cost of parts c/f</b>	<b>\$ 3,584.48</b>	<b>\$ 2,442.02</b>

### LABOUR

1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00	\$ 50.00
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 120.00	\$ 80.00
3	To apply undercoating on repaired and replaced panel.	\$ 80.00	\$ 30.00
4	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,080.00	\$ 750.00
5	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,000.00	\$ 660.00

**GRAND TOTAL**

<b>\$ 5,944.48</b>	<b>\$ 4,012.02</b>
--------------------	--------------------

Vehicle Registration No.: SMA 5189 Y

Our Ref No.: STK/10/2103/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 3,200.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

**Disclaimer**

*The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.*

**C L APPRAISER PTE LTD**



Cheong K. H  
Automotive Appraiser







































































RECORD MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

## TAX INVOICE

Date of Request: 03/11/2021

Your Ref No: 004240

Dear Sir/Madam,

Date of Accident: 17/10/2021 00:00 (SGT)

Vehicle No: SMA5189Y

Place of Accident: Tampines Ave 5, Singapore

With reference to your application for the accident report, we have attached the following accident report as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SJG6036C	Tampines Ave 5, Singapore	(29.00 )	1	(27.10 )
GST Amount				(1.90 )
Total Amount Due (GST Inclusive)				(29.00 )

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank you.

This is a computer generated document and requires no signature.



Enquire Vehicle's Insurance Particulars ( As At 17 Oct 2021 / 14:35:00 )

Vehicle No.:

**SJG6036C**

Make Description/Model:

**MERCEDES BENZ / GLC200 (R18 LED)**

Insurance Company Name:

**AIG ASIA PACIFIC INSURANCE PTE. LTD.**

Business Transaction Reference No.:

**20211019114902005040**

Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).

Printed on 19 Oct 2021 11:49:28

Copyright © Land Transport Authority of Singapore 2021

Enquire Vehicle's Insurance Particulars ( As At 17 Oct 2021 / 14:35:00 )

Vehicle No.:

**SJG6036C**

Make Description/Model:

**MERCEDES BENZ / GLC200 (R18 LED)**

Insurance Company Name:

**AIG ASIA PACIFIC INSURANCE PTE. LTD.**

Business Transaction Reference No.:

**20211029095205120415**

Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).

Printed on 29 Oct 2021 09:52:10

Copyright © Land Transport Authority of Singapore 2021





Thank you

Hoon Ang Ping has successfully logged out.  
Your last login date and time was 29 Oct 2021, 09:49:42.  
To return to ONE.MOTORING, please [click here](#)  
For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(S)
1	Vehicle	SJG6036C	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49



Thank you .

Hoon Ang Ping has successfully logged out.

Your last login date and time was 19 Oct 2021, 11:43:44.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(S\$)
1	Vehicle	SJG6036C		18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49