SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 18/10/2021 19:50 (SGT) Date of Accident 17/10/2021 14:35 (SGT) Exact Location of Accident Tampines Ave 5, Singapore Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMA5189Y

INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner LI YANG NRIC No. S8157268B Email Address ly.20080808@hotmail.com Mobile Phone No (Phone) +65-93207181 Alternative Phone No +65-93207181

VEHICLE PARTICULARS

Manufacturer

Nissan Model Qashqai Variant Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Private car Transmission Auto CC 1200

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd. Type of Coverage Comprehensive Fleet Policy Policy Number DMPCSNW00033702100 Cover Note Number

DRIVER

Name of Driver LI YANG NRIC No. S8157268B Date Of Birth 25/05/1981 Occupation Indoor Date Of Driving Pass 19/03/2008 Driving experience 13 YEARS AND 7 MONTHS Gender Female Mobile Number (Phone) +65-93207181 Alt. Phone Number +65-93207181 Email Address ly.20080808@hotmail.com Address **BLK 515B TAMPINES CENTRAL 7** Address complement #15-14 Postcode 522515 Is the driver the policyholder? Yes If No. Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Raining Road Surface Wet OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? No Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1 Name SHI LUOJIA Gender Female PASSENGER 2 Name SHI XIAO BAO Gender Male PASSENGER 3 Name MARIA CLAIRE ANTONIO MAMARIL Gender Female DETAILS OF POLICE ACTION Was the accident reported to the police? Police Station Name Tampines Neighbourhood Police Centre Police Station Phone No (Phone) +65-18005871999 Alt. Police Station Phone No (Fax) +65-65871699 Police Station Address 6 Tampines Ave 4 Singapore 529682 Was notice of intended Prosecution given?

CIRCUMSTANCES OF ACCIDENT

PLS REFER TO THE POLICE REPORT:T/20211017/2057

If yes, against whom?

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Reasons for not uploading a video of the accident

WITH DRIVER

Was there any audio recorded?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJG6036C Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Private car Name of Driver Contact Number Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

INJURED PERSONS DETAILS

INJURED 1

Name of injured person Gender Phone No Address Address Complement Post Code Approximate Age Years Old Injuries Sustained Injured person in which vehicle? Were seat belts worn? Was this injured conveyed to hospital by ambulance?	LI YANG Female - - - - - SLIGHT SMA5189Y Yes
Was this injured conveyed to hospital by ambulance?	-

INJURED 2

Name of injured person Gender	SHI XIAO BAO Male
Phone No	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	SLIGHT
Injured person in which vehicle? Were seat belts worn?	SMA5189Y
Was this injured conveyed to hospital by ambulance?	No

INJURED 3

Name of injured person Gender Phone No Address	MARIA CLAIRE ANTONIO MAMARIL Female -
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	SLIGHT
Injured person in which vehicle?	SMA5189Y
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful</u> and <u>accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

4 police report.

Tampines Au

1. algor to the police report: 5/20311011/301								
r.	1/5	et has	1.	77.	not is	Travel.	5/20011111	1 1 200-7.
	73	The same	100	property.	pointe	243000	1/120211011	1201
n.	151				Contract of the Contract of th		Marie Company of the	
r.								
A.								
			-	-				The second second second
	-							
· · · · · · · · · · · · · · · · · · ·	-	-						-
A.			- 1		in an inches			
· · · · · · · · · · · · · · · · · · ·								
			-					
								٥
				- Inches		- 1000 (1000)		
f.								
	_							
P								
F			Waster .					
					100000000000000000000000000000000000000			
A			-					
f								
P								
				183				
h								
	P		No.					
	in-day.		Appellation Co.					
	- Santa			111		-		
		-				- page 12-2-2-2-2-2-2-2-2-2-2-2-2-2-2-2-2-2-2-		
				-				
								7

Declaration

two declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel





3 of 4

Report No. T/20211017/2057

Police Station Of Origin: Tampines N.P.C 6 Tampines Avenue 4 SINGAPORE 529682

Tel No: 1800-5871999 CONTINUATION OF REPORT

Passenger					OREGODDED
Name	MARIA CLAIRE ANTONIO MAMARIL		ID No.	8	G8569225P
Related Vehicle	SMA5189Y (Car)		Contact No.		83487713
Hospital/Clinic	NIL		Class Driving Licent Expiry	g	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge NIL			

Brief Details.

On 17/10/21 at about 1435hrs, I was driving along Tampines Ave 5 towards Tampines Ave 6. I was driving on lane 2 of a 2 lane road. I made a left turn to Tampines Ave 6 however there was a bicycle crossing thus I had to stop. V2 was driving behind me, collided into the rear right side of my rear bumper.

NIL

Degree of Injury

Police and Ambulance were not at scene. I have in-car-camera pointed to the rear of my vehicle which captured the incident. The car subsequently drove off straight before I could exit my vehicle. As I was holding up traffic and V2 did not make a stop, I moved off so as to not choke the turning point.

I am not sure of the estimated cost of repairs.


No. of Days granted Medical Leave






















Institution / School Name:

Date of Expiry:

1 of 4

Report No. T/20211017/2057

Police Station Of Origin: Tampines N.P.C 6 Tampines Avenue 4 SINGAPORE 529682

REPORT OF A TRAFFIC ACCIDENT

Tel No: 1800-5871999

Race:

Chinese

Occupation:

Telephone Marketer

Date/Time 17/10/202		fade:	Vide Report No.:	Station Diary No.: 65		
Informan	t's Particu	ulars				
Name of I LI YANG	nformant:		Address: APT BLK 515B TAMP 522515	INES CENTRAL 7 #15-14 SINGAPORE		
ID Type / NRIC NO		68B	Contact No.: Home/Office: Mobile: 93207181			
Nationality			Email:			
Sex: Female	Age: 40	Date of Birth: 25/05/1981	Type of Informant: Driver			

Driving Licence Information:

Language:

English

Class: 3

seneral infor	nation of the Accider	Drink	Date/Time of	Type of Location
Type of Accident:	Non-Injury Hit and Run	Drive:	Accident: 17/10/2021 14:35	T-Junction
Location: TAMPINES A Weather:	VENUE 5	Road Surface:		Road Speed Limit:
Drizzling Traffic Flow: Two Way		Traffic Control: Traffic Light - Wo	PARTY CARL	Traffic Volume: Light
Type of Collis	sion: ring Vehicles - Head Te			Anyone conveyed by ambulance: No

Details of Volume Vehicle No.	The second secon	Make	Model	Color	Condition	No of Passenge
SJG6036C	Car	MERCEDES BENZ				0
SMA5189Y	Car	NISSAN	QASHQAI 1.2 DIG-T CVT	White	Slightly Damaged	3

Details of Vo	ehicle Insurance	The second secon		
Vehicle No.		Insurance No	Effective	Expiry Date
venicle No.	mourance company			





Police Station Of Origin: Tampines N.P.C 6 Tampines Avenue 4 SINGAPORE 529682 Tel No: 1800-5871999

2 of 4 Report No. T/20211017/2057

CONTINUATION OF REPORT

Details of Vi	ehicle Insurance			
	Insurance Company	Insurance No	Effective	Expiry Date
SMA5189Y	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	DMPCSNW000337 02100	09/02/2021	08/02/2022

Details of Perso				-	
Any Pedestrian	nvolved: No			-	and a second real file of
No. of Pedestria	ns Injured: NIL	Use of Pede	actria	n Cros	oings NA
Passenger	AND EVEN HER TO SERVICE	OSC OF FEGE	estria	n Cros	sing: NA
Name	SHI LUOJIA).	T1839068F
Related Vehicle	SMA5189Y (Car)		Conta	act No.	NIL
Hospital/Clinic	NIL			of ng ce & y Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discha		NIL	
No. of Days gran	ted Medical Leave NIL	Degree of Ir	niur/	NIL	
Driver	Company of the second of the second	203.00 01 11	July	LAIL	
Name	LI YANG	1	ID No.		S8157268B
Related Vehicle	SMA5189Y (Car)			ct No.	93207181
Hospital/Clinic	NIL	L L	Class of Driving Licence & Expiry Date		Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discha		NIL	
No. of Days grant	ed Medical Leave NIL	Degree of In	iury	NIL	
Passenger	Pellines and the second of the second	, Dugico or in	July	- VIL	244
Name	SHI XIAO BAO	10	D No.	T	S8169271D
Related Vehicle	SMA5189Y (Car)		Contact No.		93266319 M
Hospital/Clinic	NIL	D	Class of Driving Licence & Expiry Date		Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Dischar		NIL	
	ed Medical Leave NIL	Degree of Inj		IVIL	



3 of 4

Report No. T/20211017/2057

Police Station Of Origin: Tampines N.P.C 6 Tampines Avenue 4 SINGAPORE 529682

Tel No: 1800-5871999 CONTINUATION OF REPORT

Passenger						005000000
Name	MARIA CLAIRE ANTONIO MAMARIL			ID No.		G8569225P
Related Vehicle	SMA5189Y (Car)			Contact No.		83487713
Hospital/Clinic	NIL			Class Drivin Licend Expire	g	Class: NIL Date of Expiry: NIL
Date Treatment	NIL Date Disc				NIL	
No. of Days gran	NIL	Degree o	f Injury	NIL		

Brief Details.

On 17/10/21 at about 1435hrs, I was driving along Tampines Ave 5 towards Tampines Ave 6. I was driving on lane 2 of a 2 lane road. I made a left turn to Tampines Ave 6 however there was a bicycle crossing thus I had to stop. V2 was driving behind me, collided into the rear right side of my rear bumper.

Police and Ambulance were not at scene. I have in-car-camera pointed to the rear of my vehicle which captured the incident. The car subsequently drove off straight before I could exit my vehicle. As I was holding up traffic and V2 did not make a stop, I moved off so as to not choke the turning point.

I am not sure of the estimated cost of repairs.





Police Station Of Origin: Tampines N.P.C 6 Tampines Avenue 4 SINGAPORE 529682 Tel No: 1800-5871999

4 of 4 Report No. T/20211017/2057

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature of Officer Recording The Report. G / Sgt 3 NURFAIZ BIN NOORDIN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 17/10/2021 17:14
Officer In Charge Of Case: TP / HRT / SI KALESWARI PALANI Contact No.: 65476902	Classification Of Case:
Authentication Stamp	Ad-