



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:GARNET

Ref: CC4/ASM22002338/Apa3q2
Date: 30/12/2022
Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 554C	Veh. Inspected	SMY 1196B
Policy No.	P2459880	Coverage (\$)	0.00
Claim No.	S2M03VLP	Excess (\$)	0.00
Assign From		Assign Date	14/03/2022

2. Vehicle Particulars & Condition

Make & Model	MINI ONE	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	WMWXU520002P07713	Colour	RED
Odometer	13048 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/55 R16	PIRELLI	6 mm
L/H Front Tyre	185/55 R16	PIRELLI	6 mm
R/H Rear Tyre	185/55 R16	PIRELLI	6 mm
L/H Rear Tyre	185/55 R16	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/03/2022	Inspection Date	14/03/2022
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**