

TPAXA.
Veron.

SJW818T. 2015 June

2020
Spray Painting

Mercedes Benz C180 1555cc

WDD2050402R071952

Rees RH Door	Dented	2261. ✓
Rees RH Door Lock	MP M	549. +
Rees RH Door Weatherstrip	MP	285 ✓
Rees RH Door Glass Regulator	MP	586. +
Rees RH Wheel Rim	Cut	1280. 680(SN)
Rees RH Tyre	MP MP	380(SN) +
Front RH Door	Reps	2195 +
Front RH Door Weatherstrip	MP MP	278. +

2546 S.N. 680

2291.40

SJW 818 T.

Panel Beating
Spray Painting
Wiring.

1210

~~800~~ 400
~~1000~~ 600

~~50~~ 30

~~300~~ 100

~~150~~ 80

To transfer front and rear door fittings.
To perform wheel alignment.

10,114

total: 4181.40.

L/S: 3.31c

04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: