

REF: CTZ/

ASS. REC. BY:

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s LHMC

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: TBA

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 852k

IDAC Accident Rpt: _____ Consistent? : Yes or No


GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV REP. 24 HRS

Date: 11/12/22 Person Contacted: _____ Vehicle: IN / OUT



Veh No: PTL 3320A Regn: 11, 08

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit Lanch c.c. 1499

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 180047 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMYPRCY2A9M 000593

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII 18Rlm / STD A/Rlm or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 2 mm

L/Bal. 2 mm

D.O.A. 11/3/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trlp: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

\$ + RS. SI

Fuel

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: DMPCSNW00160702100
 Repairer Reference: 72522
 Date calculated: 14/03/2022 1:38 PM

Full Report
 Registration: SJL 3320A
 Printed: 14/03/2022 1:38 PM

Summary Information

Claim Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	DMPCSNW00160702100	Date of Incident:	11/03/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	MITSUBISHI		
Model:	LANCER (CY,CX,CZ)		
Sub Model:	LANCER		
Model Sheet Number:	32 39 82		
Registration:	SJL 3320A		
VIN number:			
Odometer:	180073		
Model Specs			
FROM 09/2008	AIR CONDITIONING	1.5 LTR 64KW	4-DOOR SALOON
TWO COAT METALLIC	PREPARE OFF VEHICLE		

Not withair
Presumy After Rain
3 days

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	PREPARATION TIME		2.0	8.40
514110 00	R + R FRONT BUMPER		8.0	33.60
541011 10)	R + R LEFT HEADLAMP UNIT		1.0	4.20
NO NUMBER	ADJUST HEADLAMPS		2.0	8.40
0741	L/F WING REPAIR		15.0*	63.00
Labour Cost			Hrs	WU
Panel / Mechanical Labour			2.80	28.0
Total of Labour				117.60

Paint

Paint Work

SYSTEM AZT

Code	Description - TWO COAT METALLIC	Time Basis 10 WU/h		
			WU	Price SGD
	L/F WING REPAIR PAINTING >50%		16.0	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Audatex System Using Manufacturer Times

PRINT DATE 14/03/2022

Material Per Part

Code	Description
0741	L/F WING REPAIR PAINTING >50%

Price SGD

16.20

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint				
Preparation Main Work Metal		2.50	16.0	
Total	10 WU/h	4.10	41.0	105.00
				172.20

Material Cost - Paint

Repair Painting	Price SGD
Material-constant Metal Preparation	16.20
Total	28.60
	44.80

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01	Price SGD
0575	LEFT HEADLAMP ASSY	8301A907	Original		
f: OEM Parts					
n: Non-OEM Parts					
u: Used parts					
Savings					
Subtotal					0.00
Fixed Sundry Parts Price					380.00
Total					100.00
					480.00

Final Calculation

Parts	SGD	SGD
Fixed Sundry Parts Price		
Total Parts	380.00	
	100.00	
Labour Time Base 10 WU/h		480.00
Total 28.0 WU X 42.00 SGD/h		
Total of Labour	117.60	
Paint Work Time Base 10 WU/h		117.60
Labour Cost 41.0 WU X 42.00 SGD/h		
Material Cost		
Total Paint Including Material	172.20	
	44.80	
Repair Cost Excludes GST		217.00
GST (+7.0%)		
Repair Cost Included GST		814.60
		57.02
		871.62



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	14/03/2022 12:52 (SGT)
Date of Accident	11/03/2022 19:52 (SGT)
Exact Location of Accident	Yishun Ave 5, Singapore
Additional Location Information	Blk 101 Chong Pang, Yishun Avenue 5 Open Carpark
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJL3320A
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Suganthi D/O Vadivelu
NRIC No	SXXXX439F
Email Address	geminigal_06@hotmail.com
Mobile Phone No	(Phone) +65-96705923
Alternative Phone No	+65-96705923

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Lancer
Variant	1.5 MIVEC GLS 4A/T
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Manual
CC	1499

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMPCSNW00160702100
Cover Note Number	-

DRIVER

Name of Driver	Suganthi D/O Vadivelu
NRIC No	SXXXX439F



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



A - SJL 3320A

B - BGB 3726J

Blk 101 Yishun Ave 5
CP

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

439F

Vehicle Details

Vehicle No.:

SJL3320A

Vehicle to be Exported:

No

Intended Deregistration Date:

14 Mar 2022

Vehicle Make:

MITSUBISHI

Vehicle Model:

LANCER 1.5 MIVEC GLS 4A/T

Primary Colour:

Silver

Manufacturing Year:

2008

Engine No.:

4A910109124

Chassis No.:

JMYSRCY2A9U000593

Maximum Power Output:

80.0 kW (107 bhp)

Open Market Value:

\$18,090.00

Original Registration Date:

24 Nov 2008

First Registration Date:

24 Nov 2008

Transfer Count:

2

Actual ARF Paid:

\$18,090.00

Intended PARF Rebate Details

PARF Eligibility:

Forfeited

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

23 Nov 2028

COE Category:

E - Open Category

COE Period(Years):

10

PQP Paid:

\$29,670.00

COE Rebate Amount:

\$19,854.00

Total Rebate Amount:

\$19,854.00

The information contained herein is correct as at 14 Mar 2022

OK