

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD	1	Ref:	CS3/ASM22002364/Vty3e2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11	I	Date:	30/03/2022	
	ATTN: KHONG LYI	NN	(	Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SMV 5639E	Veh. Inspected		SLL 9064B	
	Policy No.	GA572364	Coverage (\$)		0.00	
	Claim No.	S2M03VPN	Excess (\$)		0.00	
	Assign From	KHONG LYNN	Assign Date		15/03/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	SSANGYONG XLV	c.c		1597	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	KPT36B1USHP145391	Colour		BROWN	
	Odometer	358732 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	MICHELIN		5 mm	
	L/H Front Tyre	205/60 R16	MICHELIN		5 mm	
	R/H Rear Tyre	205/60 R16	MICHELIN		5 mm	
	L/H Rear Tyre	205/60 R16	MICHELIN		5 mm	
4.	Description of Damages					
	THE VEHICLE SUS PORTION.	HE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR DRTION.				
5.	General Information					
	Accident Date	11/03/2022	Inspect Date / T	ime	15/03/2022 ( 04:00 PM )	
	Survey held at	KENT AUTO SERVICES				
	2 KAKI BUKIT AVE 2 #01-21 KAKI BUKIT AUTOHUB SINGAPORE 417921					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000-\$9,000					
5b.	Estimate Days of Repair					

Report Ref No. CS3/ASM22002364/Vty3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

ESTIMATED NORMAL PERIOD FOR REPAIR:

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

**6 Working Days**