



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD  
73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556  
ATTN: ENG HUEY HUEY

Ref: CS/INC22002376/Evy3e2

Date: 27/07/2022

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                |                |            |
|--------------|----------------|----------------|------------|
| Insured Veh. | SCV 8763C      | Veh. Inspected | SMW 6310R  |
| Policy No.   |                | Coverage (\$)  | 0.00       |
| Claim No.    | MT/1164827-001 | Excess (\$)    | 0.00       |
| Assign From  | Theresa Vimala | Assign Date    | 15/03/2022 |

### 2. Vehicle Particulars & Condition

|              |                   |              |                    |
|--------------|-------------------|--------------|--------------------|
| Make & Model | HYUNDAI IONIQ     | c.c          | 1580               |
| Engine No.   | HIDDEN            | Year of Reg. | 2020               |
| Chassis No.  | KMHC851CVLU201170 | Colour       | GREY               |
| Odometer     | 85471 KM          | Steering     | IN ORDER           |
| Brakes       | IN ORDER          | Modification | STANDARD ALLOY RIM |
| General      | GOOD              |              |                    |

### 3. Conditions of Tyres

|                | Size       | Make        | Balance |
|----------------|------------|-------------|---------|
| R/H Front Tyre | 195/65 R15 | BRIDGESTONE | 4 mm    |
| L/H Front Tyre | 195/65 R15 | BRIDGESTONE | 4 mm    |
| R/H Rear Tyre  | 195/65 R15 | BRIDGESTONE | 4 mm    |
| L/H Rear Tyre  | 195/65 R15 | BRIDGESTONE | 4 mm    |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

|                |                                                                                |                     |                         |
|----------------|--------------------------------------------------------------------------------|---------------------|-------------------------|
| Accident Date  | 12/03/2022                                                                     | Inspect Date / Time | 15/03/2022 ( 02:50 PM ) |
| Survey held at | PEGASUS ENGINEERING & TRADING PTE LTD<br>74 Kian Teck Road<br>Singapore 628800 |                     |                         |

### 5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS..  
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 3 Working Days |
|-------------------------------------|----------------|