


**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 QD  TP /  S / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s: VIN'S MOTOR  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: SNM22D201778/C02  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SLL5927M Yr Regn: 28 Feb 2017  
 Type  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: MAZDA 5 c.c. 1998  
 Colour: Silver A/C: Insured / Std / NI / NA  
 Sp. Reading: 75028 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JM6CW1071G0125180 \*  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake:  Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/R or \_\_\_\_\_  
 Tyre Size: F: 205/55R16  
 R: //

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**



BS /  DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_

Bal. or Market Value: \$59k  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 5 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Front 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm Rear 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 22-03-2022  
 Survey held at \_\_\_\_\_ W/S 4:30pm  
 Des. of Damages: Frt /  Rea / O/S / N/S / U/C / Rooftop or \_\_\_\_\_  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
23/03/22@2.45pm	revised to Pauline Tham via Merimen.

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

1) \_\_\_\_\_  
 Date/Time, File Return to?  
 2) \_\_\_\_\_  
 Report Filed?  
 Long Copy/MP/...

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Insp (\$ \_\_\_\_\_)  
 : Wash/End (\$ \_\_\_\_\_)

Survey Fee:	
Transportation:	
3 + RS. SI	
Photos	
Other:	
TOTAL	