

(08/11/13) wef

ASS. REC. BY: 2mm

REF:

CS/AIS 2200 2396/Rty³

683w

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBJ 93Eat Workshop m/s Yew Teeof 34, WOODMAN CLOSE #01-12 @ MBWAInsured: AIS

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

49K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBJ 93EYr Regn: 2018 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

RENAULT KANGOO 1.5 DCI AT c.c 1461

Colour:

GREY

A/C: Insured / Std / NI / NA

Sp. Reading

88173

T/Radio: Insured / Std / NI / NA

Eng/No:

VE1FWT2H359570127

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CONTINENTAL

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

03/03/22

D.O.I.

16/03/22

Survey held at

Yew Tee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair Limit - 30K

cost of repair of L/S \$1,400.00 /- with 02 days of repair

red:1236.6.6 ;59%

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS, SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: Fax: Email:

INSURER : ALLIANZ INSURANCE CO SINGAPORE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTMG/TP/2203/004
Policy No:	MOMVC000009094-00-000	Date of Loss:	03/03/2022
Vehicle Reg. No.:	GBJ93E	Driveable?	no
Driver Age:		Third Party Vehicle No.:	XE4190Y
Any Injuries?	no	Contact No:	
Insured/Claimant:	Ken Landscape Services	Driver:	CHONG YEE LE (ZHANG YULE)

PARTS MODEL

Make/Model:	Renault, Kangoo 1.4A - VF1FC0BAA33	Vehicle Reg. Date:	04/01/2022
Vehicle Colour:		Engine Number:	
Chassis No:		Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

DESCRIPTION OF ACCIDENT/LOSS

Description of Accident/loss Refer to GIA report
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	1,746.66
Miscellaneous Items	40.00
Labour	450.00
Paintwork Labour	400.00
Towing	0.00
Gross Total(S\$):	2,636.66
GST 7.00%(S\$):	184.57
Nett Amount(S\$):	2,821.23

This claim is handled by: Tee Shu yi

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR FENDER RH Repair	1,624.80	0.00	1,624.80
2	1	REAR FENDER INNER SHIELD RH X	121.86	0.00	121.86

Total Parts (\$\$) 1,746.66

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR FENDER INNER SHEILD CLIP 12	40.00	0.00	40.00 20

Sub Total (\$\$) 40.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	450.00	0.00	450.00 200

Gross Labour Cost (\$\$) 450.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	400.00	0.00	400.00 200

Gross Labour Cost (\$\$) 400.00

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair
 H# 90010068
 2 3/4 days
 1/2 P/P
 16/03/22 @ 1535
 Resurvey after repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 04/03/2022 11:32 (SGT)
Date of Accident 03/03/2022 09:30 (SGT)
Exact Location of Accident Singapore
Additional Location Information 53 SENNET LANE
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBJ93E

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner Ken Landscape Services
Company Reg No 5XXXX683W
Email Address ENQUIRY@KENLANDSCAPE.COM.SG
Mobile Phone No (Phone) +65-83791036
Alternative Phone No (Home) +65-83791036

VEHICLE PARTICULARS

Manufacturer Renault
Model Kangoo
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Commercial vehicle
Transmission Auto
CC 0

INSURANCE COMPANY

Name of Insurance Company Great American Insurance Company
Type of Coverage Comprehensive
Fleet Policy No
Policy Number MOMVC000009094-00-000
Cover Note Number -

DRIVER

Name of Driver CHONG YEE LE (ZHANG YULE)
NRIC No SXXXX282I

Date Of Birth
Occupation
Date Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

23/11/1992
Outdoor
28/08/2014
7 YEARS AND 7 MONTHS
Male
(Phone) +65-83791036
-
EDAVIDCHONG@GMAIL.COM
BLK 50 CCK NORTH 6 #17-02
-
689574
No
Employee
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Collision - Head to Rear
Clear
Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other vehicle or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No
2
No
-
Yes
1
No

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Police Station Name
Police Station Phone No
Alt. Police Station Phone No
Police Station Address
Was notice of intended Prosecution given?
If yes, against whom?

Yes
Choa Chu Kang Neighbourhood Police Centre
(Phone) +65-18007659999
(Fax) +65-67644104
No 20 Choa Chu Kang Street 52 #01-02 Singapore 689286
No
-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?
Was there any video captured by Car Camera?
Was there any audio recorded?

Yes
No
No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number
Vehicle Manufacturer
Vehicle Model
Vehicle Variant
Vehicle Colour
Vehicle Category

XE4190Y
-
-
-
-
Commercial vehicle

Name of Driver -
Contact Number -
Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Ken Landscape Services
50 Choa Chu Kang North 6
#17-02 Yew Mei Green
Singapore 689574

[Signature]

[Signature]

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



veh A = GRS93E
veh B = XE4190Y

Describe Circumstances of the Accident


GBJ 95E

My vehicle Renault Kangoo Maxi A was parked along S3 Senett Lane and a rubbish truck from Eco Super complete KE 4190 Y hit my vehicle by accident, resulting in a dent in the side panel. Time of occurrence was in the morning at 9:10 am on the 05/05/2022. Weather was fine and clear, no rain.

Declaration

We declare the foregoing particulars are true in every respect.

Ken Landscape Services
50 Choa Chu Kang North 6
#17-02 Yew Mei Green
Singapore 689574

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Business
Owner ID:	683W
Vehicle No.:	GBJ93E
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Mar 2022
Vehicle Make:	RENAULT
Vehicle Model:	KANGOO 1.5 DCI AT EU6 110BHP
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	K9KF647D087456
Chassis No.:	VF1FWT2H359570127
Maximum Power Output:	-
Open Market Value:	\$19,438.00
Original Registration Date:	26 Nov 2018
First Registration Date:	26 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$972.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	25 Nov 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$27,509.00
COE Rebate Amount:	\$18,392.00
Total Rebate Amount:	\$18,392.00

The information contained herein is correct as at 18 Mar 2022

OK