



> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	471X
Vehicle Details	
Vehicle No.:	YN87785
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Mar 2022
Vehicle Make:	ISUZU
Vehicle Model:	NNR85UH4A
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	4JJ11D3497
Chassis No.:	JAANNR85HE7100050
Maximum Power Output:	-
Open Market Value:	\$29,602.00
Original Registration Date:	22 May 2014
First Registration Date:	22 May 2014
Transfer Count:	0
Actual ARF Paid:	\$1,481.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 May 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$4,995.00
COE Rebate Amount:	\$1,090.00
<b>Total Rebate Amount:</b>	<b>\$1,090.00</b>

The information contained herein is correct as at 15 Mar 2022

OK



# Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg Roc/GST: (199806235M)

Vehicle No. YN8778S ISUZU

Page No. 1 - 3

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	<b>PARTS (LIST ITEMS)</b>			
1	Front windscreen / BR		850.00	
1	Front windscreen seal / MC		50.00	
1	Front windscreen moulding upper / MC		90.00	
1	Front windscreen moulding lower / MC		100.00	
1	Front panel X R		552.00	
1	Front panel rubber seal X		36.00	
1	Front panel emblem "Isuzu" / MC		108.00	
1	Front panel sticker "Reward-NN" / MC		26.40	
1	Front corner top panel Lh / BR		192.00	
1	Side mirror arm top round cover Lh / MIS		12.00	
1	Center grille whole assy / BR		450.00	
7	Center grille clip @7*\$6 / MC		10 42.00	
1	Front bumper / DD		444.00	
1	Front bumper side bracket Lh / BT		102.00	
1	Headlamp Lh / BR		252.00	
1	Signal lamp Lh / BR		90.00	
1	Condense / DD		528.00	
1	Condense bracket Lh / BT		58.00	
1	Condense bracket rh / BT		58.00	
1	Fan cowling with motor / BR		456.00	
1	Front door lh / DD		816.00	
1	Front Regulator & Motor LH ?		312.00	
1	Front door lower wheel arch garnish lh / CRT		78.00	
1	Front door wheel arch garnish inner rubber seal Lh / CR9		60.00	
1	Front door outer center protector garnish lh / CRT		60.00	
1	Front door lock lh ?		114.00	
1	Front door inner trim board lh / CR9		222.00	
1	Front door window glass lh / BR		280.00	
1	Front door upper hinge lh / BT		82.00	
1	Front door lower hinge lh / BT		82.00	
1	Front door checker lh ?		36.00	
1	Front door signal lamp lh / BR		90.00	
1	Front door weatherstrip lh / CR9		138.00	
1	Step up garnish lh / CR9		114.00	
1	Front door pillar Lh / DD		1,260.00	
1	Front door pillar lower extension Lh / DD		180.00	
1	Pillar Wheel arch rubber seal Lh / CR9		48.00	
1	Pillar inner arch garnish Lh (upper) / CR9		60.00	

1	Door pillar rubber seal Lh	<del>BR</del> / CRU		102.00	
1	Headlamp lower rubber protector Lh	/ MIS		18.00	
1	Dashboard	/ CRU		600.00	
1	Floor panel (Repair refer to labour)	X R		-	
			Part Items Total:		
				9,248.40	
			10%	924.84	
				10,173.24	
<b>Page No. 2 - 3</b>					
<b>SPECIAL NETT ITEMS</b>					
1	ERP sticker	/ MC		10.00	
1	Front Windscreen Sealant	/ MC	40	50.00	
1	Front Door Pillar sealant LH	/ MC	20	60.00	
1	Headlamp Bulb LH	/ BR	10	20.00	
1	Signal Lamp Bulb LH	/ BR	10	20.00	
1	Front door Signal Lamp LH	/ BR	10	20.00	
1	Front door bulb LH	X		20.00	
1	Front Panel sealant	X		80.00	
Number plate frnt / BT \$35 /					
			SN Items Total:	280.00	315
			Total Parts	10,453.24	

10,488.24



Wah Hong Motors & Credit Pte Ltd  
Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)  
Email: motor@wahhong.sg  
(199806235M)

Page No. 3-3

Vehicle No. YN8778S ISUZU

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
1	<b>LABOUR</b> To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	2000.00	1000
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1400.00	1000
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	90.00	30
4	To remove and replace front Windscreen	150.00	170
5	To remove and refit dashboard and related wire harness and related parts	300.00	200
6	To remove and refit aircon condenser, related pipes and hoses, vaccum and refill aircon gas	100.00	/
7	To remove and refit/replace Front door LH fitting, trimmings, garnish, window glass and lock mechanism	120.00	50
Labour Total :		4160.00	
TOTAL (PARTS & LABOUR):		14613.24	

Steve CLKK)  
16/3/22, 12.20p

OP- M KL  
EX CORR?  
L/S  
M KL H  
10 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 15/03/2022 14:55 (SGT)  
Date of Accident ..... 14/03/2022 11:40 (SGT)  
Exact Location of Accident ..... Near Opp Blk 1, Singapore  
Additional Location Information ..... HENDERSON ROAD TOWARDS AYE RIGHT TURN TO TELOK  
BLANGAH WAY  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... YN8778S

### INSURED/POLICYHOLDER

Is company? ..... Yes  
Name Of Registered Owner ..... W & Y ELECTRICAL TRADING  
Company Reg No ..... 5XXXX471X  
Email Address ..... SHIRYEO@HOTMAIL.COM  
Mobile Phone No ..... (Phone) +65-96384388  
Alternative Phone No ..... +65-96384388

### VEHICLE PARTICULARS

Manufacturer ..... Isuzu  
Model ..... NNR85UH4A  
Variant ..... -  
Exact purpose for which vehicle was being used at time of  
accident ..... Employment  
Are you claiming under your own insurance policy for repair to  
your vehicle? ..... Yes  
Vehicle Category ..... Commercial vehicle  
Transmission ..... Auto  
CC ..... 2999.

### INSURANCE COMPANY

Name of Insurance Company ..... Lonpac Insurance Bhd  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... Z/21/VC00/110692  
Cover Note Number ..... -

### DRIVER

Name of Driver ..... RANJIT SINGH

Passport No/FIN	GXXXX642U
Date Of Birth	07/08/1991
Occupation	Outdoor
Date Of Driving Pass	27/10/2020
Driving experience	1 YEAR AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-89056185
Alt. Phone Number	-
Email Address	SHIRYEO@HOTMAIL.COM
Address	BLK 257 BANGKIT ROAD, #04-57
Address complement	-
Postcode	670257
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	LI LIZHU
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Bukit Panjang Neighbourhood Police Centre
Police Station Address	No.1 Segar Road #01-05 Singapore 677738
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN & POLICE REPORT NO. T/20220315/2038 FOR SUMMARY

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJR7433A
Vehicle Manufacturer	-
Vehicle Model	-

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



*Ranjit Singh*




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

**Sketch Plan**



**Describe Circumstances of the Accident**

REFER TO POLICE REPORT NO. T/20220315/2030

Lined area for describing the accident circumstances.

**Declaration**

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

*Rajit Singh*

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel





**SINGAPORE  
POLICE FORCE**



T/20220315/2038

Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677738  
Tel No: 1800-8929999

2 of 3

Report No. T/20220315/2038

**CONTINUATION OF REPORT**

Driver			
Name	RANJIT SINGH	ID No.	G2302642U
Related Vehicle	YN8778S (Lorry).	Contact No.	89056185
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	14/03/2022	Date Discharge	14/03/2022
No. of Days granted Medical Leave	03	Degree of Injury	Slight

**Brief Details.**

On 14/3/2022 at about 1130hrs at said location, I was at a traffic light junction and the light was green. I signaled to the right with intention to turn right and waited at the pocket. I inched forward to lookout for oncoming traffic and I saw one car was quite faraway thus I decided to turn right. When I was about half turning, suddenly the car hit onto the left side of my lorry. I stopped my lorry and alighted and spoke to driver. Eventually I unable to capture anything and was conveyed by ambulance eventually. I unable to exchange any details with the said driver or record down his vehicle number. I suffered lower abdomen pain and was given 3days MC from Singapore General Hospital. Earlier today, I received a text message from IO Shiras to proceed to any police station to lodge report on the matter.



**SINGAPORE  
POLICE FORCE**



T/20220315/2038

Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677738  
Tel No: 1800-8929999

3 of 3

Report No. T/20220315/2038

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature of Officer Recording The Report:  
J / SR STAFF SGT ZAKIAH  
BINTE MOHAMMED RASHIDIN

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / GIT /  
STAFF SGT SYED MUHAMMAD ISA BIN  
OMAR ALHABSHEE  
Contact No.: 65476214

NP168

Signature Of Informant:

Date/Time:  
15/03/2022 13:09

Classification Of Case: