...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SURE	OLDER TRACK	ING									
	Notified	Est Submitted	Adj Assigned	Adj Rpt	Δdi	Submitted	Inc A	uth'ed	Status		
	15 Mar 2022	15 Mar 2022	15 Mar 2022	Adj Rpc	, Adj	Submitted	1113 A	dired	Pending for Survey		
Main	15:05 Sendback Est	15:23 S\$ 2,434.75	16:12 Edit Adj Rpt						Report Cancel Case		
	15 Mar 2022 17:11	15 Mar 2022 17:17	15 Mar 2022 17:17				Con	nbine Suppl.	New Assignment		
Зарр "Т	Sendback Est	S\$ 120.00	Assign				2011	тыне эцри	Cancel Case		
CLAIM SUBF	OLDER DETAII	_S									
Insured:	ComfortDelGr	o Driving Centre	Pte Ltd , Co. F	Reg. No. : 1990	501882C,	Tel: +6590	072819), Email: da	ryltan@cdc.com.sg		
Vehicle Reg. No.:	SMM2784K	10/03/2022 17:00 - :50									
Claim Type:	OD	() () ()					Policy/Cover D20MFL0000618_02 (Comprehensive) Note No. : Coverage: 01/01/2022 - 31/12/2022				
				Exc	ess:						
Repairer:	Kang Car Repa	airers Pte Ltd (H	Q) No 1 Kaki Buk	it Ave 6, #02-	06 AutoBa	y@Kaki Bukit	, 41788	3 Kaki Bukit -	Tel: 67477636		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 [Handled by Bhargavi Purushothaman Dhanya]										
Adjuster:	LKK Auto Con	sultants Pte Ltd	(HQ) - Tel: 6256	-3561 [Hand	dled by AD	RIAN LING] [Fi	nal Rpt du	e 24/03/2022]		
Driver/Custod an:		Ansari (22 / Femal									
ASSOCIATEI	D MAIL RECEIV	'ED						View Al	I Compose Case M		
There are no r	mail for this case.							-			
No results.											
ALL ASSOCI		wer/							Create N		
No. Status No results.	Type Ass To	signed Note						Created On	Created By By		
ADJUSTER'S	CLAIM REFER	ENCE									
Assignment Fr			ional Insurance	Pte Ltd (HQ)							
Adj File Ref No		CS/III22002430/ATY3			Assignment Date:		15	15/03/2022			
Inspection / Ir Date:				Rep	ort Date:						
insurance Clai	im No:			Reci	nd'ed Resv	/. (S\$):					
Manager:	DENISE TAY KWEE CHENG Adjuster:			ADRIAN LING							
Clerical:		(First Pick-up)									
Present Vehicl	e Loc.:	Kang Car Repair	ers Pte Ltd (HQ) (from est.) (Ch	eck-in: 15,	/03/2022)					
	ON OF VEHICLE										
DESCRIPTIO		TOYOTA VIOS	1.5 (A)								
	•	2NR5342401			Chassis No: MR2B23F3X01178085						
Vehicle Model:		2NR5342401		Cha	ssis No:		MH	R2B23F3X011	78085		
Vehicle Model: Engine No:		2NR5342401 25/06/2019 (20	19)	Cha	SSIS NO:		IMI	R2B23F3X011	78085		
Vehicle Model: Engine No: LTA Reg Date	(Man Yr):		19)		ssis No: meter Rea	ding:		R2B23F3X011 032 km	78085		
Vehicle Model: Engine No: LTA Reg Date Colour of Vehi	(Man Yr): cle:	25/06/2019 (20	19)			ding:			78085		
Vehicle Model: Engine No: LTA Reg Date Colour of Vehi CLAIM LOSS	(Man Yr): cle: DETAILS	25/06/2019 (20	19)	Odo	meter Rea			032 km	78085		
Vehicle Model: Engine No: LTA Reg Date Colour of Vehi CLAIM LOSS Police Report I	(Man Yr): icle: G DETAILS No (Date):	25/06/2019 (20		Odo		<u> </u>			78085		
DESCRIPTION Vehicle Model: Engine No: LTA Reg Date Colour of Vehi CLAIM LOSS Police Report I Collision With: Third Party Inv	(Man Yr): ccle: DETAILS No (Date):	25/06/2019 (20 Silver		Odo Part Natu	meter Rea y At Fault:	;		032 km	78085		

I WAS DRIVING ALONG KAKI BT AVE 1, SUDDENLY A BUS, SBS6391H COLLIDED ONTO THE FRONT RIGHT OF MY CAR WHILE LANE CHANGING.

Description of Accident/Loss:

Singapore

Place of Loss (Postcode):

DOCUMENTS CHECKLIST	All Completed	Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: U Repairer U Handling Insurer				
Note: Remarks are private unless you show it to other parties.				
DOCUMENTS SUMMARY				
Assessment Reports				
• Kang Car Repairers Pte Ltd (HQ) [Thumbnails]:(15/03/22) Repairer Estimates, Repairer Estimates Su	uppl. #1			
Documentation				
• Kang Car Repairers Pte Ltd (HQ) [Thumbnails]:(15/03/22) Singapore Accident Statement, Driver's N				
• India International Insurance Pte Ltd (HQ) [Thumbnails]:(15/03/22) Singapore Accident Statemen	t			