

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Mar 2022 13:03 Sendback Est	15 Mar 2022 14:25 S\$ 9,749.12	15 Mar 2022 14:58 Edit Adj Rpt				Pending for Survey Report Cancel Case

CLAIM SUBFOLDER DETAILS

Insured:	COMFORTDELGRO RENT-A-CAR PTE LTD , Co. Reg. No. : 775H		
Vehicle Reg. No.:	SMA8457D	Date of Loss :	09/03/2022 16:00 - :59 [44 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD	Policy/Cover Note No. :	D20MFL0000326_01 (Comprehensive)
		Excess:	
Repairer:	ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road, 579701 Toa Payoh - Tel: 63838115		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Derrick Tan Ming Chye]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 24/03/2022]		
Driver/Custodian:	YEO PENG KENG STEVEN () Email:		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

ALL ASSOCIATED FILE NOTES

[Create New](#)

No.	Status	Type	Viewer/ Assigned To	Note	Created On	Created By	1st Read By
No results.							

ADJUSTER'S CLAIM REFERENCE

Assignment From:	India International Insurance Pte Ltd (HQ)		
Adj File Ref No:	CS/III22002438/KQY3	Assignment Date:	15/03/2022
Inspection / Investigation Date:		Report Date:	
Insurance Claim No:		Recmd'd Resv. (S\$):	
Manager:	SHIAU CHAN	Adjuster:	KENNETH KONG
Clerical:	(First Pick-up)		
Present Vehicle Loc.:	ComfortDelGro Engineering Pte Ltd (Braddell) (from est.) (Check-in: 15/03/2022)		

DESCRIPTION OF VEHICLE

Vehicle Model:	HONDA VEZEL 1.5 X CVT (A)					
Engine No:	L15B5552067			Chassis No:	RU11302060	
LTA Reg Date (Man Yr):	21/06/2018 (2018)			Odometer Reading:	10000 km	
Colour of Vehicle:	White					

CLAIM LOSS DETAILS

Police Report No (Date):		Party At Fault:	Unknown
Collision With:	Private Vehicle	Nature of Loss:	
Third Party Involved?	Yes	TP Injury Involved?	No
Description of Accident/Loss:			

DOCUMENTS CHECKLIST

[All Completed](#)[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

DOCUMENTS SUMMARY

Assessment Reports

- ComfortDelGro Engineering Pte Ltd (Braddell) [[Thumbnails](#)]:([15/03/22](#)) [Repairer Estimates](#)

Documentation

- ComfortDelGro Engineering Pte Ltd (Braddell) [[Thumbnails](#)]:([15/03/22](#)) [E-filed GIA report, Certificate of Insurance](#)
- India International Insurance Pte Ltd (HQ) [[Thumbnails](#)]:([15/03/22](#)) [Singapore Accident Statement](#)