



Your Ref: 22.29495 CFT

Date: 02<sup>nd</sup> Jun 2022

Our Ref: CS3/ASM21011170/Vvy3e2-1

**M/s Axa Insurance Pte Ltd**

C/o Seah Ong & Partners LLP

36 Robinson Road #12-03 City House

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMH 1101P**

**INSURED VEHICLE: SHD 3510J**

**ACCIDENT DATE: 31/10/2021**

We thank you for your instruction on 16/03/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMH 1101P from M/s Icon Motor Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicles SMH 1101P and SHD 3510J.
- c) Police Report of Vehicles SMH 1101P.
- d) Final Repair Bill of SMH 1101P from M/s Cheng Chuan Motor Services.
- e) Colour damaged vehicle photographs of SMH 1101P.

Pre-Repair Inspection Date : 31/10/2021 at M/s 2 Kaki Bukit Avenue 2 #02-31 Kaki Bukit Autohub, Repairer: Cheng Chuan Motor Services.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMH 1101P
Make & Model	: Audi A4 Sedan 2.0 TFSI S Tronic (NAV)
Year of Registration	: 2018
Chassis Number	: WAUZZZF40JA206486
Engine Capacity	: 1984 cc

2. We recommend that the repairs of the entire damage require about 9 (Nine) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.