

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	11/03/2022 08:43 (SGT)
Date of Accident	10/03/2022 11:18 (SGT)
Exact Location of Accident	Tampines Central 1 & Tampines Central 2, Singapore
Additional Location Information	Along Tampines Ctrl 1 junction with Tampines Ctrl 2 >TMI (after b/s 75009, 6.8km>TMI)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBS6001J
-----------------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	SBS TRANSIT LTD
Company Reg No	1XXXXXXXXXXTE01
Email Address	seahhh@sbstransit.com.sg
Mobile Phone No	(Phone) +65-62444534
Alternative Phone No	(Office) +65-62444534

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	Citaro
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Bus
Transmission	Auto
CC	6374

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	ActLiability
Fleet Policy	No
Policy Number	D-21097501MFBP
Cover Note Number	-

DRIVER

Name of Driver	Chin Tong Choy
----------------------	----------------

NRIC No	SXXXX647H
Date Of Birth	10/12/1949
Occupation	Outdoor
Date Of Driving Pass	09/09/1991
Driving experience	30 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91793868
Alt. Phone Number	-
Email Address	seahhh@sbstransit.com.sg
Address	512, Tampines Central 1
Address complement	Blk 225 Pasir Ris St 21 #03-64 Postal Code : 510225
Postcode	Singapore 520512
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Cross Junction
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	No
Number of Passengers (Including Driver)	10
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	UNKNOWN
Gender	Male

PASSENGER 2

Name	UNKNOWN
Gender	Female

PASSENGER 3

Name	UNKNOWN
Gender	Male

PASSENGER 4

Name	UNKNOWN
Gender	Female

PASSENGER 5

Name	UNKNOWN
Gender	Male

PASSENGER 6

Name	UNKNOWN
Gender	Female

PASSENGER 7

Name	UNKNOWN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

I stopped behind other vehicles at the traffic light as it was red light. When my bus was stationary in the right lane, the lorry YN9175A cam from the rear in the left lane. When it stopped behind other vehicles in its lane. I heard a sound and I then saw the driver walked its rear to close its rear doors. I thus discovered its rear doors had swung open and hit my bus rear LHS. OCC was informed and I seek my office nearby for help. When my office was exchanged details, I was told to continue my service. No injury. That's all. 3P's company :- Bio Plastic Pte Ltd / 63339600 Sales@bioplasticcs.com.sg Supevisor- Mr Tan /98205156

ATTACHMENT(S)

Are accident photos available for attachment? No
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

