

Agency: GA LSZ/LPC/9021451/G334
ASSIGNMENT (Office)
 From (Person): Ona G U of: LPC Date/Time: 28/21/2020
 Estimated Cost: _____ Bill to: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: YP 674SR Insured: XD3336G
 at Workshop no: Omega Auto PL Tel: 97291 8287 Terrence
 at: 160 Elm Drive #06-06 Glen Autocity
 Policy No: _____ Claim No: 19/19/19/VCO5/022728
 Sum Insured: _____ Excess: _____
 Make of Vehicle: _____ D.O.A. 29.11.2019
 (Client's Record) YRS
 CA / REV / REP. / REV 24 HRS 29/11/19 10.30am H.O.D. Endorsement:
 Date/Time: 04/12/19 @ 4.33pm owner writing Vehicle IN/OUT: IN
Person Conducted Terrence

Date/Time	Action/Instruction
	<u>YP 674SR - X</u>
	<u>ST 2002 G - X</u>
	<u>\$6900, 14 Days</u>
	<u>(\$8,000/- Red - 54%)</u>
16.03.22	Submit LS \$8,900.00 ; 14 days (Red \$6,000.00; 40%)

RECEIVED 18 MAR 2020

62

42

ASSIGNMENT

Date: 09/12/19
 Vehicle No: YP6245R
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mit Canter
 Colour: white
 Reg No: 16604
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: 11 / S/Rim / STD A/Rim or
 Tyre Size: F: 195/85 R 15
 R: 11
 BSY DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: 8 mm
 R/Bal: 5 mm
 L/Bal: 5 mm
 D.O.A: w/s
 Survey held at: 09-12-19
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition) PRS
 Remark: The veh had commenced its repair at the time of inspection.
 B.A. or Market Value:
 (Date) Accident Report Consistent? Yes or No
 (Date) PR Seen Consistent? Yes or No
 Est. Repair days Pay Yes or No
 Loss Sum % 3 Val Yes or No
 CA / REV / REP / 24 HRS
 Date Person Contacted Vehicle IN / OUT

Date: 02 Jun 2017
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mit Canter
 Colour: white
 Reg No: 16604
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: 11 / S/Rim / STD A/Rim or
 Tyre Size: F: 195/85 R 15
 R: 11
 BSY DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: 8 mm
 R/Bal: 5/5 mm
 L/Bal: 5/5 mm
 D.O.A: w/s
 Survey held at: 09-12-19
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: 11/12/19
 Action / Instruction: \$18k - \$20k

RECEIVED 2019

Date: 11/12/19
 Time: 4:03 PM
 Action: Prof. Report
 Final Report
 Days of Repair:
 Resurvey No. of Trip:
 Survey Fee: 120
 Transportation: 120