

REF: Thevan


REF: CS3/11122002460/vvy3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 UD/TP/WS/TPRES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: _____
 at Workshop no's _____
 of _____
 Insured: **SLQ 8313M**
 Policy No: **D21MFL0000447**
 Claims No: **MFL2022D0000903**
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vch: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: **11k**
 IDAC Accident Report _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **4** days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **FBN 91P** Yr Rogn: **25/9/20**
 Type: M. Car / **Cycle** / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Yamaha Xmax 300** c.c. **299**
 Colour: **black** NC: Insured / Std / NI / NA
 Sp. Reading: **not avail** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **MH35H0840LK012359**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **Good** / Jammed / Leaked / Burnt or
 Brake: **Good** / Jammed / Leaked / Burnt or
 Modl: **NII / SIRIM / STD A/R/M** or
 Tyre Size: F: **120/70-15**
 R: **140/70-14**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / **PIR** / SUMI /
 TOYO / YOKO or
 Front: **6** mm Rear: **6** mm
 R/Bal. _____ mm L/Bal. _____ mm
 D.O.A. **12/2/22** D.O.I. **6/3/22** 1400
 Survey held at **Equator Brotherhood**
 Des. of Damagos: **FR** / Rear / O/S / **NIS** / UIC / Roof/Top or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV: **11k**

rebate: **6233**

W: **4767**

24/3/22 Submit PRS

Date/Time File Pass to?

☐ : Procl. Report

1)

☐ : Final Report

Date/Time File Return to?

24/3/22-typist

Days Of Repair: **4**

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Insp (\$ _____)

☐ : V/A & Eng (\$ _____)

Survey Fee:

Transportation:

_____ S + RS. _____ SI

Fuel/Bus

Others

Total

Report Form 24

Date: 24/3/22

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

795A

Vehicle Details

Vehicle No.:

FBN91P

Vehicle to be Exported:

No

Intended Deregistration Date:

23 Mar 2022

Vehicle Make:

YAMAHA

Vehicle Model:

CZD300A / XMAX300

Primary Colour:

Green

Manufacturing Year:

2020

Engine No.:

H336E0091624

Chassis No.:

MH35H0840LK012359

Maximum Power Output:

-

Open Market Value:

\$4,394.00

Original Registration Date:

25 Sep 2020

First Registration Date:

25 Sep 2020

Transfer Count:

0

Actual ARF Paid:

\$660.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

24 Sep 2030

COE Category:

D - Motorcycle

COE Period(Years):

10

QP Paid:

\$7,331.00

COE Rebate Amount:

\$6,233.00

Total Rebate Amount:

\$6,233.00

The information contained herein is correct as at 23 Mar 2022

OK

dp ~~11/10~~: 170

8yrs 7/103

107x103 = 11021

= 11k

11k - 6233

= 4767

Registration Date	25/03/2020
COE Expiry Date	24/03/2030 (8 years left)
Mileage	33000km
No. of owners	1
Type of Vehicle	Scooters

SGD \$17000

Registered 2020 Yamaha Xmax 300 For Sale.
Bought It Brand New.
Well Maintained.
Accident Free.
Read more

Similar Bikes

View More



23/01/2022
★ Direct Seller
Yamaha Xmax 300
Selling My 2019 Model Yamaha

\$16500

Used Bike



02/02/2022
★ Direct Seller
Yamaha Xmax 300
Selling My Under Utilised Dec...

\$17200

Used Bike

