

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |  |                   |                 |                        |  |
|---|--|-------------------|-----------------|------------------------|--|
|   | AXA INSURANCE  | PTE LTD           | Ref:            | CC4/ASM22002475/Apa3q2 |  |
|   | 8 SHENTON WAY #24-01<br>AXA TOWERSINGAPORE 068811  |                   | Date:           | 20/09/2022             |  |
|   | ATTN:CYNTHIA   |                   | Code:           | ASM                    |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM  |                   |                 |                        |  |
|   | Insured Veh.   | SHD 6562P         | Veh. Inspected  | SKL 6345Y              |  |
|   | Policy No.   | P2465679          | Coverage (\$)   | 0.00                   |  |
|   | Claim No.  | S2M03VQE          | Excess (\$)     | 0.00                   |  |
|   | Assign From  |                   | Assign Date     | 17/03/2022             |  |
| 2.  | 2. Vehicle Particulars & Condition   |                   |                 |                        |  |
|   | Make & Model   | TOYOTA VIOS       | c.c             | 1497                   |  |
|   | Engine No.   | HIDDEN            | Year of Reg.    | 2013                   |  |
|   | Chassis No.  | MR2BT9F3201065506 | Colour          | SILVER                 |  |
|   | Odometer   | 257982 KM         | Steering        | IN ORDER               |  |
|   | Brakes   | IN ORDER          | Modification    | SPORTS RIM             |  |
|   | General  | GOOD              |                 |                        |  |
| 3.  | . Conditions of Tyres  |                   |                 |                        |  |
|   |  | Size              | Make            | Balance                |  |
|   | R/H Front Tyre   | 185/60 R15        | FALKEN          | 6 mm                   |  |
|   | L/H Front Tyre   | 185/60 R15        | FALKEN          | 6 mm                   |  |
|   | R/H Rear Tyre  | 185/60 R15        | FALKEN          | 6 mm                   |  |
|   | L/H Rear Tyre  | 185/60 R15        | FALKEN          | 6 mm                   |  |
| 4.  | Description of Damages   |                   |                 |                        |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.   |                   |                 |                        |  |
|   | DAMAGES SEE DETAILS.   |                   |                 |                        |  |
| 5.  | General Information  |                   |                 |                        |  |
|   | Accident Date  | 13/03/2022        | Inspection Date | 17/03/2022             |  |
|   | Survey held at   | SM AUTOMOTIVE     |                 |                        |  |
|   | BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883   |                   |                 |                        |  |
| 5a.   | Remarks  |                   |                 |                        |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                   |                 |                        |  |
| 5b.   | Estimate Days of Repair  |                   |                 |                        |  |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days   |                   |                 |                        |  |
|   |  |                   |                 |                        |  |