



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388



ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Ms Chia Li Li (Xie Lili) 116 Jalan Kelichap Singapore 534320 Mobile: 91012673			
			Document No. 0					
			Document Date 14/03/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2020	MZAH10R	AWXBB S2	06/04/2020	SKT9026G	0	20824	64TP/SKT9026G/120322	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTHY65BH202056087		M20AN160600	60	Wally Tan G H	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: ACC DATE: TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:						80.00
2	B	BP-LAB3 CHECK WIRING SYSTEM AND FOCUS HEADLAMP. (NETT)						216.50
3	B	BP-LAB3 REMOVE/REFIX FRONT PARKING SENSORS. (NETT)						216.50
4	B	BP-LAB3 TO CONDUCT ADJUSTMENT ON WAVE RADAR SENSOR. (NETT)						216.50
5	B	BP-LAB3 TO CONDUCT ADJUSTMENT ON FRONT CAMERA FOWARD RECOGNITION. (NETT)						216.50
6	B	BP-LAB3 REMOVE/REPLACE FRONT BUMPER COVER AND REALIGN.						1082.50
7	B	BP-RES3 SPRAY PAINT ON FRONT BUMPER COVER.						927.50
8	L	BP-LPO SUPPLY REGN PLATE (PO#) FRONT (NETT)						96.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total	
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
							Amount Due	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388



ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Ms Chia Li Li (Xie Lili) 116 Jalan Kelichap Singapore 534320 Mobile: 91012673		
			Document No. 0				
			Document Date 14/03/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MZAH10R	AWXBB S2	06/04/2020	SKT9026G	0	20824	64TP/SKT9026G/120322
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTHY65BH202056087		M20AN160600	60	Wally Tan G H	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
9	B	BP-LAB3 REMOVE/REFIX REAR WINDSHIELD TO ASSIST REPAIR. (NETT)				866.00	
10	S	BP-SUBLET INSTALLING SOLAR FILM FOR REAR WINDSHIELD. (NETT)				480.00	
11	B	BP-LAB3 TRANSFER BACK DOOR COMPONENT AND MECHANISM TO NEW DOOR SHELL. (NETT)				866.00	
12	B	BP-LAB3 REMOVE/REFIX REVERSE CAMERA. (NETT)				216.50	
13	B	BP-LAB3 CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE. (NETT)				216.50	
14	B	BP-LAB3 REMOVE/REFIX REVERSE SENSORS. (NETT)				216.50	
15	B	BP-LAB3 REMOVE/REFIX REAR LUGGAGE COMPARTMENT INTERIOR TRIM GARNISH TO ASSIST REPAIR. (NETT)				433.00	
16	B	BP-LAB3 REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN REAR PANEL, SPARE WHEEL PAN, R/R AND L/R BODY PANELS, CUT AND WELD PANEL AND FIT NEW PARTS.				4330.00	
17	B	BP-RES3 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				4081.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
<div style="border-bottom: 1px solid black; height: 20px; width: 100%;"></div>			<div style="border-bottom: 1px solid black; height: 20px; width: 100%;"></div>		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388



ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Ms Chia Li Li (Xie Lili) 116 Jalan Kelichap Singapore 534320 Mobile: 91012673		
			Document No.				
			0				
			Document Date				
			14/03/2022				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MZAH10R	AWXBB S2	06/04/2020	SKT9026G	0	20824	64TP/SKT9026G/120322

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHY65BH202056087	M20AN160600	60	Wally Tan G H	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
18	Z	BP-SLANT SUPPLY SEALANT (NETT)				200.00
19	S	BP-SUBLET TO RESET ECU & REPROGRAMME. (NETT)				216.50
20	L	BP-LPO SUPPLY REGN PLATE (PO#)				96.00
		REAR (NETT)				
21	1	L53395-76030 SEAL, HOOD TO FR END	1.00	140.90		140.90
22	2	L53101-76320 GRILLE SUB-ASSY,	1.00	1311.00		1311.00
23	3	L53141-53041 GARNISH, RADIATOR	1.00	1082.90		1082.90
24	4	L53114-76010 GRILLE, RADIATOR,	1.00	225.50		225.50
25	5	L52115-76020 SUPPORT, FR BUMPER	1.00	83.00		83.00
26	6	L52116-76020 SUPPORT, FR BUMPER	1.00	83.00		83.00
27	7	L52521-76010 RETAINER, FR BUMPER,	1.00	133.20		133.20
28	8	L52611-76080 ABSORBER, FR BUMPER	1.00	106.00		106.00
29	9	L52614-76010 ABSORBER, FR BUMPER	1.00	148.20		148.20
30	0	L52112-76904 EXTENSION, FR	1.00	362.40		362.40
31	1	L52113-76902 EXTENSION, FR	1.00	362.40		362.40
32	2	L75895-53010 TAPE, MOULDING, NO.1	2.00	55.50		111.00
33	3	L16562-24020 SEAL, RADIATOR TO	1.00	42.50		42.50
34	4	L16563-24020 SEAL, RADIATOR TO	1.00	42.50		42.50
35	5	L52125-76050 BRACKET, FOG LAMP	1.00	64.20		64.20
36	6	L52126-76050 BRACKET, FOG LAMP	1.00	64.20		64.20

For & on behalf of		Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd							
		Please acknowledge receipt of vehicle		Parts		Less	
				Labour			
				Sublet			
				Lubrication/Fluid			
				Others			
						Amount Due	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 1967000862
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388



ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Ms Chia Li Li (Xie Lili) 116 Jalan Kelichap Singapore 534320 Mobile: 91012673		
			Document No.				
			0				
			Document Date				
			14/03/2022				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MZAH10R	AWXBB S2	06/04/2020	SKT9026G	0	20824	64TP/SKT9026G/120322

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHY65BH202056087	M20AN160600	60	Wally Tan G H	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
37	7	L81481-76070 COVER, FOG LAMP, RH	1.00	145.00		145.00
38	8	L81482-76070 COVER, FOG LAMP, LH	1.00	145.00		145.00
39	9	L52411-76010 GUARD, FR BUMPER	1.00	411.10		411.10
40	0	L52114-76260 BRACKET, FR BUMPER	1.00	170.70		170.70
41	1	L89348-12070 B5 RETAINER, ULTRASONIC	1.00	44.10		44.10
42	2	L89348-12140 B5 RETAINER, ULTRASONIC	1.00	44.10		44.10
43	3	L75392-35220 RETAINER OUTSIDE	4.00	4.20		16.80
44	4	T90467-07215 CLIP	15.00	2.70		40.50
45	5	L58307-76050 PANEL SUB-ASSY, BODY	1.00	921.40		921.40
46	6	L52599-76010 STOPPER, RR BUMPER,	2.00	8.10		16.20
47	7	L68105-76900 GLASS SUB-ASSY, BACK	1.00	1395.30		1395.30
48	8	L75573-76020 MOULDING, BACK	1.00	34.30		34.30
49	9	T62785-60030 SPACER, QUARTER	5.00	6.20		31.00
50	0	L67005-76240 PANEL SUB-ASSY, BACK	1.00	6452.00		6452.00
51	1	T04562-12010 W/SCREEN DAM KIT,	1.00	128.50		128.50
52	2	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	2.00	108.00		216.00
53	3	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00
54	4	L69326-76010 PLATE, BACK DOOR	1.00	151.40		151.40
55	5	L867D0-76010 CAMERA ASSY,	1.00	1358.70		1358.70
56	6	L75441-76030 PLATE, BACK DOOR	1.00	72.30		72.30

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No.2 Pandan Crescent

Singapore 128462, Tel no.: 6631 1388



ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Ms Chia Li Li (Xie Lili)
	Document No. 0	116 Jalan Kelichap
	Document Date 14/03/2022	Singapore 534320 Mobile: 91012673

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MZAH10R	AWXBB S2	06/04/2020	SKT9026G	0	20824	64TP/SKT9026G/120322

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHY65BH202056087	M20AN160600	60	Wally Tan G H	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
57	7	L90975-02228 EMBLEM	1.00	193.40		193.40
58	8	L75442-76030 PLATE, BACK DOOR	1.00	72.30		72.30
59	9	L64716-76030 C0 COVER, DECK TRIM, RR	1.00	266.20		266.20
60	0	L52575-76020 RETAINER, RR BUMPER	1.00	179.30		179.30
61	1	L52576-76020 RETAINER, RR BUMPER	1.00	179.30		179.30
62	2	L52023-76030 REINFORCEMENT	1.00	441.60		441.60
63	3	L52591-76020 SEAL, RR BUMPER	1.00	90.10		90.10
64	4	L52592-76020 SEAL, RR BUMPER	1.00	90.10		90.10
65	5	L52159-76920 COVER, RR BUMPER	1.00	844.40		844.40
66	6	L75895-53010 TAPE, MOULDING, NO.1	2.00	55.50		111.00
67	7	L52169-76081 COVER, RR BUMPER,	1.00	456.70		456.70
68	8	L52162-76040 PLATE, RR BUMPER,	1.00	18.40		18.40
69	9	T90950-06124 TAPE, SEAL	2.00	5.20		10.40
70	0	L75392-35220 RETAINER OUTSIDE	9.00	4.20		37.80
71	1	S52161-0K040 BUMPER CLIPS	13.00	4.30		55.90
72	2	L89348-12070 B5 RETAINER, ULTRASONIC	2.00	44.10		88.20
73	3	L89348-12140 B5 RETAINER, ULTRASONIC	2.00	44.10		88.20
74	4	L89341-33220 B4 SENSOR, ULTRASONIC,	4.00	490.80		1963.20
75	5	L81671-76010 LENS & BODY, BACK-UP	1.00	202.60		202.60
76	6	L81681-76010 LENS & BODY, BACK-UP	1.00	202.60		202.60

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388




ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Ms Chia Li Li (Xie Lili) 116 Jalan Kelichap Singapore 534320 Mobile: 91012673		
			Document No.				
			0				
			Document Date				
			14/03/2022				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MZAH10R	AWXBB S2	06/04/2020	SKT9026G	0	20824	64TP/SKT9026G/120322

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHY65BH202056087	M20AN160600	60	Wally Tan G H	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
77	7	L81676-76010 RIM, BACK-UP, RH	1.00	16.00		16.00
78	8	L81686-76010 RIM, BACK-UP LAMP,	1.00	16.00		16.00
79	9	L8158A-12260 LED, RR LAMP, RH	2.00	186.50		373.00
80	0	L81910-76010 REFLECTOR ASSY,	1.00	51.60		51.60
81	1	L81920-76010 REFLECTOR ASSY,	1.00	51.60		51.60
82	2	L66259-76010 COVER, RR BODY	1.00	320.20		320.20
83	3	L58398-76010 COVER, FLOOR UNDER,	1.00	170.70		170.70
84	4	L58399-76010 COVER, FLOOR UNDER,	1.00	170.70		170.70
85	5	L75605-76010 MOULDING SUB-ASSY,	1.00	387.50		387.50
86	6	L75606-76010 MOULDING SUB-ASSY,	1.00	387.50		387.50
87	7	T90467-07220 CLIP	2.00	2.70		5.40

For & on behalf of		Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle 	Parts 23,899.20	39,169.20
			Labour 14,381.50	GST 7.00% 2,741.84
			Sublet 888.50	Less 0.00
			Lubrication/Fluid 0.00	
			Others 0.00	Amount Due 41,911.04

Customer Copy

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	14/03/2022 10:13 (SGT)
Date of Accident	12/03/2022 16:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	PAYA LEBAR ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT9026G
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CHIA LI LI (XIE LILI)
NRIC No	SXXXX097B
Email Address	audrey_cll@hotmail.com
Mobile Phone No	(Phone) +65-91012673
Alternative Phone No	+65-91012673

VEHICLE PARTICULARS

Manufacturer	Lexus
Model	UX250H 5DR SUV (AT)(2WD) EXECUTIVE
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1987

INSURANCE COMPANY

Name of Insurance Company	Sompo Insurance Singapore Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	D21MTPV01004581
Cover Note Number	06/04/2021 TO 05/04/2022

DRIVER

Name of Driver	CHIA LI LI (XIE LILI)
NRIC No	SXXXX097B

Date Of Birth	26/09/1973
Occupation	Indoor
Date Of Driving Pass	20/02/1995
Driving experience	27 YEARS AND 1 MONTH
Gender	Female
Mobile Number	(Phone) +65-91011673
Alt. Phone Number	+65-91011673
Email Address	audrey_cli@hotmail.com
Address	116 JALAN KELICHAP SINGAPORE 534320
Address complement	-
Postcode	-
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER WITH ATTACHED.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM5251Z
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private hire
Name of Driver	TEO ZHENG WEN
Contact Number	(Phone) +65-88018914
Address	-
Address complement	-

Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJM3438P
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	RAPAHIL LUKE NESARAJ S/O RAVINDRAN RUFUS
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	CHIA LI LI (XIE LILI)
Gender	Female
Phone No	(Phone) +65-91011673
Address	116 JALAN KELICHAP SINGAPORE 534320
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	CENTRAL 24 HOUR CLINIC - BEDOK - 2DAYS MC
Injured person in which vehicle?	-
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



[Signature]

Policyholder's Signature / Date & Time

[Signature]

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



— — —
— — —
[BD] / [AD] / [CD]
— — —
paya lebar road

A: SKT 90264

B: SLM 52512

C: SJM 3438P

Describe Circumstances of the Accident


It was heavy raining day on 12/3/2022.
I drove my car SKT90265 along paya lebar
road. Car in front stop and
I follow to stop. Next moment
my car was hit by car SLN52512. The
great impact push my car forward to
hit into the rear of car SJM34381.
After the incident, I felt not feeling
well and will consult a doctor later.


Note: Please note that your insurer may have 14 days time frame for you to submit an own damage claim under your own policy, please check your policy for more information.

Declaration

We declare the foregoing particulars are true in every respect.




Policyholder's Signature / Date &
Time 14/3/2022
10.00 am


Driver's Signature (If driver is not the policyholder) / Date
& Time 14/3/2022
10.00 am

Witnessed by Reporting Centre
Personnel