

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |   |                           |                 |                     |  |
|---|---|---------------------------|-----------------|---------------------|--|
|   | CHINA TAIPING IN  | ISURANCE (S) PTE LTD      | Ref:            | CS/CTI22002503/Rqy3 |  |
|   | 3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909   |                           | Date            | 17/03/2022          |  |
|   |   |                           | Code            | : CTI               |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM   |                           |                 |                     |  |
|   | Insured Veh.  | GBJ 1525U                 | Veh. Inspected  | PC 7695T            |  |
|   | Policy No.  | DMCVSNA00049832100        | Coverage (\$)   | 0.00                |  |
|   | Claim No.   | SNM22D201841/C02/JENNY    | Excess (\$)     | 0.00                |  |
|   | Assign From   | JENNY LEW                 | Assign Date     | 17/03/2022          |  |
| 2. Vehicle Particulars & Condition                                |   |                           |                 |                     |  |
|   | Make & Model  |                           | c.c             | 0                   |  |
|   | Engine No.  | HIDDEN                    | Year of Reg.    |                     |  |
|   | Chassis No.   |                           | Colour          |                     |  |
|   | Odometer -  |                           | Steering        |                     |  |
|   | Brakes  |                           | Modification    |                     |  |
|   | General   |                           |                 |                     |  |
| 3. Conditions of Tyres  |   |                           |                 |                     |  |
|   |   | Size                      | Make            | Balance             |  |
|   | R/H Front Tyre  |                           |                 | mm                  |  |
|   | L/H Front Tyre  |                           |                 | mm                  |  |
|   | R/H Rear Tyre   |                           |                 | mm                  |  |
|   | L/H Rear Tyre   |                           |                 | mm                  |  |
| 4.  | Description of Damages  |                           |                 |                     |  |
|   |   |                           |                 |                     |  |
| 5.  | General Information   |                           |                 |                     |  |
|   | Accident Date   | 16/03/2022                | Inspection Date | 21/03/2022          |  |
|   | Survey held at  | 566 WOODLAND ROAD S728697 |                 |                     |  |
|   | Repairer  | CONNECT3                  |                 |                     |  |
| 5a. Remarks   |   |                           |                 |                     |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                           |                 |                     |  |