

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE I	PTE LTD		Ref:	CS3/ASM22002507/Rqy3e2
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11		Date:	30/03/2022
	ATTN: TEO KITTY			Code:	ASM
1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHA 4184B	Veh. Inspected	k	SMH 2645E
	Policy No.	VFX/P2419138	Coverage (\$)		0.00
	Claim No.	S2M03V6S	Excess (\$)		0.00
	Assign From	TEO KITTY	Assign Date		17/03/2022
2. Vehicle Particulars & Condition					
	Make & Model	CITROEN C3 AIRCROSS FEEL 1.2 PURETECH	c.c		1199
	Engine No.	HIDDEN	Year of Reg.		2019
	Chassis No.	VF72RHNZWJ4331483	Colour		WHITE
	Odometer	36866 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	205/60 R16	HANKOOK		6 mm
	L/H Front Tyre	205/60 R16	HANKOOK		6 mm
	R/H Rear Tyre	205/60 R16	HANKOOK		6 mm
	L/H Rear Tyre	205/60 R16	HANKOOK		6 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
5.	General Information				
	Accident Date	06/03/2022	Inspect Date /	Time	18/03/2022 ( 04:08 PM )
	Survey held at REVOL CARZ GARAGE PTE LTD				
	BLOCK 10, ANG MO KIO IND PARK 2A #02-18, AMK AUTOPOINT SINGAPORE 568047				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. ITHE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				

Report Ref No. CS3/ASM22002507/Rqy3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser