

PRS

ASSIGNMENT

CS3/SMR22002508/Gty3

From:

Date:

Veh No: JSN 7092

Yr Regn: 17 JAN 2018

Estimated Cost:

Type: M.Car / ☒ Cycle / Bus / Van / Lorry / Taxi / Prime Mover /OD ☒ TP ☒ / RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

Make: YAMAHA Y15ZR

c.c 150

at Workshop m/s SIN SENG HONG

Colour: Blue

A/C: Insured / Std / NI / NA

of

Sp. Reading

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No: PMYUG0510J0129230 *

Claims No.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured: Excess:

Steering: ☒ Inorder / Jammed / Leaked / Burnt or


(Client's Record)

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: ☒ Nil / S/Rim / STD A/Rim or

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: 80/90R17 MAXXIS

R: 110/70-17 METZELER

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value: RM 8200

Front

Rear

IDAC Accident Rpt: Consistent? : Yes or No

R/Bal. 4 mm

R/Bal. 4 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. mm

L/Bal. mm

Est. Repairs: 3 days Res.: Yes or No

D.O.A.

D.O.I. 18-03-2022

Lum Sum: 20 % 3 Val.: Yes or No

Survey held at W/S 2:30pm

CA / REV / REP. / 24 HRS

Des. of Damages: ☒ Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$1500 - \$2500

SUBMIT PRS REPORT

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 3

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ : Site Insp (\$

Transportation:

Report Filed:

☐ : Interview (\$

Photos

Long Cond / MPB:

☐ : Tech. Insp (\$

Other:

☐ : W/Weekend (\$

TOTAL