

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/TP22002528/uty3

057D

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMF 4774Mat Workshop m/s 3m1

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$80K.

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: LTA 33656Date / Time Action / Instruction 20/1/1270/210 RT20/3/22 1/5 @ 3100 : informed kenny

RED: 2433.75;43%

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I.: (\$ _____)

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Survey Fee: 140Transportation: 90S + RS: 90 + 90Photos: 60

Others: _____

TOTAL

350Veh No: SMF 4774MYr Regn: 13/11/18Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: VolkswagenColour: whiteSp. Reading: 29245

Eng/No: _____

C/No: WVWZZZ442JW14055Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 15/3/22

Survey held at _____

Des. of Damages: Rear / Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.