

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III22002533/GTY3E2

Date: 01/04/2022

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MPC0001545\_01

Claimant Vehicle No : SFB9892B Insured Vehicle No : SMV121P

Date of Loss: 17/03/2022 Nature of Claim: TP Claim No: MPC2022D0001445

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFB9892B**  
Make & Model: MERCEDES-BENZ E200, 2.0 AVG (A) Engine No: 27492031251474  
Reg. Date: 15/01/2018 (Man. Year: 2017) Chassis No: WDD2130422A344760  
Colour: Grey Odometer: 92811 km  
Engine Capacity: 1991 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/45 R18 Rear Tyre Size: 245/45 R18  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

### INSPECTION

Date of Assignment: 18/03/2022

Date Inspected: 22/03/2022 Inspected At:

A T Performance (SIN MING)  
160 SIN MING DRIVE, #07-18/19 SIN MING  
AUTOCITY  
Singapore 575722

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

# REPAIR DETAILS

|               |                                                                                                                                                                              |                                                                  |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------|
| Reference     |                                                                                                                                                                              |                                                                  |
| Part Source:  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 01 Apr 2022)                    |
| Parts:        | 143                                                                                                                                                                          | MERCEDES-BENZ E200 2.0 AVG (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                |
| Print Code:   | (Unsubmitted, no print-code for SFB9892B)                                                                                                                                    |                                                                  |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                  |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                  |

## Recommended Parts

There are no new parts selected.

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

< END OF ESTIMATES >