



Exceptional Journeys

Surveyor : RASUL LKK
Claim : TP AIG
DOA : 12.03.2022
Emailed : 20.05.2022, 8.55am
Date survey : 18.04.2022

VEHICLE NO : SKF 7454 R
MODEL : KIA KOUP 1.6 A SX SR
WIP : 48331

Material	:	\$	351.20
Labour	:	\$	1,890.00
Sub-Total	:	\$	2,241.20
→ REPAIR LIMIT	:	\$	2,000.00
Less Excess	:	\$	-
Total	:	\$	2,000.00
GST 7%	:	\$	140.00
Grand Total	:	\$	2,140.00
Finalise By/Date	:	LOI /	19/05/2022

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☒ REPAIR TOOK 4 WORKING DAYS + 2 Days (1) Weekends
+ 0 Days (0) Public holiday
TOTAL DAYS REPAIR TOOK = 6

☒ TP claim SLR 9247 J

☐ Claim GIA / LTA fee

☒ Claim Loss of ☐ Use / ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 19/04/2022	Cust No/Name /Jamal Bin Idi Ahmad Reg No/Reg Date SKF7454R / 29/06/2012 Date In/Mileage 19/04/2022/ 50235 Chassis/Package KNAFW611MC5634586 Engine No G4FCCH247412 Make/Model KIA/KOUP 1.6 A SX SR HB 64 Colour/Trim HO / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	20/05/2022/ 08:56	TLE	260 / AiTing	48331

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT98000 RESpray ON REAR BUMPER, REAR END PANEL & BODY KIT, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 700.00
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER CENTRE, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 800.00
E PNT88000 REMOVE AND INSTALL REVERSE SENSOR TO FACILITATE REPAIR				✓ 80.00
M SUNDRY SUNDRIES				✓ 30.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE				✓ 120.00
S SPECIALISTJOB SUPPLY & REPLACE REAR NUMBER PLATE WITH FRAME				✓ 50.00
S SPECIALISTJOB APPLICATION TO BREAK OPC PLATE AT LTA AND RESEAL AT VICOM				✓ 80.00
X COVER-RR BUMPER,CTR	1.00	✓ 439.00	20.00	351.20
Z TEXT TP CLAIM AIG SLR9247J DOA : 12.03.22 SURVEYOR RASUL 18.04.22 REPAIR 04 DAYS				
<i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	351.20	Nett	2,241.20
Labour	1,730.00	7% GST on	156.88
Standard Menu	0.00		
Specialist Job	130.00		
Diagnostics Job	0.00	Total Payable	2,398.08
Sundry/Others	30.00		
Total(w/o GST)	2,241.20		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CERATO/FORTE../2012/G 1.6 DOH..

VCI




Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



6/6

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ESP	No Current DTC	Good
AIRBAG	No Current DTC	Good
SMK	No Current DTC	Good
PDM	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.

M-E-K-01-00-0270

VCI Ver.

02.64

ECU Ver.

M-E-K-01-00-0211

OS Ver.

Android 10