

ASS. REC. BY:

REF:

C72/22002539/K7

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

1.B.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMA 5282K Yr Regn: 06, 18

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Accent c.c. 1368

Colour:

Black/Gold

A/C: Insured / Std / NI / NA

Sp. Reading

53704

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMHCU41BTJU 431563

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M / S/Rlm / STD A/Rlm or

Tyre Size:

F:

175/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

15/3/22

D.O.I.

4/4/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear d/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

Fines

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: TP-GW 4766T
Repairer Reference: 72528
Date calculated: 18/03/2022 10:56 AM

Full Report
Registration: SMA 5282K
Printed: 18/03/2022 10:56 AM

Summary Information

Claim Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	TP-GW 4766T	Date of Incident:	15/03/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle Manufacturer:	HYUNDAI		
Model:	ACCENT (RB)		
Sub Model:	BASE MODEL		
Model Sheet Number:	30 29 01		
Registration:	SMA 5282K		
VIN number:			
Odometer:	53148		
Model Specs FROM 07.2013	AIR CONDITIONING	FOG LAMPS	REAR PARKING SYSTEM
CVT AUTO GEARBOX	TYRES 175/70 HR 14	4-DOOR	TWO COAT METALLIC
PREPARE OFF VEHICLE			

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
86651R00	RENEW REAR BUMPER INCLUDES: BOTH OUTER REARLAMPS AND REQUIRED TRIMS ASSEMBLE ATTACHED PARTS RENEW IF NECESS NOT INCLUDED: BUMPER REINFORCEMENT REMOVE AND REFIT		7.0	29.40
95704R00)	R + R REAR PARKING SYSTEM SENSOR/S		5.0	21.00
Labour Cost				
Panel / Mechanical Labour		Hrs	WU	
		1.20	12.0	50.40
Total of Labour				50.40

*Not with the
Murray B&M
2 days*

Paint

PAINT WORK

SYSTEM AZT

Time Basis 10 W

Code

Description - TWO COAT METALLIC

WU Price

REAR BUMPER COVER NEW PART PAINT K1R
L/R INN PARKING SENS SURFACE PAINT PLAST.
R/R INN PARKING SENS SURFACE PAINT PLAST.
L/R OUT PARKING SENS SURFACE PAINT PLAST.
R/R OUT PARKING SENS SURFACE PAINT PLAST.

13.0
3.0
3.0
3.0
3.0

Paint Material Per Part

Code

Description

Price SGD

2583
2681
2682
2683
2684

REAR BUMPER COVER NEW PART PAINT K1R
L/R INN PARKING SENS SURFACE PAINT PLAST.
R/R INN PARKING SENS SURFACE PAINT PLAST.
L/R OUT PARKING SENS SURFACE PAINT PLAST.
R/R OUT PARKING SENS SURFACE PAINT PLAST.

63.96
0.37
0.37
0.37
0.37

Labour Cost - Paint

Factor

Time Paint

Preparation Comp. Work Plastic

Total

42.00 SGD/h

Hrs

WU

Price SGD

25.0

1.50

15.0

63.00

10 WU/h

4.00

40.0

168.00

Material Cost - Paint

New Part Painting - Plastic K1R

Surface Painting Plastic

Material-constant Plastic

Total

Price SGD

63.96

1.48

28.60

94.04

Spare Parts

Code

Description

Part Number

Part Source

prices as at 2015-06-01

Price SGD

2626
3296
2583

R/R OUT BUMPER BRKT 866141R000
R/R REFLECTOR 924061R000
REAR BUMPER COVER 866501R000

Original
Original
Original

30.00
40.00
280.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings

Subtotal

Fixed Sundry Parts Price

Total

0.00

350.00

100.00

450.00

Calculation

Kenne

	SGD	SGD
Parts		
Fixed Sundry Parts Price	350.00	
Total Parts	100.00	450.00
Labour Time Base 10 WU/h		
Total 12.0 WU X 42.00 SGD/h		
Total of Labour	50.40	50.40
Paint Work Time Base 10 WU/h		
Labour Cost 40.0 WU X 42.00 SGD/h	168.00	
Material Cost	94.04	
Total Paint Including Material		262.04
Repair Cost Excludes GST		762.44
GST (+7.0%)		53.37
Repair Cost Included GST		815.81

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTES

1. Please read carefully the details of the accident statement and the terms of use.
2. The accident report is submitted to the Police for investigation and the Department of Transport.
3. The accident report may be used as evidence in court proceedings and may allow insurance companies to repudiate claims.
4. The accident report is a form for insurance companies to use in determining claims. It is not a statement of facts. It is a statement of what you saw or heard at the time of the accident.
5. The accident report may be referred to the Police for investigation.
6. The accident report will be referred to the Police for investigation.
7. The accident report will be referred to the Police for investigation.

ACCIDENT STATEMENT

Date of Submission: 18/08/2020 12:10 (2021)
 Date of Accident: 18/08/2020 15:30 (2021)
 Exact Location of Accident: Near 57, Kuning East Ave 1, Singapore 800778
 Additional Location Information: NG ANNY PH K 30 KUNING EAST ST 32
 Country/State of Loss: Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number: SMA5282K
 INSURANCE COMPANY:
 Is company? No
 Name Of Registered Owner: GAO XIAOJU
 NRIC No: S2609208F
 Email Address: GAOXIAOJU@GMAIL.COM
 Mobile Phone No: (Phone) +65-81257169
 Alternative Phone No: +65-81257169

VEHICLE PARTICULARS

Manufacturer: Hyundai
 Model: Accent
 Variant: -
 Exact purpose for which vehicle was being used at time of accident: Private use
 Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
 Vehicle Category: Commercial vehicle
 Transmission: Auto
 CC: 1600

INSURANCE COMPANY


Name of Insurance Company: MS First Capital Insurance Ltd
 Type of Coverage: Comprehensive
 Fleet Policy: No
 Policy Number: D-21097669MVP
 Cover Note Number: -

DRIVER

Name of Driver: GAO XIAOJU
 NRIC No: S2609208F

SKETCH PLAN

Date & Time of Accident: 15/03/22 / 2022 Location: Jurong East St 32 near by BLK 301
 Veh A: Sun A5282K Veh B: GWS 4766T Veh C/Others: _____



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 15 MAR 2022 at about 17.30hrs I was travelling along Jurong East St 32 towards Jurong Town Hall near the traffic junction the traffic light was Red all the cars in front have stopped. I also stopped my vehicle and suddenly I felt a jerk vehicle no GWS 4766T Driven by Mr Gueant collided onto my car rear my bumper was damaged.

NOTE PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION.

Own Damage Claim at Lim Tan Motor ☐ TP Claim at Lim Tan Motor ☐
 Own Damage Claim at Other Workshop ☒ TP Claim at Other Workshop ☐ Reporting Only ☐

I/We hereby authorised Lim Tan Motor Pte Ltd to forward my/our filed GIA accident report to:-

My/Our workshop via email: _____

My/Our email: Caoxjs8@gmail.com

DECLARATION

I/we declare the foregoing particulars are true in every respect.

Policyholder's Signature Date

3 Print

16 MAR 2022

Driver's Signature

(if driver is not the policyholder) Date

& Time

Reporting Centre Personnel's Signature

Name: VIEWS

NR C/PIN No. 22222222