




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT                                                       |                                                                                                                                                                                                                                                                                                                                             |                     |                                                                                       |  |
|------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|--|
| LONPAC INSURANCE BHD<br>300 BEACH ROAD #17-04/07 THE CONCOURSE<br>SINGAPORE 199555 |                                                                                                                                                                                                                                                                                                                                             |                     | Ref: CS3/LPC22002543/Gvy3e2<br>Date: 30/03/2022<br>Code: LPC2                         |  |
| 1. Policy Particulars :- (THIRD PARTY CLAIM)                                       |                                                                                                                                                                                                                                                                                                                                             |                     |                                                                                       |  |
| Insured Veh.                                                                       | GW 1883H                                                                                                                                                                                                                                                                                                                                    | Veh. Inspected      | FBL 1938B                                                                             |  |
| Policy No.                                                                         |                                                                                                                                                                                                                                                                                                                                             | Coverage (\$)       | 0.00                                                                                  |  |
| Claim No.                                                                          | 21/22/22/VC05/025567                                                                                                                                                                                                                                                                                                                        | Excess (\$)         | 0.00                                                                                  |  |
| Assign From                                                                        | GERALD POH WEE BIN                                                                                                                                                                                                                                                                                                                          | Assign Date         | 18/03/2022                                                                            |  |
| 2. Vehicle Particulars & Condition                                                 |                                                                                                                                                                                                                                                                                                                                             |                     |                                                                                       |  |
| Make & Model                                                                       | KAWASAKI Z800                                                                                                                                                                                                                                                                                                                               | c.c                 | 806                                                                                   |  |
| Engine No.                                                                         | HIDDEN                                                                                                                                                                                                                                                                                                                                      | Year of Reg.        | 2016                                                                                  |  |
| Chassis No.                                                                        | JKBZR800ABDA15527                                                                                                                                                                                                                                                                                                                           | Colour              | GREEN                                                                                 |  |
| Odometer                                                                           | -                                                                                                                                                                                                                                                                                                                                           | Steering            | IN ORDER                                                                              |  |
| Brakes                                                                             | IN ORDER                                                                                                                                                                                                                                                                                                                                    | Modification        | NIL                                                                                   |  |
| General                                                                            | GOOD                                                                                                                                                                                                                                                                                                                                        |                     |                                                                                       |  |
| 3. Conditions of Tyres                                                             |                                                                                                                                                                                                                                                                                                                                             |                     |                                                                                       |  |
|                                                                                    | Size                                                                                                                                                                                                                                                                                                                                        | Make                | Balance                                                                               |  |
| R/H Front Tyre                                                                     | 120/70Z R17                                                                                                                                                                                                                                                                                                                                 | MICHELIN            | 5 mm                                                                                  |  |
| L/H Front Tyre                                                                     |                                                                                                                                                                                                                                                                                                                                             |                     | mm                                                                                    |  |
| R/H Rear Tyre                                                                      | 180/55Z R17                                                                                                                                                                                                                                                                                                                                 | MICHELIN            | 5 mm                                                                                  |  |
| L/H Rear Tyre                                                                      |                                                                                                                                                                                                                                                                                                                                             |                     | mm                                                                                    |  |
| 4. Description of Damages                                                          |                                                                                                                                                                                                                                                                                                                                             |                     |                                                                                       |  |
|                                                                                    | THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION.                                                                                                                                                                                                                                                                            |                     |  |  |
| 5. General Information                                                             |                                                                                                                                                                                                                                                                                                                                             |                     |                                                                                       |  |
| Accident Date                                                                      | 16/03/2022                                                                                                                                                                                                                                                                                                                                  | Inspect Date / Time | 21/03/2022 ( 03:00 PM )                                                               |  |
| Survey held at                                                                     | ONG MOTOR TRADING<br>NO. 464 MACPHERSON ROAD SINGAPORE 368182                                                                                                                                                                                                                                                                               |                     |                                                                                       |  |
| 5a. Remarks                                                                        |                                                                                                                                                                                                                                                                                                                                             |                     |                                                                                       |  |
|                                                                                    | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.<br>THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.<br>D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000 |                     |                                                                                       |  |
| 5b. Estimate Days of Repair                                                        |                                                                                                                                                                                                                                                                                                                                             |                     |                                                                                       |  |
|                                                                                    | ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                                                                                                                                                                         |                     | 4 Working Days                                                                        |  |

Report Ref No. CS3/LPC22002543/Gvy3e2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or  
relying on this Report, in whole or in part, does so at his or her own risk.