SECURITY CLASSIFICATION \ SENSITIVITY CLASSIFICATION



Front View of MID 46210



Rear View of MID 46210



Left Side View of MID 46210



Right Side View of MID 46210

Figure 1A: Accident Photographs

SECURITY CLASSIFICATION \ SENSITIVITY CLASSIFICATION



Zoomed In View of MID 46210

Damage Assessment: Right vehicle side is slightly dented, multiple scratches are on the door, scratches are near the driver side.

Figure 1B: Damage photos




Figure 2A: Schematic Diagram Pt. 1




Figure 2B: Schematic Diagram Pt. 2

${\tt SECURITY\ CLASSIFICATION\ \backslash\ SENSITIVITY\ CLASSIFICATION}$

1		ATEMENT	F DRIVER/WITH	NE22	,
STATEMENT OF				ALIASES.	
NRIC NO	6806	AGE	20	MALE/FEMALE	MALE
EMPLOYMENT		DRIVING LICENCE NO	4, 1	NATIONALITY	Singaprean
DIALECT		LANGUAGE SPOKEN	Eng, chacse	TEL NO	# 10 to 10 t
-ADDRESS					
INTERPRETED BY		RANK	TIME	DATE	SIGN
RECORDED BY	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	RANK	ТІМЕ	. DATE	SIGN
		=			
1.0	o Khoo Teck Puret F	lespital on 3010		left the hospital a	+ 22+15 Hrs heading
	on Camp, At-approx 5 towards change			2 300	the car beside me Who
he squeeze-through	sh i heard an ban	g and saw a r	motorcicle drave past	t-me and stopped	infinit. After which
				-	, I signed back in the
-log book and key	at the korpress of	Medical Centr	e and proceed to	freshen up myself a	nd remembered the
incident happens	d earlier on the 1 plate he vehicle, of the	motorcicle is	FBD39040 and A	node and reported mbulance MID 46211	1-to 3SG-Rui Tins
Her	# # X #4	a transfer on the	***		

Figure 3A: Driver's Statement

${\tt SECURITY\ CLASSIFICATION\ \backslash\ SENSITIVITY\ CLASSIFICATION}$

No: 1800-8	Of Origin N.P.C stral SINO 3529999	SAPORE 76882	7				Report No	1 5. T/2019103
PORT OF A T	port Mad		Vide R	eport No.:		_	Stat	ion Diary N
/10/2019 1	0:12			_	and the later of the	THE PARTY NAMED IN	100	
ame of Info		THE WAY	Addres	CVC TOPESON	- ut	NAME OF TAXABLE PARTY.		
		ING KANG	Address	K I				
D Type / ID No.: NRIC NO / 680G		Contac	d No.:		Mobile:			
		Home	Home/Office:					
lationality: SINGAPOR	E CITIZE		70000					
Sex: Male	Age: 20	Date of Birth: 25/03/1999	Type of Driver	of Informant:			101	ani Mame:
Race	20	23/03/1898	Langu	iage:		Institutio	n / Sch	ool Name:
Chinese Occupation			Englis	g Licence Inf	ormation:		Coming	
FULL TIME	NSF		Class	3,4		Date of	Expany.	
Type of Accident.	l N	Non-Injury Sovernment Vehi	de	Drink Drive: No	Date/Tin Accident 30/10/20			ype of Loca -Junction
/ soon or it.	(Doad 1	and Road 2					Dood S	Speed Limit
Location:	ENTRAL	5					MOSO S	speed Limit
Location: Junction of YISHUN O YISHUN A	ENTRAL	5	Road	d Surface:				
Location: Junction of YISHUN O YISHUN A Weather: Clear Traffic Flo	ENTRAL VENUE	5	Dry Traff	fic Control:	rkina		Traffic Moder	Volume:
Location: Junction of YISHUN OF YISHUN A Weather: Clear Traffic Flo Two Way	W allieion	5 ehides - Side Sv	Dry Traff Traff	fic Control: fic Light - Wo			Moder	ate e conveyed
Location: Junction of YISHUN OF YISHUN A Weather: Clear Traffic Flo Two Way	W allieion	ehides - Side Sv	Dry Traff Traff wipe - Sar	fic Control: fic Light - Wo	un serve	\$1 \$1	Anyon ambul No	ate e conveyed
Location: Junction of YISHUN OF YISHUN A Weather: Clear Traffic Flo Two Way	w ollision: Moving V	5	Dry Traff Traff wipe - Sar	fic Control: fic Light - Wo		\$1 	Anyon ambul No	ate e conveyed ance:

Figure 4A: Police Report Pt. 1

SECURITY CLASSIFICATION \ SENSITIVITY CLASSIFICATION



Police Station Of Origin: Yishun North N.P.C 31 Yishun Central SINGAPORE 768827 Tel No: 1800-8529999



2 of 3 Report No. T/20191031/2027

CONTINUATION OF REPORT

Name	JONATHAN PANG	QING KAN	lG	ID No).	680G
Related Vehicle	MID46210 (Ambula	nce)		Conta	ct No.	
Hospital/Clinic	NIL			Class Drivin Licene Expin	g	Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL		Date Disc	charge	NIL	
No. of Days gran	ted Medical Leave	NIL	Degree o		NIL	

Brief Details

On 30/10/2019 at about 2235hrs, I was driving an SAF ambulance bearing plate number MID46210. I was travelling along Yishun Central towards the direction of Yishun Avenue 5. At the cross junction of Yishun Central and Yishun Avenue 2, my ambulance was stationary on the left of two lanes, as the traffic light was red. There was an unknown car on the right lane, beside my ambulance. There was a black motorcycle which lane split in between my ambulance and the car. Suddenly, I heard a loud bang on the right of the ambulance and I believed the handlebar had grazed onto the ambulance.

The motorcycle rider continued straight, but I managed to catch up at the junction near Chong Pang CC. I took down the motorcycle plate number as FBD3904D. I then drove the ambulance back to Nee Soon Camp and reported the matter to my superior. The ambulance suffered some scratches and slight dent on the right bottom portion of the ambulance cabin. No one was injured during the incident. There are cameras installed on the ambulance. It captured the motorcycle rider wobbled upon side swiping with the ambulance. However, the plate number was unclear.

Figure 4B: Police Report Pt. 2

${\tt SECURITY\ CLASSIFICATION\ \backslash\ SENSITIVITY\ CLASSIFICATION}$

POLICE FORCE	3 of 3
Police Station Of Origin:	Report No. T/20191031/202
Yishun North N.P.C	CONTINUATION OF REPORT
Sketch Plan	
Informant is not able to provide sketch plan	
NAPORTANT: Please attach a copy of your	vehicle's Insurance Certificate to this report. If you don't ha
the certificate with you now, pro-	vehicle's Insurance Certificate to this report. If you don't happy to 65474885 stating the report number as reference.
Signature Of Officer Recording The Repor	Signature Of Informant:
the certificate with you now, pro-	Signature Of Informant:
Signature Of Officer Recording The Repor	Signature Of Informant:
Signature Of Officer Recording The Report L / Sr Staff Sgt MUHAMMAD IMRAN BIN ME	Signature Of Informant: SLAN Date/Time:
Signature Of Officer Recording The Report L / Sr Staff Sgt MUHAMMAD IMRAN BIN ME	Signature Of Informant: SLAN Date/Time: 31/10/2019 10:12

Figure 4C: Police Report Pt. 3

