

AXA Insurance Pte Ltd

Assessments

General Details

Involving
Date of Loss
Time of Loss
Loss Description
Comment

2017 HONDA JAZZ 1.3 (SLW676L)
25/11/2021
06:05 PM
QX1253C (TP) > SLW676L (OI)
7 working days

Vehicle Details

Vehicle Registration#
Registration Province
Mileage
Manufacturing Year
Purchase date
Registration date
Age of vehicle

SLW676L
65173.00
2017
26/01/2018
3

	Policy Information	Assessment Information
Make	HONDA	HONDA
Model	JAZZ 1.3	JAZZ 1.3
Type		
Type of paint		
Chassis No	JHMGK3850JX204683	
Engine No	L13B11030052	
Engine Capacity		
Sum Insured	0.00	0
Market Value	0.00	0

Workshop Details

Total Rebate Amount	0.00
Net Loss Amount	0.00
Assigned Workshop	
Days of work completion	7

Assessment Summary

Category	Revised Amount
Excess	-400.00
Labour	7,940.00
Spare Parts	1,593.43

Settlement %	100.0
Amount Non-standard Deduction	0.00
Final Claim Amount	9,133.43

Detailed Assessment

Inspection Date	20211209
Assessment Details	
Total Loss	false
Towing Charges	0.00
Voluntary Excess	0.00
Compulsary Excess	400.00
Young/ Inexperienced/ Unnamed Driver Excess	0.00
Other Excess	0.00

Condition of vehicle at time of survey

General condition	Good
Steering (Serviceable)	true

Footbrake (Serviceable)
Handbrake (Serviceable)
Engine Modification
Pre-accident condition

true
true
false

Tyre condition

Age of tyres
Front Tyre Size
Rear Tyre Size
Front left side
Rear left side
Front right side
Rear right side
Spare wheel

175/65/15
175/65/15
5
5
5
5

Parts

No.	Quantity	Part Name	Condition	Dep/Batt%	Discount %	Salvage %	Adjusted Amount	Supplementary Parts	Action	Comment
1	1.00	TOTAL PARTS AMOUNT		0	0	0	1593.43	No	Approve	

Labour

No.	Description	Adjusted Labour Amount	Adjusted Paint Amount	Action	Comment
1	TOTAL LABOUR AMOUNT	7940	0	Approve	
1	7 working days				

Miscellaneous

No.	Name	Adjusted Amount	Action	Comment
-----	------	-----------------	--------	---------

Paint Labour/Material Ratio

Paint Labour Ratio20.0
Paint Material Ratio80.0
Cash Lossfalse