

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC22002583/Rvy3e2	
	300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Date:	30/03/2022	
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GW 1883H	Veh. Inspected	l	SLZ 4929R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	21/22/22/VC05/025567	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		21/03/2022	
2. Vehicle Particulars & Condition						
	Make & Model	KIA FORTE K3 1.6A SUNROOF	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	KNAFZ411MJ5761577	Colour		BROWN	
	Odometer	61112 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/45 R17	BRIDGESTONE		6 mm	
	L/H Front Tyre	215/45 R17	BRIDGESTONE		6 mm	
	R/H Rear Tyre	215/45 R17	BRIDGESTONE		6 mm	
	L/H Rear Tyre	215/45 R17	BRIDGESTONE		6 mm	
4.	I. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
5.	General Information					
	Accident Date	16/03/2022	Inspect Date /	Time	22/03/2022 (02:03 PM)	
	Survey held at	60 JALAN LAM HUAT #02-28 CARROS CENTRE				
	Repairer	LONG VIEW MOTOR WORKS				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC22002583/Rvy3e2

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser