

ASS. REC. BY:

REF:

CS3/LPC22002583/RVY³

067A

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLZ4929Rat Workshop m/s LONG VIEW MOTORof GOO JEN LAM HUAT #02-28Insured: LPC

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 71K

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLZ4929R Yr Regn: 2018 / MAY

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA CERATO K31-GAS/R cc 1591Colour: BROWN A/C: Insured / Std / NI / NASp. Reading: 6112 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAF2411MJS761577Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 16/03/22 D.O.I. 22/03/22Survey held at LONG VIEW MOTORDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	REPAIR LIMIT - 47K
	ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (3K-4K) / 6 days

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.E.A. (\$) _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	067A
Vehicle No.:	SLZ4929R
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Mar 2022
Vehicle Make:	KIA
Vehicle Model:	CERATO K3 1.6A SUNROOF
Primary Colour:	Brown
Manufacturing Year:	2017
Engine No.:	G4FGHH691646
Chassis No.:	KNAFZ411MJ5761577
Maximum Power Output:	95.3kW (127 bhp)
Open Market Value:	\$15,158.00
Original Registration Date:	07 May 2018
First Registration Date:	07 May 2018
Transfer Count:	0
Actual ARF Paid:	\$15,158.00
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 May 2028
PARF Rebate Amount:	\$11,368.00
COE Expiry Date:	06 May 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$20,000.00
COE Rebate Amount:	\$12,237.00
Total Rebate Amount:	\$23,605.00

The information contained herein is correct as at 23 Mar 2022

OK

Kia Cerato K3 1.6A Sunroof

Overview

Financial

Accessories

Similar

Research

Photos

Map



Price	\$69,800		
Depreciation ⓘ	\$10,320 /yr View models with similar depre	Reg Date	29-Mar-2018 (6yrs 5days COE left)
Mileage	89,300 km (22.4k /yr)	Manufactured ⓘ	2017
Road Tax ⓘ	\$738 /yr	Transmission	Auto
Dereg Value ⓘ	\$33,660 as of today (change)	OMV ⓘ	\$15,338
COE ⓘ	\$36,810	ARF ⓘ	\$15,338
Engine Cap	1,591 cc	Power	95.3 kW (127 bhp)
Curb Weight ⓘ	1,295 kg	No. of Owners ⓘ	1