

Surveyor : STEVE LKK
 Claim : AIG OD
 DOA : 20.03.2022
 Emailed : 19.04.2022, 3.00pm
 Date Survey : 21.03.2022

VEHICLE NO : SML 8443 K
 MODEL : KIA STONIC 1.0 A
 WIP : 48443

Material	:	\$	<u>4,632.00</u>
Labour	:	\$	<u>2,700.00</u>
Sub-Total	:	\$	<u>7,332.00</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>600.00</u>
Total	:	\$	<u>6,732.00</u>
GST 7%	:	\$	<u>471.24</u>
Grand Total	:	\$	<u>7,203.24</u>
Finalise By/Date	:	LOI /	<u>19/04/2022</u>

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 22/03/2022	Cust No/Name /YEM AI LIN Reg No/Reg Date SML8443K*KC17/ 07/06/2019 Date In/Mileage 22/03/2022/ 35544 Chassis/Package KNAD6811VK6244902 /# Engine No G3LCJP143388 Make/Model KIA/STONIC 1.0 A BET Colour/Trim SEN / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	19/04/2022/ 14:38	BLE	260 / AiTing	48443			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, BONNET, REPAIR LH FRONT FENDER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								800.00
E PNT98000 RESPRAY ON FRONT BUMPER, BONNET, LH FRONT FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME								1050.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								120.00
M SUNDRY SUNDRIES								20.00
M SUNDRY SUPPLY ANTI CORROSION								40.00
M SUNDRY SUPPLY BODY SEALANT								40.00
E PNT88000 REMOVE & REINSTALL A/COND CONDENSOR & RADIATOR TO FACILITATE REPAIR → Supp								120.00
E PNT88000 REPLACE FRONT SUPPORT PANEL → Supp								400.00
S SPECIALISTJOB VACUUM & TOP UP A/COND GAS → Supp								80.00
X EXC INSURANCE POLICY EXCESS								-600.00
X COVER-FR BUMPER UPR					1.00	493.00	20.00	394.40
X SKID PLATE-FR BUMPER					1.00	55.00	20.00	44.00
X ABSORBER-FRONT BUMPER ENERGY					1.00	98.00	20.00	78.40
X GRILLE-FRONT BUMPER					1.00	96.00	20.00	76.80
X MOULDING-FRONT BUMPER A/INTAKE					1.00	61.00	20.00	48.80
X COVER-FR BUMPER FOG LAMP,LH					1.00	64.00	20.00	51.20
X COVER-FR BUMPER,LWR					1.00	367.00	20.00	293.60
X LAMP ASSY-HEAD,LH					1.00	1845.00	20.00	1476.00

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 22/03/2022	Cust No/Name /YEM AI LIN Reg No/Reg Date SML8443K*KC17/ 07/06/2019 Date In/Mileage 22/03/2022/ 35544 Chassis/Package KNAD6811VK6244902 /# Engine No G3LCJP143388 Make/Model KIA/STONIC 1.0 A BET Colour/Trim SEN / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	19/04/2022/ 14:38	BLE	260 / AiTing	48443
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X PANEL ASSY-HOOD		1.00	1135.00	20.00	908.00
X BEAM COMPLETE-FR BUMPER		1.00	751.00	20.00	600.80
X ORNAMENT-KIA NO.115		1.00	38.00	20.00	30.40
X COOLANT (4L)		1.00	26.00	20.00	20.80
X AIR GUIDE-INTERCOOLER		1.00	35.00	20.00	28.00
X STIFFNER-FR BPR LWR		1.00	170.00	20.00	136.00
X CARRIER ASSY-FRONT END MODULE		1.00	556.00	20.00	444.80
Z TEXT					
AIG OD CLAIM					
DOA : 20.03.22					
SURVEYOR STEVE LKK 21.03.22					
POLICY NO : 1900104708-01					
7D=4D+3D					
Guarantee Your Warranty, Maintain with Cycle & Carriage!					

Parts	4,632.00	Nett	6,732.00
Labour	2,520.00	7% GST on	471.24
Standard Menu	0.00		
Specialist Job	80.00	Total Payable	7,203.24
Diagnostics Job	0.00		
Sundry/Others	-500.00		
Total(w/o GST)	6,732.00		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SML 8443 K**

<u>Materials</u>	<u>Cost (\$)</u>
1 Beam complete-fr bumper	751.00 / DD
2 Ornament-Kia No.115	38.00 / neC
3 Coolant (4L)	26.00 / neC
4 Air guide-Intercooler	35.00 / BR
5 Stiffner-Fr bpr Lwr	170.00 / CRV
6 Carrier Assy-Front end module	556.00 / BT

Total	1,576.00
Less 20% discount	315.20
Total after discount	1,260.80

<u>Labour</u>	<u>Cost (\$)</u>
1 Remove & reinstall A/Cond condensor & radiator to facilitate repair	120.00 /
2 Replace front support panel	400.00 /
3 Vacuum & top up A/cond Gas	80.00 /
Total Labour	600.00
Taxable amount	1,860.80
7% GST	130.26
Grand total	\$ 1,991.06

Thank You.

Yours faithfully

LOI AL TING

Senior Officer - Admin

KIA SERVICE CENTRE

DID : 6568 4556 / 6568 4501

FAX : 6567 5258 / 6565 1240

CAR NO: SML8443K

WIP: 48443

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Absorber-FR Bumper Energy	☒ SUPP		- RR	
2	Air duct-FR Bumper LH	☒ SUPP		- RR (MRCMD- LAR)	
3	Beam Complete-FR Bumper	☒ SUPP		- RR	
4	STIFFNER-FR BPR LWR	☒ SUPP		- RR	CRU
5	Front support Panel	☒ SUPP		- RR	
6	Clip x10	☒ SUPP		- RR	
7		☒ SUPP			
8	Remove and Install Condenser	☒ SUPP			
9	and radiator (\$120)	☒ SUPP			
10	Top up A/C GAS \$80	☒ SUPP			Steps
11	Renew Front support panel \$400	☒ SUPP			24/3/22
12	Coolant	☒ SUPP			
13	Repair Working Day x 3	☒ SUPP			
14		☒ SUPP			
15	Logo KIA	☒ SUPP		- ne	
16		☒ SUPP			
17		☒ SUPP			
18		☒ SUPP			
19		☒ SUPP			
20		☒ SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	28/3/22	Spd
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Stonic

SURVEYOR: Steve



HOME

Online



STONIC(YB CU../2019/G 1.0 T-G..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



9/9

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
PGS	No Current DTC	Good

System	DTC	Description	State
--------	-----	-------------	-------

No History or Pending DTC

S/W Ver.

M-E-K-01-00-0268

VCI Ver.

02.63

ECU Ver.

M-E-K-01-00-0208

OS Ver.

Android 10