

ASS. REC. BY: ARMREF: U6/CT122002622/Rea3

370P

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMJ 2510Aat Workshop m/s Automotive Repair Ctrof 38, Woodlawn Ind Pk E1 #05-18Insured: CTI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 76K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMJ 2510A Yr Regn: 2019 / FEBType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Shuttle 1.5 CVT.c 1496Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 040581 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: AK81201957Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / 8/Rim / STD A/Rim orTyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 17/03/22 D.O.I. 22/03/22Survey held at ARC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 52K

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

Report Format: _____

Lump Sum / L.B.F. (\$ _____)

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2203 - 154

DATE : 4-Mar-2022

POLICY NO. : BD P10143552R03

VEHICLE REG. NO. : SMJ2510A

VEHICLE MAKE : HONDA / SHUTTLE 1.5G CVT

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper <i>de</i>	1	\$ 1,200.00	\$ 1,200.00
2	Rear Bumper Clip <i>ne</i>	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer LH <i>X</i>	1	\$ 50.00	\$ 50.00
4	Rear Bumper Retainer RH <i>X</i>	1	\$ 50.00	\$ 50.00
5	Rear Bumper Grille RH <i>X</i>	1	\$ 80.00	\$ 80.00
6	Rear Bumper Grille LH <i>?</i>	1	\$ 80.00	\$ 80.00
7	Rear Bumper Grille Inner Bracket RH <i>X</i>	1	\$ 90.00	\$ 90.00
8	Rear Bumper Grille Inner Bracket LH <i>X</i>	1	\$ 90.00	\$ 90.00
9	Rear Bumper Grille Reflector LH <i>X</i>	1	\$ 70.00	\$ 70.00
10	Rear Bumper Grille Reflector RH <i>X</i>	1	\$ 70.00	\$ 70.00
11	Rear Bumper Tow Eye Cover <i>X</i>	1	\$ 50.00	\$ 50.00
12	Rear Tail Lamp LH <i>X</i>	1	\$ 680.00	\$ 680.00
13	Rear Tail Lamp RH <i>X</i>	1	\$ 680.00	\$ 680.00
14	Rear Tailgate Lamp RH <i>X</i>	1	\$ 520.00	\$ 520.00
15	Rear Tail Lamp Panel LH <i>X</i>	1	\$ 220.00	\$ 220.00
16	Rear Tail Lamp Panel RH <i>X</i>	1	\$ 220.00	\$ 220.00
17	Rear Tailgate Lamp LH <i>X</i>	1	\$ 520.00	\$ 520.00
18	Rear Tailgate <i>bu</i>	1	\$ 1,500.00	\$ 1,500.00
19	Rear Tailgate Chrome Garnish <i>X</i>	1	\$ 540.00	\$ 540.00
20	Rear Tailgate Shuttle Emblem <i>ne</i>	1	\$ 80.00	\$ 80.00
21	Rear Tailgate Honda Emblem <i>ne</i>	1	\$ 80.00	\$ 80.00
22	Rear Tailgate Lock <i>X</i>	1	\$ 150.00	\$ 150.00
23	Rear Tailgate Absorber RH <i>X</i>	1	\$ 150.00	\$ 150.00
24	Rear Tailgate Absorber LH <i>X</i>	1	\$ 150.00	\$ 150.00
25	Rear Tailgate Inner Trim <i>?</i>	1	\$ 420.00	\$ 420.00
26	Rear / End Panel Garnish No. 10 <i>de</i>	1	\$ 220.00	\$ 220.00
27	Rear Outlet Air Grille LH <i>X</i>	1	\$ 60.00	\$ 60.00
28	Rear Outlet Air Grille RH <i>X</i>	1	\$ 60.00	\$ 60.00
29	Rear / End Panel Garnish Cover No. 7 <i>?</i> <i>X</i>	1	\$ 120.00	\$ 120.00
30	End Panel <i>bt</i>	1	\$ 720.00	\$ 720.00
31	Rear Floor Panel Sink <i>X</i>	1	\$ 1,500.00	\$ 1,500.00

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
 #05-18, Singapore 757700
 Tel: 64688834 Fax: 64622278
 E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2203 - 154
 DATE : 4-Mar-2022
 POLICY NO. : BD P10143552R03
 VEHICLE REG. NO. : SMJ2510A
 VEHICLE MAKE : HONDA / SHUTTLE 1.5G CVT

TO Motor Claim Department
 China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

RASUL - Hg 90010068
 6 days - L/S - 22/03/22 P1155
 Resurvey after repair

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
32	Rear Spare Tyre Board Cover No. 3 <i>X</i>	1	\$ 400.00	\$ 400.00
33	Rear Spare Tyre Board Tray No. 6 <i>X</i>	1	\$ 300.00	\$ 300.00
34	Rear Windscreen Molding <i>re /</i>	1	\$ 100.00	\$ 100.00
35	Rear Exhaust <i>X</i>	1	\$ 880.00	\$ 880.00
36	Rear Exhaust Rubber Mount <i>X</i>	2	\$ 50.00	\$ 100.00
Total Spare Parts				\$ 12,250.00
SPECIAL NETT				
37	Rear Windscreen Sealant <i>re /</i>	1	\$ 40.00	\$ 40.00
38	Rear Licence Plate <i>X</i>	1	\$ 35.00	\$ 35.00
39	Reverse Sensor <i>cut /</i>	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 275.00
LABOUR				
40	Spray painting Rear Bumper, Tailgate, Both Rear Fender Including Blending	1	\$ 1,000.00	\$ 1,000.00
41	Remove, Replace and Repair Accident Affected Area	1	\$ 1,000.00	\$ 1,000.00
42	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
43	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 100.00	\$ 100.00
44	Remove and Refit Rear Exhaust Pipe and Silencer, Re-align	1	\$ 100.00	\$ 100.00
45	Remove and Refit Rear Windscreen	1	\$ 100.00	\$ 100.00
46	Remove and Refit Rear Reverse Sensor	1	\$ 100.00	\$ 100.00
47	Anti-Rust Tuff Coat	1	\$ 40.00	\$ 40.00
48	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,570.00
Amount Before Excess				\$ 15,095.00
Add GST @ 7%				1,056.65
Total Amount Payable				\$ 16,151.65

Estimate prepared by: Oscar Pong

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Please arrange this vehicle to be surveyed soonest possible. Thank you.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 21/03/2022 17:42 (SGT)
Date of Accident 19/03/2022 12:40 (SGT)
Exact Location of Accident Singapore
Additional Location Information CTE BEOFRE AMK AVE 1 EXIT
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMJ2510A

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner SATHIYANARAYANAN KANNIYAPPAN
NRIC No SXXXX370A
Email Address sathiya2306@gmail.com
Mobile Phone No (Phone) +65-98557820
Alternative Phone No +65-98557820

VEHICLE PARTICULARS

Manufacturer Honda
Model Shuttle
Variant -
Exact purpose for which vehicle was being used at time of accident -
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1496

INSURANCE COMPANY

Name of Insurance Company Auto & General Insurance (Singapore) Pte. Limited.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number P10143552R03
Cover Note Number -

DRIVER

Name of Driver SATHIYANARAYANAN KANNIYAPPAN
NRIC No SXXXX370A

Date Of Birth 23/05/1980
 Occupation Indoor
 Date Of Driving Pass 12/02/2016
 Driving experience 6 YEARS AND 1 MONTH
 Gender Male
 Mobile Number (Phone) +65-98557820
 Alt. Phone Number +65-98557820
 Email Address sathiya2306@gmail.com
 Address 73 ROSEWOOD DRIVE #01-13
 Address complement -
 Postcode 737784
 Is the driver the policyholder? Yes
 If No, Relationship of the Driver with the Insured -
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver -
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Chain Collision
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 3
 Was anybody injured in the Accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other vehicle or property damaged? Yes
 Number of Passengers (Including Driver) 2
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

PASSENGER 1

Name JULIE MANGUBAT
 Gender Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? Yes
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SDZ9881E
 Vehicle Manufacturer Mercedes
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Private car

Name of Driver NICOLE
 Contact Number (Phone) +65-98733363
 Address
 Address complement
 Postcode
 Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (Including Driver)


DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SCV8232X
 Vehicle Manufacturer
 Vehicle Model
 Vehicle Variant
 Vehicle Colour
 Vehicle Category Private car
 Name of Driver
 Contact Number (Phone) +65-90890228
 Address
 Address complement
 Postcode
 Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (Including Driver)

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that :
(a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

 21/3/22 11:25am
 Sketch Plan

X
 Driver's Signature (if driver is not the policyholder) / Date & Time


 Witnessed by Reporting Centre Personnel





Describe Circumstances of the Accident

Car A was driving along CTF before AMK Ave Exit.
 The cars in front stopped due to accident. Car A stopped
 in time (please refer to video). Car B and C couldn't
 stop and rear-ended Car A.

No injuries.

Declaration

We declare the foregoing particulars are true in every respect.

 Policyholder's Signature / Date & Time 2/3/22 11:25am	X Driver's Signature (if driver is not the policyholder) / Date & Time	 Witnessed by Reporting Centre Personnel
---	--	---

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	370A
Vehicle Details	
Vehicle No.:	SMJ2510A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	21 Mar 2022
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5G CVT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	L15B5462290
Chassis No.:	GK81201957
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,247.00
Original Registration Date:	26 Feb 2019
First Registration Date:	26 Feb 2019
Transfer Count:	0
Actual ARF Paid:	\$8,247.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Feb 2029
PARF Rebate Amount:	\$6,185.00
Intended COE Rebate Details	
COE Expiry Date:	25 Feb 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$25,689.00
COE Rebate Amount:	\$17,798.00
Total Rebate Amount:	\$23,983.00

The information contained herein is correct as at 21 Mar 2022

OK

Honda Shuttle 1.5A G

Overview

Financial

Accessories

Similar

Research

Photos

Map

CARZ WORLD
PTE. LTD.

Price **\$80,988**

Depreciation **\$10,410 /yr**
[View models with similar depre](#)

Reg Date **09-Jul-2019**
(7yrs 3mths 15days COE left)

Mileage **30,000 km (11.1k /yr)**

Manufactured **2019**

Road Tax **\$682 /yr**

Transmission **Auto**

Dereg Value **\$27,204 as of today (change)**

OMV **\$19,998**

COE **\$26,999**

ARF **\$9,998**

Engine Cap **1,496 cc**

Power **97.0 kW (130 bhp)**

Curb Weight **1,130 kg**

No. of Owners **1**