

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE I	PTE LTD	R	Ref:	CS3/ASM22002628/Gvy3e2	
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		D	Date:	05/04/2022	
	ATTN: ANG YVONI	NE	C	ode:	ASM	
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHD 9611L	Veh. Inspected		SKS 9800T	
	Policy No.	VFX/P2413997	Coverage (\$)		0.00	
	Claim No.	S2M03W2C	Excess (\$)		0.00	
	Assign From	ANG YVONNE	Assign Date		22/03/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA LEXUS ES250 LUXURY	c.c		2494	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	JTHBJ1GG702092516	Colour		BLACK	
	Odometer	89007 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/55 R17	BRIDGESTONE		6 mm	
	L/H Front Tyre	215/55 R17	BRIDGESTONE		6 mm	
	R/H Rear Tyre	215/55 R17	BRIDGESTONE		6 mm	
	L/H Rear Tyre	215/55 R17	BRIDGESTONE		6 mm	
4. Description of Damages						
	THE VEHICLE SUS PORTION.	STAINED DAMAGES AT THE FRONT AND REAR				
5.	5. General Information					
	Accident Date	18/03/2022	Inspect Date / Ti	me	22/03/2022 (03:30 PM)	
	Survey held at KING'S AUTO REPAIR & SERVICE PTE LTD					
	176 SIN MING DRIVE, #02-10, SIN MING AUTOCARE, SINGAPORE 575721					
5a.						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$10,000-\$12,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days					

Report Ref No. CS3/ASM22002628/Gvy3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A **Automotive Assessor** $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser