

ASS. NO.:

REF:

CS3 ASM 21012007/Dgy<sup>3</sup>

## ASSIGNMENT

CUE April 2023

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimate Cost: \_\_\_\_\_

OD / T / RES / OD RES / EVA / RV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Work in m/s \_\_\_\_\_

of \_\_\_\_\_

Insured \_\_\_\_\_

Policy No. \_\_\_\_\_

Claimant &amp; S1M03MX9

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Check record)

Make &amp; Model: \_\_\_\_\_

(Police Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. of Market Value: \_\_\_\_\_

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lump Sum 71% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SSD 9976K Yr Regn: April 2008

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Stream CC 1799

Colour: Silver A/C: Insured / Std / N/A

Sp. Reading: 231972 T/Radio: Insured / Std / N/A

Eng/No: R18A1769442

C/No: R.N61062325

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: N/A / STD A/Rim or

Tyre Size: F: 205/55 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMAI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal: 8 mm

R/Bal: 5 mm

L/Bal: 8 mm

L/Bal: 5 mm

D.O.A. 20/11/2021

D.O.L. 13/12/2021

Survey held at JL Ando 17/3006 Ubi Rd 1

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear W/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
13/04/22	AXA STLC 5731E MV 9.2K 13/12 - 1630m
	Rear lamp 400/-500/- LTA 5.2K 14/12 - 1040 m/s
	Rear bumper repair HL 4K 15/12 - 1208 m/s
13/04/22	Submit final fig \$400, 2 days. (Red \$3400, 89%) (No Lump Sum)
	Old damage on rear bumper and rear tailgate of TP vehicle
	Scene photo in OI GIA report seen. contact only at rear bumper of TP.

28/12/21 @ 5.03pm referred to Chan Kian Chuan via Smart Claims.

23/12/21 Submit PRS.

13/04 Typist

: Prefl. Report

: Final Report

Date/Time, File Return to?

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Feet:

Transportation:

S + RS: SI

Photos

2)

TP

Add Fee:

: Site Insp (\$

: Interview (\$

Report Format: Smart Claims - PRS