

ASS. REG. BY: Taught

REF:

CS/1CS22002688/Trvs.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: SLE 731E
 Policy No. MPC21A00039900
 Claims No. DMPC2200113H
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$170K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Date: _____ Person Contacted: _____
 Vehicle: IN / OUT Gray

Veh No: SMX 6839C Yr Regn: 2021 Jan.
 Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: BMW 318I c.c 1998
 Colour Gray A/C: Insured / Std / NI / NA
 Sp. Reading 21058 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WBA72DY 000 FK61322
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/50R17
 R: 1 1
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 18/3/2022 D.O.I. 24/5/22
 Survey held at BIS Auto.
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Frt o/s, 4/c
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
27/4/22	Submit preli report-revised fig \$11,742.80 check items \$8503.50 Note: TP convert to OD claim

Date/Time, File Pass to?

☐ : Proll. Report
☐ : Final Report

1)

Date/Time, File Return to?

2) 27/4/22-typist

Days Of Repair: 7

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

Photos

Others

TOTAL

Rep. / Format :

Lump Sum / L.B.I. :

BIS AUTOMOBILES

30 Teban Gardens Crescent Singapore 608927
BIS Automobiles Pte Ltd
Co. Reg. No. 201908617D. GST Reg. No. 201908617D



ESTIMATES

Estimate No. : 21998884
Date Estimated : 21/03/2022
Prepared By : Gary Poh Chai Hoon

- ESTIMATE REPAIR FOR -
WONG WEI KANG

- ACCOUNT -
ECICS Limited

REGN. NO.
SMX6839C

CHASSIS NO.
FK61322

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Motor Claims Department

MODEL
BMW 3' G20 318i

DESCRIPTION	ORIGINAL PRICE	NETT
To replace front bumper and attachments include making good the front RH fender and knocking out dents caused by the accident	720 1080	2,160.00
To spray paint front bumper and front RH fender	? w/w bumper 850	1,675.00
To replace PDC sensors and connectors include resetting and conducting checks for proper function	280	350.00
To supply front RH wheel Rim	✓	TBA
To supply front RH Tire	?	TBA
To replace front RH tire or wheel rim include wheel balancing	✓	100.00
To conduct checks on steering geometry including wheel alignment in accordance with BMW specifications	360	450.00
To remove and install Front brake discs, brake pads, brake hoses and brake calipers include bleeding of brake system, conducting brake tests and checks for leak	photo-360	450.00

BIS AUTOMOBILES

30 Teban Gardens Crescent Singapore 608927

BIS Automobiles Pte Ltd

Co. Reg. No. 201908617D. GST Reg. No. 201908617D



ESTIMATES

To remove and install Front RH suspension for inspection include replacement of damaged parts and conducting checks for proper function

photo? 720 900.00

To carry out Diagnosis Tests

400. 500.00

Sundries

✓ 100.00

DESCRIPTION	UNIT PRICE	QTY	NETT
31 10 6883131 Front axle support	1404.00	1.00 ?	1404.00
31 10 6894662 Tension strut with hydr. Mount ,right	286.15	1.00 dd✓	286.15
31 10 6898072 Wishbone, bottom,with rubber mount ,right	343.35	1.00 bt✓	343.35
31 20 6866315 Wheel hub with bearing	431.85	1.00 bt✓	431.85
31 21 6878610 Carrier, right (RWD)	499.05	1.00 bt✓	499.05
31 20 6872920 Spherical collar screw (M12x1.25x45)	8.05	4.00 ?	32.20
31 30 6889272 Support bearing front	234.95	1.00 ?	234.95
31 31 6888454 Front right spring strut	537.95	1.00 ?	537.95
31 30 6893360 Swing support, front, right	105.15	1.00 ?	105.15
31 30 1543200 Stabilizer front with rubber mounting	411.70	1.00 ?	411.70
32 10 5A3B7E2 Steering gear, electric	5244.75	1.00 ?	5244.75
32 10 6880697 Right tie rod	313.05	1.00 bt✓	313.05
32 10 6880695 Left tie rod	313.05	1.00 X	313.05
31 10 6898071 Wishbone, bottom, with rubber ,left	343.35	1.00 X	343.35
31 10 6894661 Tension strut with hydr. mount, left	286.15	1.00 X	286.15
36 11 6883517 Disk wheel,	999.40	1.00 out✓	999.40
36 13 6850834 Hub cap with chrome edge (BMW)	29.80	1.00 ?	29.80
63 11 8496158 Headlight LED, AHL, right	3397.70	1.00 out✓	3397.70
51 11 8496508 Panel, bumper, primed, fro	1089.85	1.00 de✓	1089.85
51 11 7422248 Support right	83.85	1.00 ?	83.85
51 11 7464276 Grille, side, closed, right (Basis)	79.60	1.00 out✓	79.60
51 11 7471518 Air inlet finisher, right	68.20	1.00 ?	68.20
66 20 9827060 Ultrasonic s	383.15	1.00 ?	383.15
66 20 9390408 Decoupling ring	5.15	4.00 ml✓	20.60

disassemble photo.

70w in \$ 150.00

Total Labour :	6,685.00
Total Parts :	16,938.85
Total Labour & Parts :	23,623.85
Deduction for Excess :	
Total Repair Costs less :	23,623.85
GST @7%:	1,653.67
Grand Total :	25,277.52

Tanji 97495749/62563561
WP 24/3/22 e 1045
P/P Resurvey before paint
6-7 days.

TOW JOB WORK ORDERGST Reg No. : 19-9806389-N
Co. Reg No. : 199806389N

Contract :

AVIVA ASIA PTE LTD

AUTOSWIFT RECOVERY PTE LTD

W/Order No. : T 191909

PART A: JOB DETAILS

Service Date

18/3/22

Time Received

1440

Member / Customer's Name

MR Wong

Time Arrived

1507

Membership / NRIC No.

91478755

Time Completed

1635

Contact No.

SMX 6839 C

Total Mileage

50

Vehicle Registration No.

807 Home Road

Car Make / Model

BMW 318

Breakdown Location

Towed Destination

30 Teban Gardens cres LVL

NORMAL TOWING	ADDITIONAL SERVICES
☐ Straight Towing	☐ Multi-Storey / Basement Car Park
☒ Straight Towing with King Dolley	☐ Woodlands Checkpoint / Tuas 2nd Link
☐ Flat Bed / Car Carrier	☐ Sentosa / Jurong Island
☐ Flat Bed / Car Carrier with King Dolley	☒ Accident Towing
☐ Heavy Goods Vehicle / Light Goods Vehicle	☐ Car Ditched / Winched Up / Crane Up
	☐ Dismantle Shaft / Release Brakes
SURCHARGES / OTHERS	ROADSIDE SERVICES
☐ Sunday / Public Holiday Towing (full day)	☐ Jump Start
☐ Midnight Towing (2400hrs to 0700hrs)	☐ Tyre Replacement
☐ Call Cancelled / Car Missing	☐ Patch Tyre Service
☐ Standby / Waiting Time	☐ Repair Tyre & Returned
☐ Luxury Cars	☐ Battery Replacement
☐ AA Membership Enrolment / AA Renewal	Battery Receipt No: _____

REMARKS / COMMENTS BY TOW CREW

72

Tow Crew ID

GBK7964R

Truck No

Tow Crew's Signature

PART B: MEMBER / CUSTOMER ACKNOWLEDGEMENT

- I authorise AutoSwift Recovery Pte Ltd to tow my vehicle to the above-mentioned workshop of my choice.
- I have been advised to remove all valuables (handphone, laptop, parking coupons, cash cards etc) from the vehicle.
- I understand that items left behind are at my own risk and that AutoSwift Recovery Pte Ltd will not be held responsible for any losses.
- I accept that there may be damages to my vehicle arising from the towing operation and I will not hold AutoSwift Recovery liable for the damages.
- Remarks: _____

Member / Customer Signature

Date

PART C: WORKSHOP / AGENT DECLARATION

- I hereby represent the company receiving the above mentioned vehicle.
- AutoSwift Recovery Pte Ltd will not be held responsible for any damages or loss of valuables discovered while the vehicle is in our possession.
- Remarks: _____

Workshop's Representative Signature



Workshop's Stamp

Date

CUSTOMER COPY

Swift and Safe

AutoSwift Recovery Pte Ltd

(A wholly-owned subsidiary of AA Singapore)

Head Office: 2 Kung Chong Road #06-01 AA Centre Singapore Tel: 6333 8811 Fax: 6722 5004

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	21/03/2022 23:11 (SGT)
Date of Accident	18/03/2022 13:53 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	HORNE ROAD , CARPARK LOT 36
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMX6839C
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	WONG WEI KANG
NRIC No	SXXXX479A
Email Address	www.bryan@gmail.com
Mobile Phone No	(Phone) +65-91478755
Alternative Phone No	+65-91478755

VEHICLE PARTICULARS

Manufacturer	BMW
Model	318
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1995

INSURANCE COMPANY

Name of Insurance Company	Singapore Life Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	-
Cover Note Number	-

DRIVER

Name of Driver	WONG WEI KANG
NRIC No	SXXXX479A

Date Of Birth	20/09/1988
Occupation	Indoor
Date Of Driving Pass	28/11/2008
Driving experience	13 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91478755
Alt. Phone Number	+65-91478755
Email Address	wwk.bryan@gmail.com
Address	3 BISHAN ST 15 #14-21
Address complement	-
Postcode	573911
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	KHAI LUN
Gender	Male

PASSENGER 2

Name	SELINA
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACH.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLE731E
Vehicle Manufacturer	Toyota

Vehicle Model	Wish
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	CHOE YONG CHAI
NRIC No	SXXXX896I
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	ECICS Limited
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


21 March 2022
Policyholder's Signature / Date &
Time 12:44pm

Driver's Signature (If driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre
Personnel

Sketch Plan



