



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22002701/Any3q2 Date: 09/09/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLN 2935Z	Veh. Inspected	SKN 2794A	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10014397/CD	Excess (\$)	0.00	
Assign From	SHAFAWATI MD RABU	Assign Date	23/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN GOLF	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WVWZZZAUZEW361449	Colour	BLUE	
Odometer	188008 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/03/2022	Inspection Date	24/03/2022	
Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	