

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
	MS FIRST CAPITA	L INSURANCE LTD	Ref:	CS/FCI22002713/Kvy3e2
	36 ROBINSON RO #16-01 CITY HOUS	AD SESINGAPORE 068877	Date:	06/05/2022
			Code:	FCI2
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	XD 7724T	Veh. Inspected	SNC 7650X
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22000854MFVS	Excess (\$)	0.00
	Assign From	CAROLINE CABRERA	Assign Date	24/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	TESLA MODEL 3 (A)	c.c	0
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	LRW3F7FA8MC384809	Colour	METALLIC BLACK
	Odometer	9566 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/45 R18	MICHELIN	9 mm
	L/H Front Tyre	235/45 R18	MICHELIN	9 mm
	R/H Rear Tyre	235/45 R18	MICHELIN	9 mm
	L/H Rear Tyre	235/45 R18	MICHELIN	9 mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	22/03/2022	Inspection Date	25/03/2022
	Survey held at	10 ANG MO KIO IND PARK 2A #01-05 AMK AUTOPOINT		
	Repairer	OPTIMA WERKZ PTE LTD		
5a.	Remarks			
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days			
	•		,	