



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## PRE-REPAIR INSPECTION REPORT

ALLIED WORLD ASSURANCE COMPANY LTD  
(SINGAPORE BRANCH) 60 ANSON ROAD #08-01  
(8th FLOOR) MAPLETREE ANSON  
SINGAPORE 079914

Ref: CS3/AWA22002726/Rqy3e2

Date: 05/05/2022

Code: AWA

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

<b>Insured Veh.</b>	YQ 3819A	<b>Veh. Inspected</b>	SMW 6686G
<b>Policy No.</b>	BVFCB0007242114	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	NSV2200035/HLF	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	GOH STELLA	<b>Assign Date</b>	24/03/2022

### 2. Vehicle Particulars & Condition


<b>Make &amp; Model</b>	MERCEDES BENZ C180 AV	<b>c.c</b>	1595
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	WDD2050402R252285	<b>Colour</b>	WHITE
<b>Odometer</b>	90503 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	225/45 R18	CONTINENTAL	6 mm
<b>L/H Front Tyre</b>	225/45 R18	CONTINENTAL	6 mm
<b>R/H Rear Tyre</b>	225/45 R18	CONTINENTAL	6 mm
<b>L/H Rear Tyre</b>	225/45 R18	CONTINENTAL	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.



### 5. General Information

<b>Accident Date</b>	18/03/2022	<b>Inspect Date / Time</b>	28/03/2022 ( 02:59 PM )
<b>Survey held at</b>	REVOL CARZ GARAGE PTE LTD BLOCK 10, ANG MO KIO IND PARK 2A #02-18, AMK AUTOPOINT SINGAPORE 568047		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.  
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**

Report Ref No. CS3/AWA22002726/Rqy3e2

#### Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.