

Date:

ASS. REC. BY:

REF:

SMR/ CS/SMR22002744/Kvy3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SHF 163L

Policy No. _____

Claims No. TAX/03/22/2049

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 8

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 6-7 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLU 1870X

Yr Regn: 11.17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda

c.c. 1496

Colour: M. Red

A/C: Insured / Std / NI / NA

Sp. Reading: 363886

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU13

1264690

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 2 mm

R/Bal. 2 mm

L/Bal. 7 mm

L/Bal. 2 mm

D.O.A. 23/3/22

D.O.I. 25/3/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/4/22 Kenneth informed LS \$4900 (red 9318.72, 65%)

Date/Time, File Pass to?

☐: Prell. Report

1)

☐: Final Report

Date/Time, File Return to?

2) 6/4/22-typist

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐: Site Insp (\$☐: Interview (\$☐: Tech Invs (\$☐: Weekend (\$

\$ - RS. SI

Fees

Others

Report Format: TP

Lump Sum /+B.+ (\$ 4900

TOTAL



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005486N

HEADQUARTERS / SHOWROOM / WORKSHOP

385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP

176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Repair Estimates

SLU 1870 X

Parts	(a) Cost / List Price Items	\$	11,248.40
	Plus/Less 20%	\$	2,249.68
	Total of Cost / List	\$	8,998.72
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	700.00
Total Parts Cost		\$	9,698.72
Labour		\$	4,520.00
Total		\$	14,218.72

Not Authorize

1/1/22 @

Repair After Rain

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor

:

Kenneth

Company

:

LKK

Survey conducted on

:

25/3/22

at

10:30

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : *6-7* day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor

:

Le

Date:

25/3/22

**ESTEEM**

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Spare Parts

Vehicle No. : **SLU 1870 X**
Make & Model : **HONDA VEZEL**
Chassis No. : **RU31264690**

Submit By : **Carmen Lim**
Year Manufacture : **2017 Nov**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH front fender	1	\$580.00		✓
2	RH front fender undershield	1	\$155.00		✓
3	RH front fender undershield clip	10	\$35.00		✓
4	RHF fender wording "hybrid"	1	\$68.70		✓
5	RH front fender protector	1	\$195.00		✓
6	RH front fender protector clip	10	\$35.00		✓
7	RH front lower arm	1	\$380.00		?
8	RH front shock absorber	1	\$460.10		?
9	RH front shock absorber top mounting	1	\$36.00		?
10	RH front shock absorber stopper	1	\$26.90		?
11	RH front knuckle arm	1	\$289.70		?
12	RH front knuckle bearing	1	\$155.80		?
13	RH front wheel hub	1	\$197.80		?
14	RH front wheel hub lock nut	1	\$8.00		X
15	RH front tie rod	1	\$96.80		?
16	RH front tie rod end	1	\$81.80		?
17	RH front drive shaft	1	\$1,100.00		X
18	RH front tyre	1	\$350.00	S.N	X
19	RH front rim	1	\$801.00		✓
20	RH side mirror	1	\$874.50		X
21	RH front door	1	\$1,080.50		✓
22	RH front door hinge top	1	\$48.60		X
23	RH front door hinge bottom	1	\$48.60		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLU 1870 X**
 Make & Model : **HONDA VEZEL**
 Chassis No : **RU31264690**

Submit By : **Carmen Lim**
 Year Manufacture : **2017 Nov**
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	RH front door weatherstrip	1	\$76.30		X
25	RHF door glass outer moulding	1	\$60.00		X
26	RH front door power window motor	1	\$398.10		?
27	RH front door power window regulator	1			
28	RH rear door	1	\$930.60		✓
29	RH rear door hinge top	1	\$48.60		X
30	RH rear door hinge bottom	1	\$48.60		X
31	RH rear door lock	1	\$210.00		X
32	RH rear door checker	1	\$48.40		X
33	RH rear door weatherstrip	1	\$92.30		✓
34	RH rear door stand rubber	1	\$86.80		X
35	RH side skirt	1	\$387.50		✓
36	RH side skirt clip	10	\$40.00		✓
37	RH rear fender protector	1	\$195.00		✓
38	RH rear fender protector clip	10	\$35.00		✓
39	RH rear tyre	1	\$350.00	S.N	X
40	RH rear rim	1	\$801.00		✓
41	Rear bumper	1	\$777.90		X
42	Rear bumper clip	10	\$35.00		X
43	Rear bumper side retainer RH	1	\$27.50		X
44	Rear bumper RH	1	\$195.00		X
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200006485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Labour

Vehicle No. : **SLU 1870 X**

Submit By : **Carmen Lim**

Make & Model : **HONDA VEZEL**

Year of Manufacture : **2017 Nov**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(RHF FENDER,RHF DOOR,RHR DOOR,RH SIDE SKIRT,RHR FENDER,REAR BUMPER,RH CENTRE PILLAR)	\$1,400.00	600
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(RHF FENDER,RHF DOOR,RHR DOOR,RH SIDE SKIRT,RHR FENDER,REAR BUMPER,RH CENTRE PILLAR)	\$1,600.00	880
3	To check wiring	\$50.00	20
4	To remove & refit undercarriage to assist work load.	\$250.00	?
5	To do wheel alignment.	\$120.00	60
6	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$300.00	120
7	To tuff coat	\$200.00	90
8	To do art work (Bil 1)	\$600.00	?

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 24/03/2022 16:08 (SGT)
Date of Accident 23/03/2022 15:25 (SGT)
Exact Location of Accident N Canal Rd, Singapore
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLU1870X

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner GRAB RENTALS PTE LTD
Company Reg No 2XXXXX200G
Email Address gr.sg.accident@grab.com
Mobile Phone No (Phone) +65-90905770
Alternative Phone No (Home) +65-66550005

VEHICLE PARTICULARS

Manufacturer Honda
Model Vezel
Variant -
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private hire
Transmission Auto
CC 1496

INSURANCE COMPANY

Name of Insurance Company India International Insurance Pte Ltd
Type of Coverage Comprehensive
Fleet Policy Yes
Policy Number D21MFL0000447_01
Cover Note Number -

DRIVER

Name of Driver VINCENT YAP ZHE BIN
NRIC No SXXXX346F

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

VEH A
SLU1870X
VEH B
SHF163L

