

Our Ref: CT0322/SH 8566P/CK(st)  
Date: 05.05.2022

CHINA TAIPING INSURANCE CO (S)PTE L  
3 ANSON ROAD #16-00  
Singapore 079909

Attn : Motor Claims Department

**Without Prejudice**

**ComfortDelGro Engineering Pte Ltd**  
59 Loyang Drive Singapore 508969

www.cdge.com.sg

Company Registration No: 199506048W

Dear Sir/Madam

**ACCIDENT ON 19.03.2022 INVOLVING SH 8566P & SMU7032Y ALONG BLK 596D ANG MO KIO STREET 52**

We are the authorised repair workshop for Comfort Transportation Pte Ltd , the owner of vehicle No SH 8566P, which was involved in the captioned accident with your insured vehicle No SMU7032Y.

The vehicle owner and the taxi hirer/driver concerned have requested and authorised us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage of the vehicle.

As the accident was caused by the negligent act of your insured driver, we are submitting these claims for your consideration on behalf of the claimants:

**Taxi Owner's Claim :**

1. Cost of Repairs		S\$	1,712.00
2. Loss of Rental	2 days x S\$ 125.40	S\$	250.80
3. Survey Report Fee		S\$	0.00
4. LTA Search Fee		S\$	7.49
5. GIA / Police Report Fee		S\$	0.00
6. Others		S\$	0.00

**Hirer's Claim :**

1. Loss of Income	2 days x S\$ 80.00	S\$	160.00
2. Others		S\$	0.00

[E&OE]      **Total Claims**      S\$      **2,130.29**

A copy each of the following supporting documents marked [X] is enclosed:

<input checked="" type="checkbox"/> Original Repair Bill	<input checked="" type="checkbox"/> Letter of Authority from Owner/Hirer/Operator
<input checked="" type="checkbox"/> GIA/Police Report(s)	<input checked="" type="checkbox"/> Rental Rate Letter
<input checked="" type="checkbox"/> LTA/GIA Search Slip(s)	<input checked="" type="checkbox"/> Downtime/Mileage Record
<input type="checkbox"/> Survey Report / Bill	<input type="checkbox"/> Witness Statement / Accident Scene Photo(s)
<input type="checkbox"/> Driver's IC/DL/VL / Road Tax / Log Card / Certificate of Insurance	
<input type="checkbox"/> Tow Chit / PIR / Hirer's IRAS / Others :	

Kindly look into the matter and let us hear from you on the settlement of our clients' claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours sincerely

Catherine Koh

CDGE Claims Department

DID: 62148733

FAX: -

Email: catherinekoh@cdge.com.sg

This is a computer-generated letter. No signature is required.

A member of

**LETTER OF AUTHORISATION**

(NAF / PAF)

**ACCIDENT INVOLVING TOYOTA PRIUS SH8566P , SMU7032Y ON 19-Mar-22 04:15**  
**ALONG BLK 596D ANG MO KIO STREET 52**

I / We **NG CHEE KEONG** (Hirer) NRIC No.: **SXXXX112Z**

and/or **ELIZABETH HO MENG H...** (Relief) NRIC No.: **SXXXX737B**

Taxi Number **SH8566P**

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of earning (Pending successful recovery), loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date **21-Mar-2022**

Name of Hirer **NG CHEE KEONG**

Hirer NRIC **SXXXX112Z**

Signature :



Address **349 YISHUN AVENUE 11 #12-243**  
**760349**

Contact No. **87839921**

Name of Relief **ELIZABETH HO MENG HUA**

Relief NRIC **SXXXX737B**

Signature :



Address **409 YISHUN RING ROAD #12-1789**  
**760409**

Contact No. **91690097**

GST REG. NO. M2-8921817-3

**TAX INVOICE**

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD  
SPRINGLEAF TOWER

3 ANSON ROAD #16-00  
SINGAPORE 079909

CONTACT NO: 62222366

Description : 3P 19.03.2022

**VEHICLE NO**  
SH 8566P

**NO/DATE**  
91670151 27.04.2022

**MAKE**  
TOYOTA

**JOB NO.**  
305509554

**MODEL**  
PRIUS HYBRID(G4)

**ODOMETER READING**  
\_\_\_\_\_

**DATE OF REG**  
03.10.2017

**CHASSIS CODE**  
JTDKB3FU003565037

**JOB TYPE**

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt		1,600.00
Add GST @ 7.000 %		112.00
<b>Total Invoice amount</b>		<b>1,712.00</b>

Issued by : CHEWBEELENG 27.04.2022 14:49:15  
Repair Type : CLSO/57/57  
Payment Type/Term : /Credit 30 days

BY DELIVERING TAKING ALL NECESSARILY PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS RESPONSIBILITY FOR CARE ON OTHER PROPERTIES BELONGING TO CUSTOMERS WHO VEHICLES ARE DRIVEN AND KEPT ON COMPANY'S PREMISES.  
IF CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY IN WRITING TO THE COMPANY OF ANY COMPLAINTS OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.  
AN INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FOR THE PERIOD OF DEFAULT.  
PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCY WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd

Head Office:  
205 Braddell Road  
Singapore 579701

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.

Kindly note that no receipt shall be issued unless requested.

**CUSTOMER'S COPY**

Our Ref: CT22030301

Date: 25 April 2022



## TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON                    19/03/2022    @   04:15 hrs  
ALONG                            BLK 596D ANG MO KIO STREET 52  
INVOLVING                    SMU7032Y

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SH8566P** (the "Taxi"). The Taxi was hired to **NG CHEE KEONG IC NO SXXXX112Z** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$125.40** per day (inclusive of GST).

Please be advised that the Taxi was insured with **AXA Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Philip Chia  
Manager, Fleet Safety

This is a computer generated letter. No signature is required.



## Enquire Vehicle-Related Transaction History

### Transaction History Details

Log Date/Time:	21 Mar 2022 / 12:31:54		
Asset Type:	Vehicle	Transaction Amount:	\$7.49
Asset ID:	SMU7032Y		
Transaction Type:	18.32 Insurance Enquiry (GIRO Payment)	Channel:	External Agency
User ID:	ECENHKM1 - HOW KEEN MENG ROGER	Business Transaction Reference No.:	20220321123154463215

Search Date / Time: 19 Mar 2022 04:15:00  
Insurance Company: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Information displayed is correct as at the log date and time.

[Enquire Related Logs](#)

[Back to List](#)

SH 8566P