

Our Job Ref No : 305509158
Date : 02.04.22

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SHB6385U

Date of Accident : 16.03.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA TAIPING --- SLA9317E
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$2,445.08
 - (b) Labour Charges (include advertisement stickers etc,if any) \$2,360.00
 - Total for Part-By-Part Repair Cost \$4,805.08
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 3 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : LMT S

Name : THEVAN

Tel : 62148398

Date : 25/4/22

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 02.04.2022

Time: 10:24:23

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305509158
 REGN NO : SHB6385U
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 07.11.2019
 DATE/TIME IN : 17.03.2022 12:10
 ACCIDENT DATE : 16.03.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-3813-G	FRT FENDER BLUE DRIVE LH	1	26.60	20.00	21.28
0002 04-01-0104-2467-G	FRT DR LWR PROTECTOR LH	1	186.20	20.00	148.96
0003 04-01-0104-2469-G	REAR DR LWR PROTECTOR LH	1	166.20	20.00	132.96
0004 04-01-0104-0920-G	ROCKER PANEL GARNISH LH	1	290.00	20.00	232.00
0005 03-01-0104-2061-G	REAR WHEEL CAP LH	1	346.40	20.00	277.12
0006 28-01-0103-0003-A	FRT DR COMFORTDELGRO LH	1	75.00		75.00
0007 28-01-9999-2023-A	REAR DOOR APPS LH	1	80.00		80.00
0008 28-01-0302-2017-A	RR FENDER (PETROL ONLY) LH	1	40.00		40.00
0009 04-01-0104-0593-G	FRONT DOOR LH	1	1,797.20	20.00	1,437.76

SUB-TOTAL : 2,445.08

JOB NATURE

0000 PB	PANEL BEATING-SHB6385U	700.00
0001 SP	SPRAYPAINT CHARGE	1500.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305509158
REGN NO : SHB6385U
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 07.11.2019
DATE/TIME IN : 17.03.2022 12:10
ACCIDENT DATE : 16.03.2022

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0002 17-01	CHECK ALL LIGHTING			30.00		
0003 20-00	TUFF COAT ON AFFECTED PARTS.			50.00		
0004 L	TRANSFER OF DOOR			80.00		

SUB-TOTAL : 2,360.00

TOTAL : 4,805.08


MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE : AUTHORIZED : YES / NO

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

DATE: 17-Mar-22 @ 15:56 hrs.

MODEL: Hyundai Ioniq

INSURANCE: CHINA TAIPING (PIP)

VEHICLE NO.: SHB6385U

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Frt Fender LH	1		\$588.80
	Frt Fender Blue-Drive LH	1		\$26.60
	Frt Wheel Cap LH	1		\$346.40
	Frt Door LH	1		\$1,797.20
	Frt Door Lower Protector LH	1		\$186.20
	Rear Door LH	1		\$1,789.90
	Rear Door Lower Protector LH	1		\$166.20
	Rocker Panel Garnish LH	1		\$290.00
	Rear Wheel Cap LH	1		\$346.40
	SUB TOTAL			\$5,537.70
	LESS 20%			\$1,107.54
	DISCOUNTED TOTAL			\$4,430.16
	Frt Door ComfortDelGro LH	1		\$75.00
	Rear Door APPS LH	1		\$80.00
	Rear Fender (Petrol Only) LH	1		\$40.00
	S/NETT TOTAL			\$195.00
	SPARE PARTS TOTAL			\$4,625.16
	Labour Charge			
	Panel Beating – Rear Fender LH			\$800.00
	Spray Painting Charge – Rear Bumper Etc			\$1,800.00
	Check Wirings.			\$60.00
	Tuff Kote			\$100.00
	Transfer Of Doors			\$240.00
	TOTAL LABOUR			\$3,000.00
	ESTIMATE TOTAL			\$7,625.16

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan 8223 5769
21/3/22 1645
PIP 48 3days up
bforpaint

I KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: